

TOOELE COUNTY SCHOOL DISTRICT


TABLE OF CONTENTS

Page	
3	Statement of Purpose
4	Organization of the Plan
5	District Enrollment History
7	District Enrollment Projections
14	District Schools and Facilities
19	District Capital Fiscal Capacity
23	Current District Capital Debt
24	Capital Needs Assessment & Action Plans
28	Future Considerations
29	Five-Year Capital Budget Outlook
	Appendices
30	A – Tooele County Population, 1940 – 2012
32	B – Tooele County Births 1940 – 2012
34	C – October 1/Birth Method Enrollment Projection, 2014 – 2024
38	D – Total Population Method Enrollment Projection, 2014 – 2024
43	E – October 1, 2013 Enrollment Count
45	F – Open Enrollment/Boundary Report
47	G – District Current Facilities Catalog
203	H – Assessed Valuation Per Student By Utah School District
205	I – Zions Bank Info Regarding MBA to GO Bond Conversion
228	J – Utah Demographics Study

STATEMENT OF PURPOSE

The Tooele County School District Master Facilities/Capital Management Plan provides guidance to the TCSD Board of Education and District Administration as they ensure that students in Tooele County are served in school facilities that optimize learning opportunities. The plan will provide the Board, the administration, and the community with data, analysis, and interpretation needed to make thoughtful, prudent, and cost effective decisions to provide school buildings for all students.

The plan will also communicate to Tooele County citizens a clear understanding of the District's intentions and preparations regarding school facilities planning. The document will help citizens understand the Board and administration decision-making processes by providing the public with the same information available to the Board. The document





The plan accomplishes these purposes by describing the objectives for school facilities, by projecting future District enrollment, by quantifying District financial capacity, by cataloging current District facilities, and by describing and analyzing multiple options for meeting future school and support facility needs. The plan is presented avoiding technical jargon so that it communicates to the general public the both the processes used to arrive at the District's plan, as well as the specific nature and impact of the plan.

PLAN FORMAT

The Tooele County School District Master Facilities/Capital Management Plan is organized as follows:

- District Enrollment History a brief review of the District's enrollment history relative to facilities planning and construction.
- District Enrollment Projections a presentation of data and statistics regarding Tooele County demographics, District enrollment, and future enrollment, accompanied by a description of the assumptions that were used to develop the projections.
- Current District Facilities an assessment of the District's current facilities, and the future potential of each of these facilities.
- District fiscal capacity an analysis of the District's capacity to provide the fiscal resources that may be required to fund capital needs.
- Current District Debt a review of outstanding general obligation and Municipal Building Authority debt.
- Needs Assessment and Action Plan analysis of District needs over a 10-year period (2014-2024) based on projected changes in District enrollment and the status of current District facilities.
- Future Considerations a list of possible future next steps in site acquisition and construction of facilities.
- Five-Year Capital Budget Outlook annualized projections of revenue and expenditure to meet the needs identified for the first five years of the plan.


DISTRICT ENROLLMENT HISTORY



The Tooele County School District encompasses the entire geographic area of Tooele County. The District was formed in 1915, consolidating ten small community school districts. The District is governed by a seven-member Board of Education elected to four-year terms. Each Board member represents a geographic area within the District of approximately equal population.

For much of its history, the Tooele County School District was comprised of relatively rural schools, isolated both economically and geographically from the Wasatch Front communities. Since the 1990's, the economic and geographic integration of the much of Tooele County with the Salt Lake Valley has significantly changed the dynamics of the School District (Appendix A, Population, 1850-2010). The District experienced rapid growth beginning in 1994 (when enrollment was 7,564 students) and continuing unabated until the present time. Current District enrollment is 14,016.

At the same time enrollment has grown in the Tooele Valley, more remote parts of the District have decreased in enrollment. For example, in 1990, Dugway High School (grades 7-12) enrolled over 250 students, in the current school year; enrollment is fewer than 70 students. Nevertheless, the district has remained committed to providing quality opportunities for all students in every geographic area of Tooele County. The District is currently constructing a new school building at the Dugway Proving Grounds as part of an historic partnership with the Department of Defense, and in the past ten years has undertaken major construction related to Wendover area schools.



To accommodate the growth over the last twenty years, the District has engaged in a nearly continuous school building program. During that period the district has constructed nine elementary schools, two high schools, one junior high school, and a community learning center. In addition, the district has made additions and improvements to existing buildings.

Also during this time, the District has found economical solutions to provide for support services facilities. In 2003, the District purchased an administrative facility from Detroit Diesel at a cost of less than \$40 per square foot. This compares to more than \$150 per

square foot for typical construction of similar space. This District has similarly upgraded warehouse space that allows economical bulk purchasing for both general district supplies and the school food service program, along with space for district maintenance operations.

The community support for carefully planned construction of additional school facilities has been manifest in a strong record of electoral support for General Obligation Bonds to finance the needed buildings. Elections for citizen approval of Bonds were held in 1994, 2000, 2003, and 2007.

The positive response of voters to the Board of Education in its requests for bonding authority has been achieved by creating a consistent record of high quality cost effective school construction guided by careful prudent planning with an eye to maintaining quality while limiting cost. The Utah Taxpayers Association has supported recent bond elections in Tooele County because of this record, and frequently cites the TCSD as an example of an effective model for high quality AND economical school building construction.

DISTRICT DEMOGRAPHICS AND ENROLLMENT PROJECTIONS

Accurate projections of future enrollment are vital to the planning process. Without accurate projections, no meaningful plan can be developed or implemented. To estimate future enrollment with the highest possible degree of confidence, this plan relies on data and statistics that have been thoroughly reviewed and audited.

OCTOBER 1/BIRTH METHOD – This method relies of the development of patterns from past enrollment records. These patterns are then used to project future enrollment.


Enrollment data for past years is taken from annual reports submitted to and audited by the Utah State Office of Education. These enrollment data are collected each fall on October 1 by the USOE according to rigorous standards established in State Board of Education rules. The consistent use of the October 1 enrollment (rather than unaudited first-day or end-of-year enrollment) ensures that the trends of the past that are a critical part of the future projections are as accurate as possible.

An additional data set for the October 1/Birth Method is the number of births each year to Tooele County residents. The projected birth rates provided by the Utah Bureau of Vital Statistics are found in Appendix B. The data are specifically by county of residence rather than the local where the birth occurred. The number of births in a given year provides a leading indicator of kindergarten enrollment five years later.



Together, these data form the basis of the October 1/Birth Method projection of enrollment. Factors are added annually to each cohort to account for in-migration. The accuracy of the October 1/Birth Method is very high in the short term. As updated on a year-to-year basis, it accounts for changes in circumstance. For example, the pending or past impact of the opening of a charter school within the District's boundaries can be incorporated into this model.

The complete October 1/Birth Method projection is found in Appendix C. The following chart depicts data actuals and projections from 1991 to 2024.



TOTAL POPULATION METHOD – This method relies on population distribution and enrollment ratios using U.S. Census Bureau estimates.

Total Utah and Tooele County population, determined every ten years by the U. S. Census Bureau and updated annually by the Utah Bureau of Vital Statistics, provides a useful data set to project future enrollment. Tooele County population is a predictable percentage total Utah population, and School District enrollment is a predictable percentage (within

a narrow range) of overall county population. Calculation of enrollment as a percentage of projected future overall county population provides a check as to the reasonableness of other methods of projections.


Over the past two decades, the percentage of the overall Utah population residing in Tooele County has increased. Between 2000 and 2008, the percentage of Utah's population residing increased from 1.8 percent to 2.1 percent. This percentage increased as Tooele County grew faster than the rest of the state. However, since 2008, Tooele County has grown as about the same rate as the rest of the state.

Future projections of County population are based on projections made by the Governor's Office of Planning and Budget. Projections of county population have been made using the current percentage of overall state population residing in Tooele County.


During that time, the total enrollment in the Tooele County
School District has been consistently between 21.75 % and 23.64 % of the total County population. Factors that have

affected this percentage are the opening of charter and private schools, changing demographics of in-migrating families, and home-school participation.

Because of the high level of reliability of the Census projections, the accuracy of the total the total population method is high, provided that the percentages of population distribution remain constant. However, this method cannot account for specific enrollment circumstances such as charter school start-ups, nor can it account for changes in economic conditions such as the relocation of major employers.



The complete Total Population Method projection is found in Appendix D. The chart below illustrates the two projection methods and the median line.



Combining these methods of provides a rational and reasonable range within which the District is able to plan. The projection error potential increases as the time horizon becomes more distant. The range projected for total District enrollment at the five-year point of this plan is 1,112. The range projected for total District enrollment at the ten-year point in this plan is 2,975. The differences between these two methods are illustrated in the next table.

School Year	October 1 / Birth Method	Total Population	Median Range							
Actual										
1991-1992	7,476	7,476	7,476							
1992-1993	7,558	7,558	7,558							
1993-1994	7,607	7,607	7,607							
1994-1995	7,772	7,772	7,772							
1995-1996	7,771	7,771	7,771							
1996-1997	7,716	7,716	7,716							
1997-1998	8,019	8,019	8,019							
1998-1999	8,169	8,169	8,169							
1999-2000	8,777	8,777	8,777							
2000-2001	9,177	9,177	9,177							
2001-2002	9,520	9,520	9,520							
2002-2003	10,036	10,036	10,036							
2003-2004	10,512	10,512	10,512							
2004-2005	11,039	11,039	11,039							
2005-2006	11,793	11,793	11,793							
2006-2007	12,507	12,507	12,507							
2007-2008	12,988	12,988	12,988							
2008-2009	13,406	13,406	13,406							
2009-2010	13,180	13,180	13,180							
2010-2011	13,439	13,439	13,439							
2011-2012	13,675	13,675	13,675							
2012-2013	14,034	14,034	14,034							
2013-2014	14,107	14,107	14,107							

School Year	October 1 / Birth Method	Total Population	Median Range		
	Estin	nated			
2014-2015	13,807	13,807	13,807		
2015-2016	13,993	14,246	14,120		
2016-2017	14,200	14,755	14,478		
2017-2018	14,351	15,235	14,793		
2018-2019	14,536	15,648	15,092		
2019-2020	14,641	16,060	15,351		
2020-2021	14,772	16,473	15,623		
2021-2022	14,904	17,018	15,961		
2022-2023	15,007	17,564	16,286		
2023-2024	15,134	18,109	16,622		
2014-2015	13,807	13,807	13,807		
2015-2016	13,993	14,246	14,120		
2016-2017	14,200	14,755	14,478		
2017-2018	14,351	15,235	14,793		
2018-2019	14,536	15,648	15,092		
2019-2020	14,641	16,060	15,351		
2020-2021	14,772	16,473	15,623		
2021-2022	14,904	17,018	15,961		
2022-2023	15,007	17,564	16,286		
2023-2024	15,134	18,109	16,622		

ANALYSIS – The increases in District enrollment over the past twenty years has been driven by two distinct elements. The most visible to Tooele Valley residents has been the development of the County as a residential community linked to the Wasatch Front. Overall Tooele County population over the past two decades has increased well in excess of 10,000 residents per decade. County population in 2000 was 41,548; in 2012 county population was 59,870.

Over the past twenty years, a significant factor driving enrollment growth has been the size of the entering kindergarten classes when compared to the size of the graduation senior classes. Because the growing population of Tooele County included many young families, the enrolling kindergarten classes have typically been much larger than the graduating senior classes, resulting in increased enrollment based on "internal growth" beyond any in-migration. The enrollment of a cohort of 1,000 kindergartners and the graduation of a cohort of 500 seniors results in a gain of enrollment of 500 students.

This "internal growth" dynamic will change dramatically beginning in 2014. For the first time in decades, the size of the 2014 enrolling kindergarten cohort and the 2014 senior class will be approximately equal. This signals a tipping point in the dynamics of the District's growth. The internal move-up factor becomes insignificant. Unless there is a change in the current in-migration pattern, with a large new influx of very young families, it appears that the District is entering a period of slower, though still steady, growth.

In the near term, projections also account for immediate factors that impact growth: housing starts, opening of new private schools or public charter schools, and general economic conditions. However, as the time horizon moves forward, these elements become far less predictable, and changes in conditions are certain to have an effect on the accuracy of projections. Nonetheless, if the projections are updated, these unforeseen changes can be accounted for with sufficient time for plans to be adapted to new circumstances. The October 1/ Birth Method will be the method used for budget planning purposes.



A breakdown of elementary and secondary enrollment projections based on the October 1/ Birth Method is shown in the following table.

SUMMARY TABLE - ELEMENTARY AND SECONDARY ENROLLMENT

Year	Elementary	Secondary	Total
2014	7,348	6,459	13,807
2015	7,398	6,595	13,993
2016	7,441	6,759	14,200
2017	7,498	6,853	14,351
2018	7,548	6,988	14,536
2019	7,545	7,096	14,641
2020	7,602	7,170	14,772
2021	7,708	7,196	14,904
2022	7,798	7,209	15,007
2023	7,868	7,266	15,134

For illustrative purposes, a chart showing the actual October 1, 2014 enrollment count was included as Appendix E. Appendix F shows the most recent Boundary Report for the District dated November 7, 2013. This report provides data about Open Enrollment across the District.

CURRENT DISTRICT SCHOOLS AND FACILITIES

A careful analysis of the capacity current facilities is a prerequisite to an effective plan. The analysis that follows considers a wide range of factors to determine building capacity. These include building age, quality of original construction, current condition, capacity of the core facilities, size of building site, and adaptability.

Building age – The District operates schools of varying ages. Portions of Vernon Elementary School were constructed more than 100 years ago. Most schools in the District are less than 50 years old and many have been built within the last decade. It has been the consistent practice of the District to set construction standards for school buildings that will result in at least a 75 year life span for a building.

Quality of original construction – Despite the District's standard of constructing to a 75 year building life span, the construction quality of some older facilities, or parts of some facilities, do not meet these standards. The construction to lower standards may have been due to constraints imposed at the time by limited budgets. In some cases, the construction standards may be such than even efforts to make minor changes to the building would require significant construction to meet current building standards.

Adaptability – When older schools in the District were constructed, the current needs for computer networking and other technology could not be foreseen. The degree to which buildings can be upgraded to meet modern educational needs is the measure of adaptability.

Capacity – Determination of a buildings capacity is perhaps the most difficult consideration in a review of current facilities. The capacity of a building is dependent upon (at least) the following factors:

Class size - The capacity can be varied greatly by manipulating the class size that is a key input in capacity calculations. For example, the calculated capacity of an elementary school with twenty-six classrooms can by increased by one hundred students simply by increasing the anticipated class size by four. Similarly, the calculated capacity of the same elementary school can be decreased by one hundred by decreasing the anticipated class size by four.

Site size - Some schools are limited in capacity by the size of the school site. This may limit available parking, playground space, or the possibility of locating portable classroom buildings on the site. Furthermore, a smaller site limits the potential for the construction of additions.

Portables - The location of portable classrooms at a school may also increase school capacity. The potential for portable location at a school is sometimes limited by the size of the school site and by the capacity of the school's core facilities.

Core facilities - A school may not have sufficient parking space to accommodate addition enrollment, or the restroom facilities may already be at the capacity allowed by building and occupancy codes.

Space utilization – some classroom spaces may have been converted, over time, to other uses such as office space, storage, or other non-instructional uses. Though these uses may be legitimate, they detract from the overall enrollment capacity of the school.

A complete catalog of District facilities and capacities, as well as, a complete building and portable inventory and condition rating is found in Appendix G.

Capacity may be increased by changes in school schedules and calendars. These possibilities have not been considered in the determination of school capacities as listed in this plan, but should still be mentioned briefly. Extended-day schedules are currently in use in Utah school districts that have increased building capacity as much as 15 percent. Extended-year calendars are currently in use in Utah school districts that have increased building capacity as much as 33 percent.

Extended-day and extended year plans are more common at the elementary grade level. As of this time, there have not been successful full-scale demonstrations of year-round calendars at the secondary level, though the possibilities have been frequently discussed.

For this Master Facilities/Capital Management Plan, capacity has been determined at three levels:

1. Ideal

- a. Elementary 26:1 student teacher ratio, one classroom available, computer labs as designed/currently in use, no portables
- b. Secondary 26:1 student teacher ratio, all classrooms available to assigned teachers during preparation periods, no portables

2. Stretch

- a. Elementary 26:1 student teacher ratio, all classrooms in use, not portables
- b. Secondary 26:1 student teacher ratio, maximum deployment of portables on site

3. Maximum

- a. Elementary 26:1 student teacher ratio, all classrooms in use, maximum deployment of portables on site
- b. Secondary 26:1 student teacher ratio, maximum deployment of portables on site, student use of all classrooms each period

In practice, it is unlikely that schools will fill evenly, so that schools will be at different capacity levels. Further, in practice, the strategies employed to achieve these capacities may not be in the specific order noted above, but may be combinations and variations of these.

For the tables below, enrollment and capacity have been considered for the Tooele Valley elementary and secondary schools only. Growth in the more remote areas of the District is not anticipated, so the enrollment in those schools (Wendover, Dugway, Vernon, Ibapah) has been subtracted from the totals, as also has the capacity of the school buildings in those areas.

SUMMARY TABLE - ELEMENTARY:

Tooele County School District Tooele Valley Elementary Schools

School	Year Constructed	Site Size in Acres	ldeal ¹ Capacity	Stretch ² Capacity	Maximum ³ Capacity with Portables	Current Enrollment Oct 1, 2013	School Square Footage Without Portables	Current Number of Portables	Portable Square Footage	Total Square Footage	Maximum Number of Portables the Site Can Handle	Assessment Condition Score	50 Year Life Span	End of Useful Life 75 Year Span
Copper Canyon Elementary	2004	8.13	650	675	775	620	55,293	0		55,293	4	81.5	2054	2079
East Elementary	1967	11.7	600	620	700	530	50,279	0		50,279	3	47.9	2017	2042
Grantsville Elementary	2011	10.6	850	900	1,050	761	73,159	0		73,159	6	90.1	2061	2086
Harris Elementary	1952	10.34	625	650	750	407	58,858	0		58,858	4	42.9	2002	2027
Middle Canyon Elementary	2002	8	675	700	800	493	55,263	0		55,263	4	79.6	2052	2077
Northlake Elementary	1993	11.18	775	800	950	521	72,590	0		72,590	6	72.5	2043	2068
Overlake Elementary	2002	8.9	650	675	825	584	55,293	0		55,293	6	80.3	2052	2077
Rose Springs Elementary	2005	8.61	650	675	875	841	55,293	3 Doubles 2 Singles	7,200	62,493	8	80.4	2055	2080
Stansbury Park Elementary	1978	8.4	775	800	900	900	59,896	1 Double 1 Single	2,800	62,696	6	63.8	2028	2053
Settlement Canyon Elementary	2008	4.85	675	700	700	673	57,268	0		57,268	0	84.6	2058	2083
West Elementary	1960	15.63	535	560	660	386	65,170	1	900	66,070	4	51.5	2010	2035
Willow Elementary	2002	10.57	675	700	800	657	55,293	0		55,293	6	79.3	2052	2077
TOTAL			8,135	8,455	9,785	7,373	713,655			724,555		71.2	Average	e Score

School capacities are figured on a classroom size of 26 students and special education classroom size of 15 students per space.

¹Each school has one open classroom to use for special programs in that school.

²Every classroom space is used full time as a classroom.

³Maximum capacity with the addition of portables on the site.

SUMMARY TABLE - SECONDARY:

Tooele County School District

Tooele Valley Secondary Schools

School Blue Peak High	Year Constructed 2010	Site size in acres	Ideal ¹ Capacity	Stretch ² Capacity	Maximum ³ Capacity	Current Enrollment Oct 1, 2013	School Square Footage Without Portables	of	Portable Square Footage	Square	Maximum number of Portables the Site Can Handle	Assessment Condition Score	50 Year Life Span	End of Useful Life 75 Year Span
Community Learning Center	2010	8.32	469	585	775			0			6	90.2	2060	2085
Clarke N. Johnsen Jr. High	2006	15.53	825	942	1,250	880	126,588	0		126,588	6	83.1	2056	2081
Grantsville High	1985	23.39	978	1,050	1,300	755	184,664	2 Singles	1,800	186,464	4	66.1	2035	2060
Grantsville Jr High	1980	12	675	750	1,000	391	83,037	0		83,037	4	60.3	2030	2055
Stansbury High School	2009	37.29	1,313	1,547	1,850	1597	241,984	2 Doubles 1 Single	4,500	246,484	12	89.8	2059	2084
Tooele High School	2003	27.19	1,317	1,551	1,850	1500	241,495	6 Doubles	10,800	252,295	12	74.7	2053	2078
Tooele Jr. High	1963	14.8	600	834	1,100	846	95,189	6 Doubles	10,800	105,989	12	53.9	2013	2038
TOTAL		138.52	6,292	7,399	9,290	6,067	972,957			1,000,857		74.0	Average	e score

School Capacities are figured on a classroom size of 26 students and special education classroom size of 15 students per space

¹Each classroom is only used by one teacher and the teachers uses the classroom for prep period

²Ideal capacity with the addition of portables on the site

³Every classroom and portable space is used full time as a classroom

FISCAL CAPACITY

The authority to impose property taxes for educational purposes has been assigned in Utah law to District Boards of Education. The Board is required to impose a certain minimal level of property taxation in order to participate in State funding that is distributed from state personal and corporate income tax collections. There are some property taxes that may only be levied by the Board with approval of the district's voters. Other taxes may be levies with the approval of a simple majority of the Board.

Within the statutory fiscal structure that governs the operations of school districts, the responsibility for funding school buildings and associated support facilities lies largely with the districts. School buildings are expensive investments made by communities to provide for the education of children within those communities. The capacity to make this investment is a function of the value of taxable property, both real and personal, within that community.

The amount of revenue generated by property taxes levied by the Board of Education is a function of the overall "taxable value" within the County. The taxable value for Tooele County in Fiscal Year 2013 was \$2,835,936,096. This amount



grows as the County grows. The total taxable value in Tooele County has more than doubled since 2004. It is anticipated that total taxable value in Tooele County will grow at a 3 percent annual rate. This is a conservative estimate of growth based on historical patterns.

Taxes are levied based on "tax rates." In Tooele County, a tax rate of .0001 yields a revenue of \$283, 594, assuming a collection rate of 100 percent.


The effort required to fund the education programs within school districts varies between communities. The most meaningful measure that shows this difference is the "assessed value per student." The Utah average assessed value per student in 2013 was \$338,076. Tooele County's assessed value per student of

\$206, 466 (2013) is well below that average. The lower the assessed value per student, the higher the tax rate needed to produce the same amount of revenue per student. Typically, districts with lower value per student have higher overall tax rates (see Appendix H.)

The total levy imposed within the Tooele County School District is expressed by a number that, when multiplied by a taxable value, results in the required tax payment. For the 2014 fiscal year the total tax rate levied under the District's authority is .009593. For an individual property owner in the district, a tax rate of .0095 means that for every \$1,000 of taxable value, a property tax of \$9.50 is due in property tax.

Of this total rate, .004754 is levied for operations and maintenance; .004839 is levied for capital purposes. More than half of the total tax rate levied by the Board is committed to capital purposes. The discussion in this document will be on the management and allocation of the tax rate imposed for capital purposes. However, even as this document is limited to that half of the rate, the issue of the appropriate balance between taxes levied for ongoing operations and taxes levied for capital purposes is one that merits careful consideration by the Board. The current balance between these two portions of the total tax levy is not typical of Utah school districts.

Within the capital portion of the levy are two distinct rates. The first, the "debt service levy," is a tax rate to generate revenue to pay the principle and interest on general obligation (GO) bonds that have been issued by the District. The current "debt service" rate levied by the Board is .00385.



The tax rate for the debt service levy is set by formula: it must generate the amount required to pay principal and interest on general obligation debt during the fiscal year – no more, no less. The current debt service levy imposed by the Board is expected to generate \$10,918,354 in FY2014.

The District is limited in the amount of general obligation debt it can incur. Because general obligation debt must be approved by voters, there is a political limit. The District may only incur as much debt as the voters will approve. There is also a limit based on prudent management. The District should incur only as much debt as can be repayed within prudent budgetary limits. And finally, there is a statutory limit. The District may not incur general obligation debt greater than 4 percent of the total taxable value of property within its boundaries.

The other portion of the overall capital levy is the "local capital" levy This levy provides the revenue for all capital expenditures in the district (with the exception of general obligation bond debt service). The current "local capital' levy imposed by the Board is .000989. The total revenue anticipated from this rate in FY2014 is \$2,482,721. Of that revenue, \$2,482,721 is committed to repayment of Municipal Building Authority debt.

When most of the local capital levy revenue is committed to service of the Municipal Building Authority debt, only a small amount is left or all the other capital needs of the District. These include purchases such as school busses and major repair projects such as parking lot repairing and roof replacements.

The "local capital" rate is capped by statute at .0024, well above the current rate.

The Board has wisely set aside funds for unanticipated or future needs in a "capital reserve" account. The current balance in this account is \$9,872,439 million. The revenue source for these funds are generally the local capital levy, but may include other sources, including rents collected on leased district property and sale of surplus real estate owned by the district.

It should be noted that in recent fiscal years, the Board has drawn from the capital reserve fund to meet current capital expenses. The capital reserve account balance as fallen from more than \$18 million in 2007 to just over \$9.8 million, which is approaching a reduction of about one-half of the historical balances. There are ample reasons for this, including the needed reconstruction of Grantsville Elementary. However, a reserve fund cannot be a perpetual source of revenue for ongoing expense. This is an area of particular concern that must be urgently addresses. Failure to address this trend can lead to financial insolvency.

The reliance on the capital reserve fund as an annual revenue source has, to some extent, been the result of a reduction in state revenue that was designated for local capital purposes. In 2008, Tooele County School District received \$5,319,248 from the state for capital purposes. During years of budget cuts at the state level, the appropriation made

for this purpose by the Legislature was reduced and has not increased. The 2013 allocation to the District is \$430,094, a reduction of more than 90 percent.

An effective plan ensures that tax revenue is sufficient to provide for a judicious, prudent plan for school facilities. It should contain both careful borrowing through the issuance of general obligation debt and a program of limiting debt by accumulations of capital reserves to fund some part of needed construction.

The citizens of the Tooele School District are best served when the Board manages the capital taxation as a single unit (with revenues to be distributed as needed to debt service, on-going capital projects, and capital reserves) rather than separately. By managing the capital taxation as a single unit, the Board can provide the public the assurance that the revenue is adequate is adequate to fund a carefully developed plan while not being in excess of what is precisely needed.

CURRENT DEBT

The Board of Education appropriately borrows for capital needs in various ways, the two most common being the sale of general obligation bonds and the sale of Municipal Building Authority (MBA) bonds.

Both forms of Board debt (general obligation and municipal building authority) provide a mechanism to allow more beneficiaries of school buildings, present and future, to bear a portion of the cost of the building. While school buildings are generally constructed with an intended useful life of fifty to seventy-five years, most school bonds have a term of less than twenty years. Nevertheless, the use of long term debt distributes the cost across a larger population of beneficiaries.

General Obligation (GO) bonds are backed by the "full faith and credit" of the residents of the county. To incur general obligation debt, the Board of Education must have the approval of the citizens of the county, thus the need for bond elections. The voters are limited in the total general obligation debt that they may authorize the Board of Education to incur; general obligation debt may not exceed 4 percent of the total market value of the County (property taxes are levied on taxable value; the debt limit is set based on market value). Because of the nature of general obligation debt, bonds of this type sold by the Board carry very low interest rates.

The Board currently has \$71,575,000 of outstanding general obligation debt, which is 1.376 percent of the total taxable value of the county, well below the statutory limit.

Authority to incur debt through the sale of Municipal Building Authority bonds does not require approval by the citizens. Rather, the Board of Education has statutory authority to issue this debt with a simple majority vote of the Board, and with that vote commits revenue generated by its local capital levy to make the payments on that debt.

Because MBA debt is not backed by the "full faith and credit" of the voters, it is generally subject to a higher interest rate (because it is thought to carry higher risk). However, some MBA debt has been given special consideration for federal tax purposes. Interest on debt issued under the Qualified School Construction Bond (QSCB) program is highly subsidized, yielding a very low practical interest rate.

The Board currently has \$27,450,000 in outstanding municipal building authority debt. Of this debt, approximately \$6,000,000 was issued under the QSCB program.

NEEDS ASSESSMENT AND ACTION PLANS

Every decision made in determining a needs assessment is a choice between costs and benefits. One way to think of this is as a balance on a "pain versus gain" scale. Each decision the Board makes has some benefit, that is "gain," and some cost, that is "pain."

An example of the "pain" versus "gain" balance is the use of school attendance boundaries. State law gives the Board ample authority to establish and enforce school attendance boundaries. However, as is widely known, changing school boundaries can be a time consuming and controversial process. While frequent boundary changes might add to efficiency, it may also create unacceptable levels of parent and student uncertainty and frustration.

Another example of the "pain" versus "gain" balance is in class size. The capacity of any elementary school could be immediately be increased simply by increasing class size. The "gain" in such a decision would surely by off-set by the "pain" of resulting losses in educational effectiveness.

A full understanding of the benefits and costs requires thorough analysis and it should be understood that individual perceptions and circumstances among school district patrons may result in very different judgments regarding the appropriate weighting and balance of costs and benefits.

NEED 1 - Effective utilization of capacity.

Goal 1 – Achieve more than 90 percent efficiency use of district "max" capacity in the elementary grades (all Tooele Valley buildings combined) and 90 percent efficiency use of the district "stretch" capacity in the secondary grades (all Tooele Valley buildings combined) before considering new school construction.

Rationale – Each building the district operates carries with it fixed costs. These costs include administration, maintenances and custodial services, utilities, and transportation. Each additional elementary building adds approximately \$500,000 to these fixed costs. Each additional secondary school building adds approximately \$1,000,000 to these costs. These fixed costs are incurred without the generation of any new revenue.

While fixed costs are necessary to support instruction, they are not directly instructional. Each additional school building increases these costs, so operating the current schools to capacity focuses resources on instruction.

Of course, in addition to the fixed cost noted above, each new building requires a large expenditure for construction. At current construction rates, a new elementary with a capacity of 750 students costs approximately \$15,000,000, while a high school with a capacity of 1,800 students may cost as much as \$50,000,000.

Achievement of 100 percent efficiency may require excessive intervention in school boundaries, family choice, and community convenience. However, 90 percent is a reasonable goal that seeks to ensure that public assets are well used.

At the present time, the District has ample student capacity in the current school buildings. If the District can achieve the target utilization levels, neither the projected elementary 90 percent enrollment nor the projected secondary enrollment will not exceed the capacity of existing school buildings prior to 2024.

Action 1a – To communicate to the public this fact and to educate the community as to the District's need to use this capacity effectively, continue the recently begun boundary committee and enlarge the participation.

Action 1b – Conduct community meetings to ensure public understanding of projected enrollment and the plans to fully utilize current facilities. Additionally, other avenues of communication should be employed to ensure public understanding of and support for Board actions.

Action 1c – To maximize the use of current buildings, the District will need to acquire and deploy portable classrooms as a tool to manage capacity between schools. Judicious use of portables may also have the effect of ameliorating some boundary issues.

Action 1d – Some limits on open enrollment will be needed. The Board must ensure that clear policies and procedures are in place to close schools to out of boundary attendance. Advertise and follow statutory timelines for school closure to out-of-boundary enrollment.

NEED 2 - Management of the capital tax rate and revenue.

Goal 2 – Establish and maintain a constant capital block (debt service and local capital levy) tax rate of at least .0046.

Rationale – The Tooele County Board of Education's capacity to levy taxes is a grant of authority from the Utah Legislature with the expectation that the Board acts in the public's interest, applying sound principals of management and planning. The goal of a long-range tax plan is to create a stable tax rate that generates sufficient revenue to sustain a frugal, prudent, and judicious capital maintenance and improvement program.

Action 2a – Establish and maintain a consistent overall capital tax rate once the .0046 goal is achieved. It is typical that as the county population grows, the tax rate needed to provide the revenue to pay general obligation debt will fall. The Board should maintain a constant overall capital tax rate by increasing the local capital levy a corresponding amount. The local capital levy is capped by statute at .0024, but the district will not reach that cap in the foreseeable future.

Action 2b – Build capital reserves to maintain a minimum balance 5 million – maximum \$20 million. The purpose of the capital reserve fund is to provide resources in the event of emergency needs (school fire, other unforeseeable needs) and to lower (though not completely eliminate) the amount that will need to be borrowed in the future through general obligation bonds for future school construction.

Action 2c – Plan budget calendars and procedures to ensure that all statutory requirements are met to maintain a constant or level tax rate within the capital rate block. This strategy will require an annual "truth in taxation" public hearing.

NEED 3 - Restructuring and lowering of current capital debt.

Goal 3 – Rebalance capital expenditures to lower the overall capital tax rate to .0046 over the next five years and to ensure taxing capacity to provide adequate local capital revenue.

Rationale – the current level of debt service (general obligation and municipal building authority debt) places excessive demands on the capital revenue stream. Additionally, restructuring of the debt may facilitate lower interest rates.

Action 3a – Convert existing municipal building authority bonds to general obligation bonds. This action will require voter approval. It is recommended that the Board and administration conduct a series of

community meetings preparing the public for a vote in November 2014. This will require immediate planning and action (see Appendix J).

Action 3b – Restructure existing general obligation debt to create a repayment schedule that will allow the transferred municipal building authority debt to be included without increasing the overall general obligation annual expense and that will take advantage of lower current interest rates.

NEED 4 - Invest in needed school reconstruction and support facilities improvements.

Goal 4 – Appropriate \$1million annually to current capital needs, and make appropriate expenditures from capital reserves.

Rationale – Capital investment is a critical on-going part of school district success. Current buildings need to be improved and some inadequate buildings need to be replaced. Even though the pattern of district growth has changed, there will come a time that additional capacity (i.e. new schools) will be required.

Action 4a - Replace Dugway High School and Dugway Elementary School with one K-12 school building.

Action 4b – Acquire future school sites. Of particular importance is the purchase of a future high school site.

Action 4c – Replace current school transportation facilities.

Action 4d – After 2020, begin planning for new construction as data directs.

FUTURE CONSIDERATIONS

- 1. Boundary & Open Enrollment Management
- 2. Address Building Closure/Retirement & Useful Life Issues
- 3. Site Needs
 - a. Transportation department relocation and possible CNG fueling site with public side (12–15 acres)
 - b. Junior high site in Stansbury area (20 acres)
 - c. High school site in Overlake area (40 acres)
- 4. Site Selection Considerations
 - a. Access to utilities
 - b. Access for transportation services (proximity & location)
 - c. Soils (cannot overlook collapsible issues)
 - d. Slope
 - e. Ground water considerations/rights
 - f. Cost
- 5. Building Needs
 - a. Elementary school in Millpond/Benson Grist Mill area
 - b. High school in Overlake Area
 - c. Middle school in Stansbury area
 - d. East/Harris remodel or replacement



FIVE-YEAR CAPITAL BUDGET OUTLOOK

Anticipated Annual Revenues – Total Capital Levy (debt service and local capital):

Year	Total	Debt Service	Local Capital
FY2015	29,856,439	12,454,444	17,401,995
FY2016	16,854,444	12,454,444	4,400,000
FY2017	16,954,444	12,454,444	4,500,000
FY2018	17,154,444	12,454,444	4,700,000
FY2019	17,254,444	12,454,444	4,800,000


Anticipated Annual Distributions:

Year	Total	Debt Service	Capital Expenditures	Capital Reserve
FY2015	34,028,432	12,454,444	21,573,988	5,628,007
FY2016	16,547,054	12,454,444	4,092,610	5,935,397
FY2017	16,553,527	12,454,444	4,099,083	6,336,314
FY2018	16,563,940	12,454,444	4,109,496	6,926,818
FY2019	16,583,214	12,454,444	4,128,770	7,598,048

For more detailed information on the District's complete budget and/or capital budget, there is a page on the website at www.tooeleschools.org dedicated to fiscal accountability and transparency (or your can contact the District Office). The entire budget package is found online, as well, as the annual Independent Auditor's Report.


APPENDIX A:






APPENDIX B:





APPENDIX C:



OCTOBER 1 / BIRTH METHOD PROJECTION ENROLLMENT HISTORY AND PROJECTION January 17, 2014

				Cohort Year							
School Yea	ar	Octo	ber 1	Births	к	1	2	3	4	5	6
1991-1992			1991		470	541	536	540	622	634	617
1992-1993			1992		512	504	547	554	544	637	648
1993-1994			1993		485	534	510	539	556	548	648
1994-1995			1994		533	528	546	517	559	570	580
1995-1996			1995		557	589	502	558	527	552	574
1996-1997			1996	DATA	559	602	584	515	572	547	584
1997-1998			1997	NOT	630	629	602	632	547	615	567
1998-1999			1998	AVAILABLE	662	697	627	614	654	556	633
1999-2000			1999	AVAILABLE	737	743	736	687	665	685	623
2000-2001			2000		800	822	752	777	719	669	715
2001-2002			2001		847	816	823	780	784	736	697
2002-2003			2002		943	901	844	818	819	790	756
2003-2004			2003		952	985	905	851	809	846	796
2004-2005		2004			1,012	970	963	903	891	835	834
2005-2006			2005	955	1,060	1,067	1,000	987	946	917	870
2006-2007			2006	996	1,097	1,142	1,093	1,051	1,051	993	969
2007-2008			2007	998	1,075	1,168	1,169	1,129	1,045	1,071	1,015
2008-2009			2008	1,085	1,186	1,108	1,160	1,181	1,152	1,075	1,066
2009-2010			2009	1,055	1,112	1,131	1,070	1,101	1,105	1,079	985
2010-2011			2010	1,057	1,070	1,125	1,120	1,058	1,131	1,093	1,065
2011-2012			2011	1,099	1,113	1,076	1,119	1,108	1,052	1,118	1,097
2012-2013			2012	1,144	1,159	1,106	1,082	1,128	1,114	1,067	1,129
2013-2014			2013	1,099	1,083	1,172	1,113	1,100	1,130	1,101	1,082
2014-2015	,		2014	1,099	974	1,051	1,106	1,057	1,046	1,071	1,045
2015-2016			2015	989	1,000	1,012	1,055	1,119	1,072	1,056	1,084
2016-2017		[2016	1,019	1,030	1,038	1,016	1,069	1,135	1,083	1,070
2017-2018			2017		1,030	1,068	1,042	1,030	1,085	1,146	1,097
2018-2019	Estin	nated	2018		1,050	1,068	1,072	1,056	1,046	1,096	1,160
2019-2020	Ye	ars	2019		1,060	1,088	1,072	1,086	1,072	1,057	1,110
2020-2021			2020		1,070	1,098	1,092	1,086	1,102	1,083	1,071
2021-2022			2021		1,080	1,108	1,102	1,106	1,102	1,113	1,097
2022-2023			2022		1,090	1,118	1,112	1,116	1,122	1,113	1,127
2023-2024			2023		1,100	1,128	1,122	1,126	1,132	1,133	1,127


OCTOBER 1 / BIRTH METHOD PROJECTION ENROLLMENT HISTORY AND PROJECTION January 17, 2014


School Yea	er Octo	ober 1	7	8	9	10	11	12	Total	ELEM	Secondary	Self Contained	Grand Total
1991-1992		1991	609	613	604	565	556	538	7,445	3,960	3,485	31	7,476
1992-1993		1992	673	617	616	591	559	532	7,534	3,946	3,588	24	7,558
1993-1994		1993	702	670	604	602	571	499	7,468	3,820	3,648	139	7,607
1994-1995		1994	715	699	686	624	554	532	7,643	3,833	3,810	129	7,772
1995-1996		1995	644	683	683	661	584	508	7,622	3,859	3,763	149	7,771
1996-1997		1996	596	604	631	643	612	515	7,564	3,963	3,601	152	7,716
1997-1998		1997	616	568	615	648	613	602	7,884	4,222	3,662	135	8,019
1998-1999		1998	568	623	590	604	618	568	8,014	4,443	3,571	155	8,169
1999-2000		1999	696	610	629	610	624	576	8,621	4,876	3,745	156	8,777
2000-2001		2000	663	679	612	640	608	574	9,030	5,254	3,776	147	9,177
2001-2002		2001	716	660	674	639	647	548	9,367	5,483	3,884	153	9,520
2002-2003		2002	713	723	668	658	606	598	9,837	5,871	3,966	199	10,036
2003-2004		2003	775	732	716	675	647	556	10,245	6,144	4,101	267	10,512
2004-2005		2004	837	783	731	732	662	599	10,752	6,408	4,344	287	11,039
2005-2006		2005	894	838	793	728	727	635	11,462	6,847	4,615	331	11,793
2006-2007		2006	937	926	896	870	766	716	12,507	7,396	5,111		12,507
2007-2008		2007	981	958	937	855	845	740	12,988	7,672	5,316		12,988
2008-2009		2008	1,029	978	962	905	824	780	13,406	7,928	5,478		13,406
2009-2010		2009	1,005	940	992	957	907	796	13,180	7,583	5,597		13,180
2010-2011		2010	1,000	1,000	1,013	982	928	854	13,439	7,662	5,777		13,439
2011-2012		2011	1,037	1,017	1,078	989	981	890	13,675	7,683	5,992		13,675
2012-2013		2012	1,109	1,056	1,089	1,070	988	937	14,034	7,785	6,249		14,034
2013-2014		2013	1,123	1,084	1,114	1,054	1,026	925	14,107	7,781	6,326		14,107
2014-2015		2014	1,108	1,120	1,100	1,110	1,038	983	13,807	7,348	6,459		13,807
2015-2016		2015	1,116	1,104	1,190	1,096	1,094	995	13,993	7,398	6,595		13,993
2016-2017		2016	1,155	1,113	1,174	1,186	1,080	1,051	14,200	7,441	6,759		14,200
2017-2018		2017	1,141	1,152	1,183	1,170	1,170	1,037	14,351	7,498	6,853		14,351
2018-2019	Estimated	2018	1,168	1,138	1,222	1,179	1,154	1,127	14,536	7,548	6,988		14,536
2019-2020	Years	2019	1,231	1,165	1,208	1,218	1,163	1,111	14,641	7,545	7,096		14,641
2020-2021		2020	1,181	1,228	1,235	1,204	1,202	1,120	14,772	7,602	7,170		14,772
2021-2022		2021	1,142	1,178	1,298	1,231	1,188	1,159	14,904	7,708	7,196		14,904
2022-2023		2022	1,168	1,139	1,248	1,294	1,215	1,145	15,007	7,798	7,209		15,007
2023-2024	4	2023	1,198	1,165	1,209	1,244	1,278	1,172	15,134	7,868	7,266		15,134

OCTOBER 1 / BIRTH METHOD PROJECTION ENROLLMENT HISTORY AND PROJECTION January 17, 2014

						andary 17,			
				Increase	Percentage	Charter&	Charter & Private		District % of
School Ye	ar	Octo	ber 1	From PY	Increase PY	Private	% of District	County Population	County Population
1991-1992			1991						
1992-1993			1992	82	1.097%				
1993-1994			1993	49	0.648%				
1994-1995			1994	165	2.169%				
1995-1996			1995	(1)	-0.013%				
1996-1997			1996	(55)	-0.708%				
1997-1998			1997	303	3.927%				
1998-1999			1998	150	1.871%				
1999-2000			1999	608	7.443%				
2000-2001			2000	400	4.557%			41,548	22.088%
2001-2002			2001	343	3.738%			43,768	21.751%
2002-2003			2002	516	5.420%			45,741	21.941%
2003-2004			2003	476	4.743%			47,368	22.192%
2004-2005			2004	527	5.013%			48,561	22.732%
2005-2006			2005	754	6.830%			50,926	23.157%
2006-2007			2006	714	6.054%			53,120	23.545%
2007-2008			2007	481	3.846%			55,081	23.580%
2008-2009			2008	418	3.218%			56,722	23.635%
2009-2010			2009	(226)	-1.686%	715	5.425%	57,606	22.880%
2010-2011			2010	259	1.965%	728	5.417%	58,522	22.964%
2011-2012			2011	236	1.756%	749	5.477%	59,133	23.126%
2012-2013			2012	359	2.625%	745	5.309%	59,870	23.441%
2013-2014			2013	73	0.520%	1,203	8.528%	61,746	22.847%
2014-2015			2014	(300)	-2.127%	1,200	8.691%	63,622	21.702%
2015-2016		[2015	186	1.347%	1,200	8.576%	64,748	21.611%
2016-2017		[2016	207	1.479%	1,200	8.451%	66,874	21.234%
2017-2018		[2017	151	1.063%	1,250	8.710%	69,000	20.799%
2018-2019	Estin	nated	2018	185	1.289%	1,250	8.599%	71,126	20.437%
2019-2020	Ye	ars 2019		105	0.722%	1,250	8.538%	73,002	20.056%
2020-2021		2020		131	0.895%	1,250	8.462%	74,877	19.728%
2021-2022		2021		132	0.894%	1,250	8.387%	77,356	19.267%
2022-2023		2022		103	0.691%	1,250	8.329%	79,835	18.798%
2023-2024			2023	127	0.846%	1,250	8.260%	82,314	18.386%

APPENDIX D:





TOTAL POPULATION METHOD ENROLLMENT HISTORY AND PROJECTION January 17, 2014

						idi y 17, 2					
				Cohort Year							
School Ye	ar	Octo	ber 1	Births	к	1	2	3	4	5	6
1991-1992			1991		470	541	536	540	622	634	617
1992-1993			1992		512	504	547	554	544	637	648
1993-1994			1993		485	534	510	539	556	548	648
1994-1995			1994		533	528	546	517	559	570	580
1995-1996			1995		557	589	502	558	527	552	574
1996-1997			1996	DATA	559	602	584	515	572	547	584
1997-1998			1997	DATA NOT	630	629	602	632	547	615	567
1998-1999			1998	AVAILABLE	662	697	627	614	654	556	633
1999-2000			1999	AVAILABLE	737	743	736	687	665	685	623
2000-2001			2000		800	822	752	777	719	669	715
2001-2002			2001		847	816	823	780	784	736	697
2002-2003			2002		943	901	844	818	819	790	756
2003-2004			2003		952	985	905	851	809	846	796
2004-2005			2004		1,012	970	963	903	891	835	834
2005-2006			2005	955	1,060	1,067	1,000	987	946	917	870
2006-2007			2006	996	1,097	1,142	1,093	1,051	1,051	993	969
2007-2008			2007	998	1,075	1,168	1,169	1,129	1,045	1,071	1,015
2008-2009			2008	1,085	1,186	1,108	1,160	1,181	1,152	1,075	1,066
2009-2010			2009	1,055	1,112	1,131	1,070	1,101	1,105	1,079	985
2010-2011			2010	1,057	1,070	1,125	1,120	1,058	1,131	1,093	1,065
2011-2012			2011	1,099	1,113	1,076	1,119	1,108	1,052	1,118	1,097
2012-2013			2012	1,144	1,159	1,106	1,082	1,128	1,114	1,067	1,129
2013-2014			2013	1,099	1,083	1,172	1,113	1,100	1,130	1,101	1,082
2014-2015			2014	1,099	974	1,051	1,106	1,057	1,046	1,071	1,045
2015-2016			2015	989	1,133	1,022	1,065	1,129	1,082	1,066	1,094
2016-2017			2016	1,019	1,221	1,181	1,036	1,089	1,155	1,103	1,090
2017-2018			2017		1,258	1,269	1,195	1,060	1,115	1,176	1,127
2018-2019		nated ars	2018		1,187	1,306	1,283	1,219	1,086	1,136	1,200
2019-2020	16	ars	2019		1,286	1,235	1,320	1,307	1,245	1,107	1,160
2020-2021			2020		1,281	1,334	1,249	1,344	1,333	1,266	1,131
2021-2022			2021		1,432	1,329	1,348	1,273	1,370	1,354	1,290
2022-2023			2022		1,483	1,480	1,343	1,372	1,299	1,391	1,378
2023-2024			2023		1,478	1,531	1,494	1,367	1,398	1,320	1,415

TOTAL POPULATION METHOD ENROLLMENT HISTORY AND PROJECTION January 17, 2014

							uary 17,						
										Total	Total		
School Ye	ar O	ctober 1	7	8	9	10	11	12	Total	ELEM	Secondary	Self Contained	Grand Total
1991-1992		1991	609	613	604	565	556	538	7,445	3,960	3,485	31	7,476
1992-1993		1992	673	617	616	591	559	532	7,534	3,946	3,588	24	7,558
1993-1994		1993	702	670	604	602	571	499	7,468	3,820	3,648	139	7,607
1994-1995		1994	715	699	686	624	554	532	7,643	3,833	3,810	129	7,772
1995-1996		1995	644	683	683	661	584	508	7,622	3,859	3,763	149	7,771
1996-1997		1996	596	604	631	643	612	515	7,564	3,963	3,601	152	7,716
1997-1998		1997	616	568	615	648	613	602	7,884	4,222	3,662	135	8,019
1998-1999		1998	568	623	590	604	618	568	8,014	4,443	3,571	155	8,169
1999-2000		1999	696	610	629	610	624	576	8,621	4,876	3,745	156	8,777
2000-2001		2000	663	679	612	640	608	574	9,030	5,254	3,776	147	9,177
2001-2002		2001	716	660	674	639	647	548	9,367	5,483	3,884	153	9,520
2002-2003		2002	713	723	668	658	606	598	9,837	5,871	3,966	199	10,036
2003-2004		2003	775	732	716	675	647	556	10,245	6,144	4,101	267	10,512
2004-2005		2004	837	783	731	732	662	599	10,752	6,408	4,344	287	11,039
2005-2006		2005	894	838	793	728	727	635	11,462	6,847	4,615	331	11,793
2006-2007		2006	937	926	896	870	766	716	12,507	7,396	5,111		12,507
2007-2008		2007	981	958	937	855	845	740	12,988	7,672	5,316		12,988
2008-2009		2008	1,029	978	962	905	824	780	13,406	7,928	5,478		13,406
2009-2010		2009	1,005	940	992	957	907	796	13,180	7,583	5,597		13,180
2010-2011		2010	1,000	1,000	1,013	982	928	854	13,439	7,662	5,777		13,439
2011-2012		2011	1,037	1,017	1,078	989	981	890	13,675	7,683	5,992		13,675
2012-2013		2012	1,109	1,056	1,089	1,070	988	937	14,034	7,785	6,249		14,034
2013-2014		2013	1,123	1,084	1,114	1,054	1,026	925	14,107	7,781	6,326		14,107
2014-2015		2014	1,108	1,120	1,100	1,110	1,038	983	13,807	7,348	6,459		13,807
2015-2016		2015	1,126	1,114	1,200	1,106	1,104	1,005	14,246	7,591	6,655		14,246
2016-2017		2016	1,176	1,133	1,194	1,206	1,100	1,071	14,755	7,875	6,880		14,755
2017-2018	F-tht-	2017	1,172	1,183	1,213	1,200	1,200	1,067	15,235	8,200	7,035		15,235
2018-2019	Estimated Years	2018	1,209	1,179	1,263	1,219	1,194	1,167	15,648	8,417	7,231		15,648
2019-2020	rear 3	2019	1,282	1,216	1,259	1,269	1,213	1,161	16,060	8,660	7,400		16,060
2020-2021		2020	1,242	1,289	1,296	1,265	1,263	1,180	16,473	8,938	7,535		16,473
2021-2022		2021	1,213	1,249	1,369	1,302	1,259	1,230	17,018	9,396	7,622		17,018
2022-2023		2022	1,372	1,220	1,329	1,375	1,296	1,226	17,564	9,746	7,818		17,564
2023-2024		2023	1,460	1,379	1,300	1,335	1,369	1,263	18,109	10,003	8,106		18,109

TOTAL POPULATION METHOD ENROLLMENT HISTORY AND PROJECTION January 17, 2014

					illuary 17,			
			Increase	Percentage	Charter &	Charter & Private		District % of
School Ye	ar Oo	tober 1	From PY	Increase PY	Private	% of District	County Population	County Population
1991-1992		1991						
1992-1993		1992	82	1.097%				
1993-1994		1993	49	0.648%				
1994-1995		1994	165	2.169%				
1995-1996		1995	(1)	-0.013%				
1996-1997		1996	(55)	-0.708%				
1997-1998		1997	303	3.927%				
1998-1999		1998	150	1.871%				
1999-2000		1999	608	7.443%				
2000-2001		2000	400	4.557%			41,548	22.09%
2001-2002		2001	343	3.738%			43,768	21.75%
2002-2003		2002	516	5.420%			45,741	21.94%
2003-2004		2003	476	4.743%			47,368	22.19%
2004-2005		2004	527	5.013%			48,561	22.73%
2005-2006		2005	754	6.830%			50,926	23.16%
2006-2007		2006	714	6.054%			53,120	23.54%
2007-2008		2007	481	3.846%			55,081	23.58%
2008-2009		2008	418	3.218%			56,722	23.63%
2009-2010		2009	(226)	-1.686%	715	5.42%	57,606	22.88%
2010-2011		2010	259	1.965%	728	5.42%	58,522	22.96%
2011-2012		2011	236	1.756%	749	5.48%	59,133	23.13%
2012-2013		2012	359	2.625%	745	5.31%	59,870	23.44%
2013-2014		2013	73	0.520%	1,203	8.53%	61,746	22.85%
2014-2015		2014	(300)	-2.127%	1,200	8.69%	63,622	21.70%
2015-2016		2015	439	3.180%	1,200	8.42%	65,498	21.75%
2016-2017		2016	509	3.573%	1,200	8.13%	67,374	21.90%
2017-2018		2017	480	3.253%	1,250	8.20%	69,250	22.00%
2018-2019	Estimated Years	2018	413	2.711%	1,250	7.99%	71,126	22.00%
2019-2020	1 cars	2019	412	2.633%	1,250	7.78%	73,002	22.00%
2020-2021		2020	413	2.572%	1,250	7.59%	74,877	22.00%
2021-2022		2021	545	3.308%	1,250	7.35%	77,356	22.00%
2022-2023		2022	546	3.208%	1,250	7.12%	79,835	22.00%
2023-2024		2023	545	3.103%	1,250	6.90%	82,314	22.00%

APPENDIX E:



Tooele School District Enrollment Count October 1, 2013

School	SC	ĸ	1	2	3	4	5	6	7	8	9	10	11	12	SC & K-12 Total	K-12 minus SC Total	Oct 1, 2012	Difference
Early Learning	138																	
Anna Smith	4	40	40	47	47	39	39	27							279	275	258	21
Copper Canyon	5	83	93	95	90	85	90	84							620	615	654	-34
Dugway	3	11	16	14	9	13	12	14							89	86	124	-35
East	5	78	83	63	69	86	71	80							530	525	511	19
Grantsville Elem	21	98	102	106	122	101	113	119							761	740	787	-26
Harris	6	59	51	60	48	60	64	65							407	401	425	-18
lbapah	0	7	2	4	2	3	2	0							20	20	22	-2
Middle Canyon	0	60	80	73	70	71	77	62							493	493	497	-4
Northlake	31	79	76	64	74	76	74	78							521	490	526	-5
Overlake	15	77	92	82	73	103	71	86							584	569	560	24
Rose Springs	13	107	121	129	115	132	120	117							841	828	835	6
Settlement Canyon	6	106	111	94	97	80	91	94							673	667	637	36
Stansbury	5	130	154	137	124	129	113	113							900	895	844	56
Vernon	0	5	1	5	2	3	2	3							21	21	34	-13
West	6	56	49	56	60	54	61	50							386	380	395	-9
Willow	0	88	101	84	98	95	101	90							657	657	673	-16
Grantsville Jr.	7								197	194					391	384	379	12
Tooele Jr. High	47								428	418					846	799	855	-9
Clarke Johnsen	21								456	424					880	859	837	43
Dugway High	1								12	10	8	14	12	9	65	64	80	-15
Grantsville High	14										190	192	193	179	754	740	777	-23
Wendover High	2								30	38	27	28	34	37	194	192	198	-4
Tooele High	120										442	408	373	279	1,502	1,382	1,482	20
Stansbury High	39										448	398	377	374	1,597	1,558	1,555	42
Blue Peak High	17											14	37	47	98	81	85	13
Grand Total	388	1,084	1,172	1,113	1,100	1,130	1,101	1,082	1,123	1,084	1,115	1,054	1,026	925	14,109	13,721	14030	79
							•		•									
Current #	14,109							Е	lementa	ry Tota	ls	Oct. 1,	2012	7,782	Total	7,782		
October 1, 2012	14,030	l						S	econda	ry Tota	ls	Oct. 1,	2012	6,248	Total	6,327		
Difference from October 1												1-Oct-12		14,030	Actual Total:	14,109		
		•								,				Di	fference:	79		

APPENDIX F:



Looele Schoo	District	Koundary	Kenort	November 7, 201	- 3

					100	CIC 3	CITC	01 0	istrici	Doc		_	Bound				,,,	-								l	
Attending School	Anna Smith Elementary	Copper Canyon Elementary	Dugway Elementary	East Bementary	Grantsville Elementary	Harris Elementary	Ibapah Elementary	Middle Canyon Elementary	Northlake Elementary	Overlake Elementary	Rose Springs Elementary	Settlement Canyon Elementary	Stansbury Park Elementary	Vernon Elementary	West Elementary	Willow Elementary	Grantsville Jr. High	Johnsen Jr. High	Tooele Jr. High	Dugway High	Grantsville High	Stansbury High	Too ele High	Wendover High	Out of District	Total Out of Boundary Enrolled	Total Enrolled
Anna Smith Elementary	280																								П	0	280
Copper Canyon Elementary		522				45	П	37	4	2		4	4		5										П	101	623
Dugway Elementary		1	80			1	П	1		1															П	4	84
East Elementary		6		455	5	25		12	17	4		4	2		3										П	78	533
Grantsville Elementary		5	2	2	706	8	П	1	4			11	1		1	19		П							П	54	760
Harris Elementary		2		25	1	365		3	6	2		2	3	П	3	1									П	48	413
Ibapah Elementary							20																		П	0	20
Middle Canyon Elementary		18		11	1	64	П	368	14	1		7	3		4										П	123	491
Northlake Elementary		15		15	3	17	П	11	429	5		13	1		10			П							П	90	519
Overlake Elementary		16		9	12	8		1	8	516		2			1										П	57	573
Rose Springs Elementary		4		2	44	1		4	3	6	714	5	67		1										П	137	851
Settlement Canyon Elementary		7		9		5		4	11			592	1	1	42											80	672
Stansbury Park Elementary		6		7	13	3	П	2	4		25	2	840		2										П	64	904
Vernon Elementary			1											20											П	1	21
West Elementary		3		10	6	3		3	14		3	7	2	2	329										П	53	382
Willow Elementary					32	1			3							622										36	658
Grantsville Jr. High																	377	8	8							16	393
Johnsen Jr. High																	5	807	74							79	886
Tooele Jr. High																	1	3	839							4	843
Dugway High																				56	1		6			7	63
Grantsville High																					694	32	30		2	64	758
Stansbury High																					19	1406	177			196	1602
Tooele High																					16	83	1400		1	100	1500
Wendover High																								194		0	194
Blue Peak High																					21	38	37				96
Total Resident-Out of Boundary	0	83	3	90	117	181	0	79	88	21	28	57	84	3	72	20	6	11	82	0	57	153	250	0	3		
Total Resident School	280	605	83	545	823	546	20	447	517	537	742	649	924	23	401	642	383	818	921	56	751	1559	1650	194	3		14119

APPENDIX G:



Appendix G



District Current Facilities Catalog



Building Statistics

Pages 1 to 6

District Schools

Pages 7 to 84

Support Facilities

Pages 85 to 96

Portables

Pages 97 to 154

Tooele County School District Instructional Facilities

School	Year Constructed	Site size	Ideal Capacity ¹	Stretch Capacity	Maximum Capacity With Portables	Current Enrollment OCT 1, 2013	School square footage without portables			Total Square Footage	Maximum number of portables the site can handle	Facility Condition	50 year	End of useful life 75 year life
Anna Smith Elementary	1997	12.1	325	350	350	278	42,420	- Fortables	Footage	42,420		73.5	2047	span 2072
Copper Canyon Elementary	2004	8.13	650	675	775	620	55,293	0		55,293		81.9	2054	2079
Community Learning Center W/O Blue Peak	2010	8.32	469	585	775		93,400	0		93,400		90.2	2060	2085
Blue Peak High	2010		115	140	165	98		0						
Clarke N. Johnsen Jr. High	2006	15.53	825	942	1,250	880	126,588	0		126,588	6	83.1	2056	2081
Dugway Elementary*	1951	10	190	210	260	89	32,611	0		32,611	2	37.7	2001	2026
Dugway High*	1953	18	265	305	400	65	51,900	0		51,900	2	34.5	2003	2028
Early Learning Center	1977	9.19	125	140	140		15,000	0		15,000	0	51.3	2027	2052
East Elementary	1967	11.7	600	620	700	530	50,279			50,279	3	47.9	2017	2042
Grantsville Elementary	2011	10.6	850	900	1,050	761	73,159	0		73,159	6	90.1	2061	2086
Grantsville High	1985	23.39	978	1,050	1,300	755	184,664	2 Singles	1,800	186,464	4	66.1	2035	2060
Grantsville Jr High	1980	12	675	750	1,000	391	83,037	0		83,037	4	60.7	2030	2055
Harris Elementary	1952	10.34	625	650	750	407	58,858	0		58,858	4	42.7	2002	2027
Ibapah Elementary	1960	10.46	40	50	100	20	4,907	0		4,907	2	47.0	2010	2035
Middle Canyon Elementary	2002	8	675	700	800	493	55,293	0		55,293	4	79.4	2052	2077
Northlake Elementary	1993	11.18	775	800	950	521	72,590	0		72,590	6	73.0	2043	2068
Overlake Elementary	2002	8.9	650	675	825	584	55,293	0		55,293	6	80.3	2052	2077
Rose Springs Elementary	2005	8.61	650	675	875	841	55,293	3 Doubles 2 Singles	7,200	62,493	8	80.5	2055	2080
Stansbury Park Elementary	1978	8.4	775	800	900	900	59,896	1 Double 1 Single	2,800	62,696	6	64.1	2028	2053
Stansbury High School	2009	37.29	1,313	1,547	1,850	1597	241,984	2 Doubles 1 Single	4,500	246,484	12	89.8	2059	2084
Settlement Canyon Elementary	2008	4.85	675	700	700	673	57,268	0		57,268	0	85.4	2058	2083
Tooele High School	2003	27.19	1,317	1,551	1,850	1500	241,495	6 Doubles	9,900	251,395	12	75.5	2053	2078
Tooele Jr. High	1963	14.8	600	834	1,100	846	95,189	6 Doubles	9,000	104,189	12	53.9	2013	2038
Vernon Elementary	1929	6.18	50	75	100	21	5,521	1	900	6,421	1	36.3	1979	2004
Wendover High	1966	15.44	338	400	625	194	64,282	1	900	65,182	3	48.6	2016	2041
West Elementary	1960	15.63	535	560	660	386	65,170	1	900	66,070	4	51.5	2010	2035
Willow Elementary	2002	10.57	675	700	850	657	55,293	0		55,293	6	79.4	2052	2077
Total		336.8	15,760.00	17,384.00	21,100	14,107	1,996,683	45	37,900	2,034,583	123	65.6	Average	score

^{*}These two schools are in the process of being replaced

¹ School capacities are figured on a classroom size of 26 students and special education classrooms size of 15 students per space

Tooele County School District Tooele Valley Elementary Schools

School	Year constructed	Site size	Ideal ¹ Capacity	Stretch ² Capacity	Maximum ³ Capacity with Portables	Current Enrollment OCT 1, 2013	School Square Footage without portables	Current Number of Portables	Portable Square Footage	Square	Maximum number of portables the site can handle	Assessment Condition Score	50 Year life span	End of useful life 75 year span
Copper Canyon Elementary	2004	8.13	650	675	775	620	55, 293	0		55, 293	4	81.5	2054	2079
East Elementary	1967	11.7	600	620	700	530	50,279			50,279	3	47.9	2017	2042
Grantsville Elementary	2011	10.6	850	900	1,050	761	73, 159	О		73, 159	6	90.1	2061	2086
Harris Elementary	1952	10.34	625	650	750	407	58,858	0		58,858	4	42.9	2002	2027
Middle Canyon Elementary	2002	8	675	700	800	493	55,263	0		55, 263	4	79.6	2052	2077
Northlake Elementary	1993	11.18	775	800	950	521	72,590	0		72,590	6	72.5	2043	2068
Overlake Elementary	2002	8.9	650	675	825	584	55, 293			55, 293	6	80.3	2052	2077
Rose Springs Elementary	2005	8.61	650	675	875	841	55, 293	3 Doubles 2 Singles	7,200	62,493	8	80.4	2055	2080
Stansbury Park Elementary	1978	8.4	775	800	900	900	59,896	1 Double 1 Single	2,800	62,696	6	63.8	2028	2053
Settlement Canyon Elementary	2008	4.85	675	700	700	673	57,268	0		57,268	0	84.6	2058	2083
West Elementary	1960	15.63	535	560	660	386	65, 170	1	900	66,070	4	51.5	2010	2035
Willow Elementary	2002	10.57	675	700	800	657	55, 293	0		55, 293	6	79.3	2052	2077
Total			8,135	8,455	9,785	7,373	713,655		•	724,555	·	71.2	Average S	core

School capacities are figured on a classroom size of 26 students and special education classroom size of 15 students per space

¹Each school has one open classroom to use for special programs in that school

²Every classroom space is used full time as a classroom

³Maximum capacity with the addition of portables on the site

Tooele County School District Tooele Valley Secondary Schools

School	Year Constructed	Site size	Ideal ¹ Capacity	Stretch ² Capacity	Maximum ³ Capacity	Current Enrollment OCT 1, 2013	School Square Footage without portables	Current Number of Portables	Portable Square Footage	Square	Maximum number of portables the site can handle	Assessment Condition Score	50 Year life span	End of useful life 75 year span
Blue Peak High	2010		115	140	165	98		о			1			
Community Learning Center	2010	8.32	469	585	775						6	90.2	2060	2085
Clarke N. Johnsen Jr. High	2006	15.53	825	942	1,250	880	126,588	О		126,588	6	83.1	2056	2081
Grantsville High	1985	23.39	978	1,050	1,300	755	184,664	2 singles	1,800	186,464	4	66.1	2035	2060
Grantsville Jr High	1980	12	675	750	1,000	391	83,037			83,037	4	60.3	2030	2055
Stansbury High School	2009	37.29	1,313	1,547	1,850	1597	241,984	2 Doubles 1 Single	4,500	246,484	12	89.8	2059	2084
Tooele High School	2003	27.19	1,317	1,551	1,850	1500	241,495	6 Doubles	10,800	252,295	12	74.7	2053	2078
Tooele Jr. High	1963	14.8	600	834	1,100	846		6 Doubles		105,989	12	53.9	2013	2038
Total		138.52	6,292	7,399	9,290	6,067	972,957			1,000,857		74.0	Average s	core

School Capacities are figured on a classroom size of 26 students and special education classroom size of 15 students per space

¹Each classroom is only used by one teacher and the teachers uses the classroom for prep period

²Ideal capacity with the addition of portables on the site

³Every classroom and portable space is used full time as a classroom

Tooele County School District Support Facilities

Building	Year Constructed	Facility Maximum Occupancy ³	Site size	Building Square Footage without portables		Total Square Footage	Maximum number of portables the site can handle	Assessment Condition Score	50 Year life span	End of useful life 75 year span
Food Service/Maintenance	2000	82	3	18,500		18,500	0	73.1	2050	2075
District Office ¹	1990	351	0.66	29,100		29,100	0	70.1	2040	2065
Transportation/Bus Garage	1967	97	4.039	5,790	1,650	7,440	2	41.0	2017	2042
Warehouse #2	2001	34	4.4	12,000		12,000	10	50.9	2051	2076
Wendover housing			0.994							
Ibapah House #1										
Ibapah House #2										
Total			13.093	65,390	1,650	67,053				
-								58.8	Average S	Score

Inventory of land

Location	Size in acres	
Stansbury Park by Benson Grist Mill	7.5	Future Elementary School Site
West Side of Grantsville	10	Future Elementary School Site
East Bench of Tooele off Droubay Lane ²	4	Too small to built a school on
Terra	0.11	We should look into selling this site
South of Vernon in Benmore	2.25	Old school site

Notes

¹ Tooele County School District only owns the land under the building

²This property has been declared surplus by the Board of Education and is for sale

³Occupancies are based on the International Fire Code



Portables Current Assigned location	Type of portable	Quantity	Number of Classrooms	Current use	Portable Number	Portable Condition Score	End of useful life
Grantsville High School							
	Single classroom	1	1	Classroom for construction class	127	23.5	2030
	Single classroom	1	1	IT work room and office	128	24.5	2030
Tooele High School							
	Double classroom	1	2	Classroom/Classroom	107	38.7	2030
	Double classroom	1	2	Classroom/ROTC	108		
	Double classroom	1	2	Fitness/Fitness	109	31.7	2030
	Double classroom	1	2	Classroom/Classroom	110		
	Double classroom	1	2	Classroom/Home Study	111	32.9	2030
	Double classroom	1	2	Classroom/Classroom	112	40.8	2035
Chanabana Iliah Cabaal							
Stansbury High School	D. H. H. H.		2	(6)	124	20.5	2025
	Double classroom	1	2	Classroom/Classroom	124		
	Single classroom	1	1	Classroom	125		
	Double classroom	1	2	Classroom/Classroom	126	32.6	2035
Wendover High School							
Tremaduri mg. sensor	Single classroom	1	1	Storage	100	25.4	2035
Tooele Jr, High School							
	Double classroom	1	2	Tooele Family Center	101	41.1	2040
	Double classroom	1	2	Classroom/Classroom	102	40.9	2040
	Double classroom	1	2	Classroom/Classroom	103	39.9	2040
	Double classroom	1	2	Classroom/Classroom	104	40.5	2040

	Double classroom	1	2	Classroom/Classroom	105	25.1	2040
	Double classroom	1	2	Classroom/Classroom	106	25.8	2035
Rose Springs Elementary							
	Double classroom	1	2	Classroom	118	25.6	2030
	Double classroom	1	2	Classroom	119	26.4	2030
	Double classroom	1	2	Classroom	120	20.5	2025
	Single classroom	1	1	Music/Art	121	24.9	2030
	Single classroom	1	1	Classroom	123	23.4	2030
Stansbury Park Elementary							
	Double classroom	1	2	Classroom/Classroom	116	29.5	2035
	Single classroom	1	1	Classroom	117	28.4	2035
Vernon Elementary							
***	Single classroom	1	1	Media Center	129	31.6	2030
West Elementary							
	Single classroom	1	1	PEP Grant office	115	28.4	2030
Bus Garage							
	Single room	1	1	Training room	113	26.7	2035
	Single room	1	1	Transportation Office	114	34.6	2035

Notes	29	47	District Average	30.7
Total portables used for classrooms		36		
Total portables used for administration		2		
Total portables used for other uses		9		

Anna Smith Elementary School



731 North Aria Blvd Wendover, Utah 84083 435-665-7562





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	73.5
Original Building	1997	42,420	District Average	65.6
			Rating System 1 to 100	
Current Student				
Enrollment	279			
Ideal Capacity	325		Special Needs or Actions	
Stretch Capacity	350		 ADA Upgrade to the playground 	d equipment
Maximum Capacity	350		 New landscape for the front hil 	I





School Assessment Building Condition	Total Score 73.5		7.7
		Interior 301:General Aesthetics	7
Rating System 1 to 10 , 1=Poor 10=Excellent		302Administration office complex	7
		303 Proper egress corridors/doors	
Factors	Rating Score	304 Multi-propose room	7
1. Exterior Building	8.2	305 Special needs rooms	
101 General Aesthetics	8	306 Media Center	
102 Exterior walls	8	307Storage rooms 308 Computer labs	7
103 Exterior Doors	8	309 W Indows/Glass	a
104 ADA Automatic door operators	. 8	310Doors	-
105 ADA complaint entrances	9	311 a. Condition	9
106 Windows		312 b. ADA Door Hardware	9
107 Roofing		313 ADA Access to all spaces 314Signage	
	<u> </u>	31.5 flooring	
108 Flashing		31.6 a. carpet	ь
109 Canopies	8	3L7 b. VCT	Б
110 Vestibules	<u>L8</u>	318 c. Special type	ь
	10 ²	319Walk	8
2. Exterior Site	7.8	320 Ceiling	8
201 Landscaping		SZL Stairs, ramps and hand railing	N/A
202 a. Irrigation System		322 ADA Lifts 323 Seismik, needs	N/A
203 b. Turf		324 Adequacy of custodial spaces	
	1	,	
204 c. Planting		4. Teaching Environment	7.2
205 Playgrounds		401.Adequate heating, cooling and ventilation	8
206 a. ADA compliant	<u>8</u>	402 Proper lighting and lighting control	8
207 b. Equipment	8	403 Adequate power needs	ь
208 c. Playground safety	7	404 Classroom sound systems 405 Classroom technology	
209 d. Playfields	5	406LDC projectors in classrooms	7
210 Asphalt condition	6	407Classroom safety	ģ
211 Fencing	8	408 W indows/blinds 1	34
212 Student drop-off area		409 Classroom doors with a window	9
213 Traffic control		410W hite boards	8
	3	411 Classroom furniture	
214 Bus Lane			7.2
215 ADA Side walks	<u>8</u>	5. Building Restrooms 50LADA Compliant	7.2
216 ADA Access to building	9	502Partitions	7
217 ADA Parking	9	503 Lavatories and faucets	7
218 Adequate parking	9	504 Water closets with flush valves	7
219 Stairs, ramps and hand railing	8	505 Urinals with flush valves	7
220 Storm drainage system	0 0	50b1 looning	7
221 a. Site drainage		507Walls	- 3
222 b. Storm water detention	-	508 Ceilings 509 Exhaust fans	1
	1	500 Extra ust tans 510 Emergency Lighting	#
223 Fire truck access	├ ── 3	511Floor Drains	9
224 Fire hydrant location and access	9		

Page 8

Anna Smith Elementary School



6. Life Safet	ty	8.9	9. School Mechanical & Plumbing Systems		7.4
	601 Fire alarm system	9	901 Boiler	7	
	602 Proper egress	9	902 Chiller	7	
	603 Intercom system	8	903 Cooling towers	7	
	604 Fire Extinguisher placement	9	904 Pumps	7	
	605 AED's	9	905 Water heaters	7	
	606 Fire Sprinkling systems	9	906 Hydronic components	7	
	607 Emergency egress Lighting	3	907 Temperature controls systems	7	
	608 Fire department emergency radio & cell phone buster	N/A	908 Air handling units/fans rooms	8	
0.0000000000000000000000000000000000000	\$\cdot\cdot\cdot\cdot\cdot\cdot\cdot\cdot	<u> </u>	909 A/C units	N/A	
7. Kitchens,	-	7.3	910 Air compressors	7	
	701 Cooking equipment	7	911 Exhaust fans	7	
	702 Refrigerating /freezing equipment	7	912 Unit heaters & Cabinet heaters	7	
	703 Kitchen hood & suppression system	7	913 Exterior hose bibs	8	
	704 Storage	7	914 Roof drainage system	8	
	705 Serving Counter		915 Sewer drain lines	8	
	706 Fire Extinguishers K type where needed	9	916 Grease interceptor	7	
	707 Make-up air systems	7	917 Building water lines	8	
	708 Exhaust Fans	7	918 ADA Compliant Drinking fountain fixtures	8	
		<u></u>	919Soft water system 920Steam lines and traps	N/A	
8. School El	lectrical Systems	6.3	920 Steam lines and traps	IN/A	
	801 Lighting systems	7	10. Future Needs		5.8
	802 Proper Exit Signs	9	1001 Capability for Expansion	6	
	803 Building Power system		1002 Capability for Portables	6	
	804 a. Main power service to building	9	1003 Energy efficiency rating	5	
	805 b. Emergency generator	9	1004Adaptability for Technology	6	
	806 c. Adequate classroom power	6			
	807 Security system	7	Notes		
	808 Clocks	7	¹ This building could use new blinds		
	809 Access control system	О			
	810 CCTV system	О	Special needs		
	811 Data systems	9	ADA Upgrade to playground equipment		
	812 Wireless access	7	Upgrade old T-12 lighting to T-8		
	813 MDF/IDF Room	8	Install new CCTV system		
	814 Stage lighting/Sound systems	7	New landscape for the front hill		

Page 9

Copper Canyon Elementary



1600 North Broadway Tooele, Utah 84074 435-843-3820






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	81.9
Total Building	2004	55,293	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	620		 ADA upgrade to playground equipment 	
Ideal Capacity	650		 Install WeatherTrak irrigation controller 	
Stretch Capacity	675			
Maximum Capacity	775			

Copper Canyon Elementary





Page 11

Copper Canyon Elementary



6. Life Safety	9 8.6	9. School Mechanical & Plumbing Systems	Γ	8.1
601 Fire alarm system	9	901Boiler	8	-
602 Proper egress	9	902 Chiller	8	
603 Intercom system	8	903 Cooling towers	N/A	
604 Fire Extinguisher placement	9	904 Pumps	8	
605 AED's	9	905 Water heaters	8	
606 Fire Sprinkling systems	9	906 Hydronic components	8	
607 Emergency egress Lighting	9	907 Temperature controls systems	- 3	
608 Fire department emergency radio & cell phone buster	7	908 Air handling units/fans rooms	9	
	28 (22 23 23 23		- 0	
7. Kitchens/Serving	8.1	909 A/C units	8	
701 Cooking equipment	8	910 Air compressors	8	
702 Refrigerating /freezing equipment	8	911 Exhaust fans	8	
703 Kitchen hood & suppression system	8	912 Unit heaters & Cabinet heaters	8	
704 Storage	8	913Exterior hose bibs	8	
705 Serving Counter	8	914Roof drainage system	8	
706 Fire Extinguishers K type where needed	9	915 Sewer drain lines	8	
707 Make-up air systems	8	916Grease interceptor	8	
708 Exhaust Fans	8	917Building water lines	8	
8. School Electrical Systems	8.1	918ADA Compliant Drinking fountain fixtures	9	
801 Lighting systems	8	919Soft water system	8	
802 Proper Exit Signs	9	920Steam lines and traps	N/A	
803 Building Power system				
804 a. Main power service to building	9	10. Future Needs		7.8
805 b. Emergency generator	8	1001 Capability for Expansion	7	
806 c. Adequate classroom power	8	1002 Capability for Portables	7	
807 Security system	9	1003 Energy efficiency rating	8	
808 Clocks	8	1004 Adaptability for Technology		
809 Access control system	8	1004/Madpladmit from recimology		
810 CCTV system	7	Notes		
811 Data systems	8	Notes		
812 Wireless access	8			
813 MDF/IDF Room	8	Special needs		
814 Stage lighting/Sound systems	8	WeatherTrak Irrigation controller		
		ADA Upgrade to playground equipment		

Community Learning Center



211 South Tooele Blvd. Tooele, Utah 84074 435-833-8700





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	90.2
Total Building	2010	93,400	District Average	65.6
			Rating System 1 to 100	
Current Student Enrollment			Special Needs or Actions	
Ideal Capacity	469		 This School is currently using the 	stage as a fitness room
Stretch Capacity	625		 Install an WeatherTrak Water Co 	ntroller
Maximum Capacity	775			

School Assessment Building Condition

Community Learning Center




Secretar Secretar		Rating System 1 to 10 , 1-Poor 10-Excellent				
10.0 General Asstrations	Factors		Rating Score			
1.00 Exterior valide	1. Exterior Buik	ding	9.20			
100 Exterior colores		101 General Aesthetics	9			
100 Externol aloos 2 30.0 General Assthetics 2 30.0 Complex 3 30.0 Comp		102 Exterior walls	9	3. Interior		8.89
100 ABA Automitation decidency operation: 10 100 ABA Automitation (infinition) 10 100 ABA ABA Automitation (infinition) 10		103 Exterior doors	9		301 General Aesthetics	9
10 ARA complame elements		104 ADA Automatic door operators	10			9
1.06 Windows		105 ADA complainte ritrances	10		27(1) P. C. T. B. C. G. S. J. C.	10
1.07 Asoling		106 Windows	9			
1.06 Habring 9 306 Media Center 9 9 9 9 9 9 9 9 9		107 Roofing	9			- 5
100 Canopus 9 307 Storage rooms 9 9 9 9 9 9 9 9 9		108 Flashing	9			ā
2. Exteriol 586		109 Canopies	9			- 1
Deterior See		1 10 Ve stibules	9			1
200 Londicarring 90 310 Londicarring 10 10 10 10 10 10 10 1			<u> </u>			- 3
311 a. Condition 10	2. Exterior Site		9.00			10
312		201 Landscaping				
200 C. Planting			9			
20P Hygrounds		203 b.Turf	9			
200			9			111
315 a.carpet 3 3 3 3 3 3 3 3 3						<u> </u>
200 c. P layground safety			9			<u> </u>
200 d. Phyfields 9 9 9 9 9 9 9 9 9			9			1
210 Apphat condition 9 319 Walls 9 9 9 9 9 9 9 9 9			9			<u> </u>
211 Fercing 3 320 Celling 9 9 9 9 9 9 9 9 9			9			9
212 Student drop-off area 9 321 Stairs, ramps and hand railing 9 9 9 9 9 9 9 9 9			- 9			9
211 taffix control			- 9			9
214 Bus Lane			9			
215 ADA Scke wells			- 9			N/A
21.5 ADA Access to building 9 32.5 Adequacy of custodial spaces 9 9 9 9 9 9 9 9 9			9			9
217 ADA Parking 3 328 Gymna slums 3 328 Weight Rooms 3 328 W			9			10
219 Starts, ramps and hand rating 9 327 Locker rooms 9 328 Weight Rooms 9 328 Weight Rooms 9 329 Starts, ramps and hand rating 9 328 Starts, ramps and hand rating 9 328 Starts Rooms 9 329 Starts Rooms 9 329 Starts Rooms 9 329 Starts Rooms 9 329 Starts Rooms 9 320 Wrestling room 9 9 9 9 9 9 9 9 9			3			9
2.19 Starts, ramps and hand railing 3 328 Weight Rooms 3 329 Fitness room 1 4 4 4 4 4 4 4 4 4			<u> </u>		326 Gymna siums	9
2.00 Storm dramage system 3.26 Fitness from 1 4 4 4 4 4 4 4 4 4			9		327 Locker rooms	9
221 a. Site dianage 3 329 Fitness from 4 4 4 4 4 4 4 4 4 4			9		328Weight Rooms	5
222 b. Storm water detention 9 330 Wrestling room N/A					329 Fitness room 1	- 4
331 Dance studio N/A			1		330 Wrestling room	N/A
221 Fernancourts			1 1		331 Dance studio	N/A
225 tenne courts			- 3			1,0
225 225			1	4. Teachine	Environment	9.27
227 a. Sport play fields						9
228 b. Bleachers						
229 c. Running track						
230 d.Restrooms						
231 e. Concession						
232 f. landscaping						10
235 Fercing						10
234 h. Practice fields N/A 409 Classroom door with window 10 235 i. ADA accessibility N/A 410 White boards 9						10
235 I.ADA accessibility N/A 410 White boards 9						
						10
411Classroom Furniture		AND THE STATE OF T				⊢
		Early, area age	INC.		411 Classroom Furniture	

Total Score 90.28

Page 14

Community Learning Center





Page 15

Clarke N. Johnsen Jr. High School

TIAO1 LIAD TOOLLE COUNTY SCHOOL DISTRICT CHAPMAG A GRETIER OF

2152 North 400 West Tooele, Utah 84074 435-833-1939






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	83.1
Total Building	2006	126,588	District Average	65.6
			Rating System 1 to 100	
Current Student Enrollment	880			
Ideal Capacity	825		Special Needs or Actions	
Stretch Capacity	1,100		 This school was designed to be able 	to add four
Maximum Capacity	1,250		classrooms to the south classroom v	wing

Clarke N. Johnsen Jr. High School





Page 17





6. Life Safety	8.63	9. School Mechanical & Plumbing Systems	8.05
601 Fire alarm system	8	901 Boiler	8
602 Proper egress	9	902 Chiller	8
603 Intercom system	9	903 Cooling tower	- 9
604 Fire Extinguisher placement	9	1 	
605 AED's	9	904 Pumps	8
606 Fire Sprinkling system	9	905 Water heaters	8
607 Emergency egress Lighting	9	906 Hydronic components	8
608 Fire department emergency radio & cell phone buster	7	907 Temperature controls systems	8
		908 Air handling units/fan rooms	8
7. Kitchens/Serving	8.50	909 A/C units	8
701 Cooking equipment	8	910 Air compressors	8
702 Refrigerating /freezing equipment	8	911 Exhaust fans	8
703 Hood suppression system	9	912 Unit heaters & cabinet heaters	8
704 Storage	9	913 Dust Collectors	
705 Serving Counter	9	914 Roof drainage system	
706 Fire Extinguishers K type where needed	9	Specialists by the week	
707 Make-up air systems 708 Exhaust fans		915 Sewer drain lines	8
708 Exhaust lans	0	916 Grease interceptor	8
8. School Electrical Systems	8.46	917 Building water lines	8
801 Lighting systems	8	918 ADA Complaint Drinking fountain fixtures	9
802 Proper Exit Signs	9	919 Soft water system	8
803 Building Power system		920 Steam lines and traps	N/A
804 a. Main Power service to building	9		500 200
805 b. Emergency generator	8	10. Future Needs	8.00
806 c. Adequate classroom power	8	1001 Capability for Expansion	9
807 Security system	9	1002 Capability for Portables	7
808 Clocks	8	1003 Energy efficiency rating	- 8
809 Access control system	9	1004 Adaptability for Technology	
810 CCTV system	8	1004 Adaptability for Technology	8
811 Data systems	9		
812 Wireless access	8	Special needs	
813 MDF/IDF Room	8	Four Classroom Addition	
814 Stage Lighting/Sound	9		

Page 18

Dugway Elementary School



Bldg. 5000 Valdez Circle Dugway, Utah 84022 435-831-4259





Facility Assessment Summary


Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	37.7
Original Building	1951	32,611	District Average	65.6
			Rating System 1 to 100	
Current Student Enrollment	89		Special Needs or Actions	
Ideal Capacity	190		 Seismic Needs 	
Stretch Capacity	210		Reduce the height of the tall chimney	
Maximum Capacity	260		(Major Concern)	

Dugway Elementary School



School Assessment Building Condition Total Score

Rating System 1 to 10, 1=Poor 10=Excellent



37.7

Page 20

Dugway Elementary School



6. Life Safety	5.4	9. School Mechanical & Plumbing Systems	2.8
601 Fire alarm system	9	901 Boiler	3
602 Proper egress	8	902 Chiller	N/A
603 Intercom system	5	903 Cooling towers	N/A
604 Fire Extinguisher placement	8	904 Pumps	3
605 AED's	8	905 Water heaters	3
606 Fire Sprinkling systems	О	906 Hydronic components	3
607 Emergency egress Lighting	5	907 Temperature controls systems	3
608 Fire department emergency radio & cell phone buster	р	908 Air handling units/fans rooms 909 A/C units	3
	<u> </u>	910 Air compressors	3
7. Kitchens/Serving	4.3	911 Exhaust fans	1
701 Cooking equipment	4	912 Unit heaters & Cabinet heaters	3
702 Refrigerating /freezing equipment	4	913 Exterior hose bibs	3
703 Kitchen hood & suppression system	4	914 Roof drainage system	-3
704 Storage	4	915 Sewer drain lines	2
705 Serving Counter	4	916 Grease interceptor	N/A
706 Fire Extinguishers K type where needed	6	917 Building water lines	2
707 Make-up air systems		918 ADA Compliant Drinking fountain fixtures	2
708 Exhaust Fans	4	919 Soft water system	3
,		920 Steam lines and traps	2
8. School Electrical Systems	2.7	10. Future Needs	3.4
801 Lighting systems	4	1001 Capability for Expansion	3
802 Proper Exit Signs	6	1002 Capability for Portables	3
803 Building Power system		1003 Energy efficiency rating	4.5
804 a. Main power service to building	5	1004 Adaptability for Technology	3
805 b. Emergency generator	0		
806 c. Adequate classroom power	3	Notes	
807 Security system	o	A control of the cont	
808 Clocks	2	Special needs	
809 Access control system	0	Seismic Needs from the Rapid Visual Screening of buildings	done by Ensign Engineering
810 CCTV system	0	a. Reduce the height of the tall chimney (Major concern)	
811 Data systems	7	b. Detailed evaluation recommended	
812 Wireless access	7	WeatherTrak Irrigation controller	
813 MDF/IDF Room	1	ADA Upgrade to playground equipment	
814 Stage lighting/Sound systems	2		

Dugway High School



Bldg. 5020 5th Ave. Dugway, Utah 84022 435-831-4566





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	34.5
Original Building	1953	51,900	District Average	65.6
			Rating System 1 to 100	
Current Student Enrollment			Special Needs or Actions	
Ideal Capacity	265		 This school is in the process of being it 	replaced
Stretch Capacity	350		with a DoD matching grant	
Maximum Capacity	400			

Dugway High School




School Assessment Building Condition	Total Score 34.59		
Rating System 1 to 10, 1-Poor 10-Excellent			
Factors	Rating Score		
1. Exterior Building	4.11		4
101 General Aesthetics	4	3. Interior	3.96
102 Exterior walls	4	301 General Aesthetics	4
103 Exterior doors	4	302 Administration office complex	4
104 ADA Automatic door operators		303 Proper egress corridors/doors	Б
105 ADA complaintentrances		304 Multi-propose room	4
10b Windows	-	305 Special needs rooms	4
1.07 Roofing		306 Media Center	4
108 Flashing		307 Storage rooms	4
109 Canopies	N/A	308 Computer labs	4
110 Vestibules	10,5	309 W indows/Glass	a
I ID Vestiones	75	S10 Doors	
2. Extenor Site	5.72	311 a. Condition	4
	3.74	312 b. ADA Door Hardware	4
201 Landscaping		313 A DA Access to all spaces	ь
202 a. Irrigation System	4	514 Signage	4
203 b. Turf	4	315 flooring	1
204 c. Planting	4	316 a. carpet	5
205 Playgrounds	Page 100 and 1	317 b. VCT	S
206 a. ADA compliant	N/A	318 c. Special type	1
207 b. Equipment	N/A	sie Walls	1 1
208 c. Playground safety	5	320 Ceiling	1 1
209 d. Playfields		321 Stairs, ramps and hand railing	- 3
210 Asphalt condition	3	322 A DA Lifts	
211 feinding		323 Elevator	
212 Student drop-off area	3		
2.13 Traffix control	3	324 Seismic needs	1
2.14 Bus Lane	3	325 Adequacy of custodial spaces	 2
215 ADA Side walks		32b Gymnasiums	5
216 ADA Access to building	- 5	527 Locker rooms	2
217 ADA Parking	5	328 Weight Rooms	2
Z18 Adequate parking	4	329 Fitness room	
219 Stairs, ramps and hand railing	N/A	330 W restling room	N/A
2 20 Storm drainage system		331 Dance studio	N/A
221 a. Site drainage	4	332 Welding Shop	N/A
222 b.Storm water detention	0	555 Wood Shop	3
2.23 Fire truck access	ь	334 A nimal Lab	N/A
2.24 Fire hydrant location and access	ь		
2.25 Tenns courts		4. Teaching Environment	4.18
2.2b Sport Stadiums	f .	401 Adequate heating, cooling and ventilation	3
2.27 a. Sport play fields	.5	402 Proper lighting/control	3
2.28 b. Bleachers	4	403 Adequate power needs	3
229 c. Running track	8	404 Classroom sound systems	5
230 d. Restrooms	o	405 Classroom technology	
231 e. Concession	o	406 LDC projectors in classrooms	
2.32 f. landscaping	4	407 Classroom safety	ь
233 g. Fencing	4	408 Window/blinds	3
2.34 h. Practice fields	3	409 Classroom door with window	3
235 I. ADA access ibility	4	410 White boards	3
2.5b J. Storage	5	411 Classroom furniture	3
& 5	70 .00		***************************************

Page 23

Dugway High School





Early Learning Center



555 East Vine Street Tooele, Utah 84074 435-833-1966






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	51.3
Original Building	1977	14,540	District Average	65.6
Boiler room addition	1988	460	Rating System 1 to 100	
Total Building		15,000		
Current Student Enrollment			Special Needs or Actions	
Ideal Capacity	125		 Outside walls do not have any insul 	ation in them
Stretch Capacity	140		 This school needs an fire sprinkling 	system
Maximum Capacity	140		 This school does not have a emerge 	ency generator
			 This school needs a seismic upgrade 	e

Early Learning Center






Page 26

Early Learning Center





East Elementary School

TOOLLE COUNTY SCHOOL DISTRICT GLATING A GETTIRE OF LEARNING FOR ALL

135 South 7th Street Tooele, Utah 84074 435-833-1952





• Add new fire sprinkling system to the original building

Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	47.9
Original Building	1967	36,060	District Average	65.6
Classroom wing addition	1997	14,219	Rating System 1 to 100	
Total Building		50,279		
			Special Needs or Actions	
Current Student Enrollment	530		 ADA upgrade to original building and 	front parking lot
Ideal Capacity	600		• Seismic upgrade to the original building	ng
Stretch Capacity	620		 light upgrade to the total school 	
Maximum Capacity	700		a. Upgrade old T-12 Lighting to T-8	
			b. The school need emergency back	up lighting & power

East Elementary School




School Assessment Building Condition	Total Score	47.9	3. Interior		4.7
				301General Aesthetics	5
Rating System 1 to 10 , 1=Poor 10=Excellent				302Administration office complex	4
Tabling System 2 to 10, 1-1 box 10-to-to-to-to-				303 Proper egress corridors/doors	7
Factors	Rating Score			304 Multi-propose room	Б
1. Exterior Building		5.7		305 Special needs rooms	
101 General Aesthetics				30 b Media Center	- 4
102 Exterior walls				307Storage rooms 308Computer labs	- 1
				309Windows/Glass	4
103 Exterior Doors	- 3			\$10Doors \$	
104 ADA Automatic door operators				311 a Condition	3
105 ADA complaint entrances 1	5			312 b. ADA Door Hardware	3
106 Windows	5			515ADA Access to all spaces	7
107 Roofing	7			314Signage	3
108 Flashing	7			315 Flooring	
109 Canopies	N/A			316 a. carpet	- 5
110 Vestibules				317 b. VCT 318 c. Specialtype	
				319Walls	4
2. Exterior Site	28	4.8		320Cerling	5
		4.8		521Stairs, ramps and hand railing	5
201 Landscaping				322ADA Lifts	N/A
202 a. Irrigation System	5			323Seismic needs	- 5
203 b. Turf	4			324Adequacy of custodial spaces	5
204 c. Planting	4			on order of the contract of th	4.5
205 Playgrounds			4. Teaching Er	401A dequate heating, cooling and ventilation	4.3
206 a. ADA compliant	5			402 Proper lighting and lighting control	4
207 b. Equipment	s			405 Adequate power needs	3
208 c. Playground safety	5			404 Classroom sound systems	Б
209 d. Playfields	5			405 Classroom technology	8
210 Asphalt condition				40 BLDC projectors in classrooms	8
211 Fencing	=======================================			407Classroom safety	2
	- 1			408 Windows/blinds	
212 Student drop-off area	<u> </u>			409Classroom doors with a window 4 410W hite boards	
213 Traffic control	4			411Classroom furniture	
214 Bus Lane	4				18 1 - 18 1
215 ADA Side walks	4		5. Building Re:	strooms	4.8
216 ADA Access to building	4			501ADA Compliant	ь
217 ADA Parking ²	4			502 Partitions	5
218 Adequate parking	6			503 Lavatories and faucets	5
219 Stairs, ramps and hand railing	Δ			504 Water closets with flush valves	- 5
220 Storm drainage system				505 Urinals with flush valves 506 Flooring	- 3
				507Walls	5
221 a. Site drainage	- 1			508Cerlings	5
222 b. Storm water detention	<u> </u>			509£xhaust fans	
223 Fire truck access				510E mergency Lighting	3
224 Fire hydrant location and access					

Page 29







Grantsville Elementary School



50 South Park Street Grantsville, Utah 84029 435-884-9991





Facility Assessment Summary

Maximum Capacity

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	90.1
Original Building	2011	73,159	District Average	65.6
			Rating System 1 to 100	
Current Student Enrollment			Special Needs or Actions	
Ideal Capacity	850			
Stretch Capacity	900			

1,050

Grantsville Elementary School




School Assessment Building Condition	Total Score	90.1	3. Interior		0.e
				301 General Aesthetics	9
Rating System 1 to 10 , 1=Poor 10=Excellent				302 Administration office complex	9
Factors	Rating Scor	Δ.		303 Proper egress corridors/doors	9
1. Exterior Building	Rating Scot	9.0		304 Multi-propose room	9
101 General Aesthetics	9			305 Special needs rooms	9
102 Exterior walls	9			306 Media Center	9
103 Exterior Doors	9			307 Storage rooms	9
104 ADA Automatic door operators	9			308 Computer labs	9
105 ADA complaint entrances	9			309 Windows/Glass	9
106 Windows	9			310 Doors	1
107 Roofing	9			311 a. Condition	9
108 Flashing	9			312 b. ADA Door Hardware	9
109 Canopies	9			313 ADA Access to all spaces	- 9
110 Vestibules	9			314 Signage	
	F			315 Flooring	1
2. Exterior Site	y-	9.0		316 a. carpet	0
201 Landscaping				317 b. VCT	9
202 a. Irrigation System	9			318 c. Special type	- 3
203 b. Turf	9			319 Walls	3
204 c. Planting					9
205 Playgrounds				320 Ceiling	
206 a. ADA compliant	9			321 Stairs, ramps and hand railing	N/A
207 b. Equipment	9			322 ADA Lifts	N/A
208 c. Playground safety	9			323 Seismic needs	9
209 d. Playfields	9			324 Adequacy of custodial spaces	9
210 Asphalt condition	9				
211 Fencing	9		4. Teaching	Environment	9.0
212 Student drop-off area	9			401 Adequate heating, cooling and ventilation	9
213 Traffic control	9			402 Proper lighting and lighting control	9
214 Bus Lane	9			403Adequate power needs	9
215 ADA Side walks	9			404 Classroom sound systems	9
216 ADA Access to building	9			405 Classroom technology	9
217 ADA Parking	9			406LDC projectors in classrooms	9
218 Adequate parking	9			407 Classroom safety	9
219 Stairs, ramps and hand railing				408 Windows/blinds	9
220 Storm drainage system				409 Classroom doors with a window	9
221 a. Site drainage	9			410 White boards	9
222 b. Storm water detention	9			411 Classroom furniture	<u> </u>
223 Fire truck access	9			-11 Gaba con faithfule	
224 Fire hydrant location and access	9				

Page 32

Grantsville Elementary School





Page 33

Grantsville High School



155 East Cherry Street Grantsville, Utah 84029 435-884-4500





Facility Assessment Summary

Building Information		
	Year	Square Feet
Old Gym	1967	11,232
Original Building	1985	134,249
Classroom wing addition	2001	37,335
Animial Lab	1975	1,848
Total Building		184,664
Current Student Enrollment	754	
Ideal Capacity	978	
Stretch Capacity	1,200	
Maximum Capacity	1,300	

Facility Conditions Summary


Facility Condition Score	66.1
District Average	65.6
Rating System 1 to 100	

Special Needs or Actions

- Chiller Replacement, the chiller is old and we cannot get the R500 refrigerant anymore
- Several of the restrooms need to be upgraded
- Carpet in the lunchroom needs to be replaced
- The emergency generator needs to be upgraded
- The old pneumatic controls system needs to be upgraded
- Several of the inside doors need to be replaced

Grantsville High School






Page 35

Grantsville High School





Grantsville Jr. High School



318 South Hale Street Grantsville, Utah 84029 435-884-4510






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	60.7
Original Building	1980	64,000	District Average	65.6
Classroom wing addition	2005	19,307	Rating System 1 to 100	
Total Building		83,073		
Current Student Enrollment	391		Special Needs or Actions	
Ideal Capacity	675		 Relocate emergency generator from 	om the upstairs
Stretch Capacity	900		boiler room to ground floor outsid	de
Maximum Capacity	1,000		 Upgrade the HVAC system in the 	old part of the school
			 ADA upgrade to the old part of th 	e school
			 Replace the old pneumatic control 	ols with DDC controls
			 Seismic upgrade to the old part of 	f the school

Grantsville Jr. High School





Page 38

Grantsville Jr. High School



6. Life Safety	~	7,13	9. School Mecha	anical & Plumbing Systems		5.94
601 Fire alarm system	8			901 Boiler	7	
602 Proper egress	8			902 Chiller	N/A	
603 Intercom system	8			903 Coolingtower	N/A	
604 Fire Extinguisher placement	8			904 Pumps	6	
605 AED's	8			905 Water heaters	6	
606 Fire Sprinkling system	8			906 Hydronic components	į į	
607 Emergency egress Lighting	9					
608 Fire department emergency radio & cell phone buster	0			907 Temperature controls systems ³	3	
				908 Air handling units/fan rooms	6	
7. Kitchens/Serving	W	6.00		909 A/C units	1	
701 Cooking equipment	7	1.0		910 Air compressors	1	
702 Refrigerating /freezing equipment	6			911 Exhaust fans	7	
703 Hood suppression system	6			912 Unit heaters & cabinet heaters		
704Storage	5			913 Dust Collectors	5	
705 Serving Counter	6			914 Roof drainage system	6	
706 Fire Extinguishers K type where needed	6			915 Sewer drain lines	6	
707 Make-up air systems	6			916 Grease interceptor	o	
708 Exhaust fans	6			917 Building water lines	6	
				918 ADA Complaint Drinking fountain fixtures	8	
8. School Electrical Systems	3	5.31		919 Soft water system	6	
801 Lighting systems	6			920 Steam lines and traps	N/A	
802 Proper Exit Signs	8			99-95-05-05-05-05-05-05-05-05-05-05-05-05-05		
803 Building Power system			10: Future Need	ds.	1	6.00
804 a. Main Power service to building	8			1001 Capability for Expansion		0.00
805 b. Emergency generator ²	5			1002 Capability for Portables		
806 c. Adequate classroom power	6				1	
807 Security system	0			1003 Energy efficiency rating	1	
808 Clocks	5			1004 Adaptability for Technology		
809 Access control system	0					
810 CCTV system	6		Notes			
811 Data systems	6			¹ The old section of the school needs new ADA door hardware		
812 Wireless access	6			² The emergency generator need to be moved outside the building		
813 MDF/IDF Room	7			³ The old section of the school has old pneumatic controls that need	to be undated	
814Stage Lighting/Sound	6					
			Special needs			
			3	Relocate emergency generator from the boiler room to the ground	d floor out side	
				Upgrade the lighting in the old part of the school from T-12 to T-8		
				Upgrade the HVAC system in the old part of the school		
				Replace the old pneumatic controls with DDC controls		
				Seismic upgrade to the old part of the school		
				Install a WeatherTrak water controller		

Harris Elementary School



251 North 1st Street Tooele, Utah 84074 435-833-1961






Facility Assessment Summary

		Facility Conditions Summary	
Year	Square Feet		
1953	39,593	Facility Condition Score	42.7
1962	19,265	District Average	65.6
1997	3,737	Rating System 1 to 100	
1991	460		
1978	1,200	Special Needs or Actions	
	58,858	 ADA upgrade to whole school 	
		 ADA upgrade to the playground equipment 	
		 Remodel student restrooms 	
407		 Remodel front parking and student drop off 	
625		 Seismic upgrade to the school 	
650		 Upgrade the power to the classrooms 	
750			
	1953 1962 1997 1991 1978 407 625 650	1953 39,593 1962 19,265 1997 3,737 1991 460 1978 1,200 58,858	1953 39,593 Facility Condition Score 1962 19,265 District Average 1997 3,737 Rating System 1 to 100 1991 460 1978 1,200 Special Needs or Actions 58,858 • ADA upgrade to whole school • ADA upgrade to the playground equipment • Remodel student restrooms 407 • Remodel front parking and student drop off 625 • Seismic upgrade to the school 650 • Upgrade the power to the classrooms

Harris Elementary School






Page 41

Harris Elementary School





Page 42

Ibapah Elementary School



116 Eagle's Nest Ibapah, Utah 84034 435-234-1175






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	47.0
Original Building	1960	4,907	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	20		 ADA upgrade to the playground equipment 	
Ideal Capacity	40			
Stretch Capacity	50			
Maximum Capacity	100			

Ibapah Elementary School





Page 44

Ibapah Elementary School



6. Life Safety		4.0	9. School	Mechanical & Plumbing Systems	T	4.5
601 Fire ala	arm system	6		901 Boiler	N/A	
602 Proper	egress	7		902 Chiller	N/A	
603 Interco	om system	2		903 Cooling towers	N/A	
604 Fire Ex	tinguisher placement	6		904 Pumps	5	
605 AED's		9		905 Water heaters	5	
606 Fire Sp	rinkling systems	О		906 Hydronic components	N/A	
607 Emerge	ency egress Lighting	2			19/25	
608 Fire de	epartment emergency radio & cell phone buster	О		907 Temperature controls systems	4	
			e	908 Air handling units/fans rooms	- 6	
7. Kitchens/Serving		3.6		909 A/C units	6	
701 Cookin	ng equipment	4		910 Air compressors	N/A	
702 Refrige	erating /freezing equipment	4		911 Exhaust fans	5	
703 Kitcher	n hood & suppression system	4		912 Unit heaters & Cabinet heaters	N/A	
704 Storage	e	4		913 Exterior hose bibs	5	
705 Serving	g Counter	5		914 Roof drainage system	6	
706 Fire Ex	tinguishers K type where needed			915 Sewer drain lines	6	
707 Make-	up air systems	0		916 Grease interceptor	0	
708 Exhaus	st Fans	4		917 Building water lines	5	
			r.	918 ADA Compliant Drinking fountain fixtures	6	
8. School Electrical System	ns .	4.3		919 Soft water system	0	
801 Lightin	g systems	7		920 Steam lines and traps	N/A	
802 Proper	Exit Signs	7		See Steam lines and traps		
803 Buildin	ng Power system		10. Future	Mondo		5.3
804 a. M	lain power service to building	7	IO. Futule			3.3
	mergency generator	0		1001 Capability for Expansion	- 6	
806 c. Ad	dequate classroom power	5		1002 Capability for Portables	- 6	
807 Securit	ty system	О		1003 Energy efficiency rating	4	
808 Clocks		0		1004 Adaptability for Technology	5	
809 Access	control system	0				
810 CCTV s	system	0	Notes			
811 Data sy	ystems	9				
812 Wirele	ss access	9	Special ne	eeds		
813 MDF/II	DF Room	6		WeatherTrak Irrigation controller		
814 Stage I	ighting/Sound systems	N/A		ADA Upgrade to playground equipment		

Page 45

Middle Canyon Elementary



751 East 1000 North Tooele, Utah 84074 435-833-1906





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	79.4
Original Building	2002	52,696	District Average	65.6
Classrooms addition	2007	2,600	Rating System 1 to 100	
Total Building		55,296		
			Special Needs or Actions	
Current Student Enrollment	493		 Install sidewalk on east side of 	the driveway
Ideal Capacity	675		 ADA upgrade to the playground 	equipment
Stretch Capacity	700		 Remove part of the main canop 	y to open up
Maximum Capacity	800		the sidewalk	

Middle Canyon Elementary



School Assessment Building Condition	Total Score 79.4	3. Interior	8.0
870		301 General Aesthetics	8
		302 Administration office complex	. 8
Rating System 1 to 10 , 1=Poor 10=Excellent		303 Proper egress corridors/doors	9
		304 Multi-propose room	<u> </u>
Factors	Rating Score	505 Special needs rooms	8
1. Exterior Building	8.1	30 b Me dia Center	
101 General Aesthetics	8	307 Storage rooms	
102 Exterior walls	- 8	508Computer labs 309W indows/Glass	1
103 Exterior Doors	8	310 Doors	
104 ADA Automatic door operators	9	511 a. Condition	8
105 ADA complaint entrances	9	312 b. ADA Door Hardware	9
106 Windows	8	313ADA Access to all spaces	9
107 Roofing		514 Signage	8
and the second of the second o		315 Flooring	100
108 Flashing	8	316 a.carpet 317 b.VCT	1 3
109 Canopies		318 c. Specialtype	- 1
110 Vestibules	8	319 Walls	a
		320Cerling	8
2. Exterior Site	7.6	321 Stairs, ramps and hand railing	8
201 Landscaping		322ADA Lifts	
202 a. Irrigation System	്ള	323Seismic needs	9
203 b. Turf	6	324A dequacy of custodial spaces	
204 c. Planting	6	4. Teaching Environment	8.0
205 Playgrounds		401 Adequate heating, cooling and ventilation	8
206 a. ADA compliant	7	40.2 Proper lighting and lighting control	8
207 b. Equipment		403 Adequate power needs	8
		404 Classroom so und systems	7
208 c. Playground safety	8	40.5 Classroom technology	
209 d. Playfields	7	40 b LDC projectors in classrooms	7
210 Asphalt condition	- 8	407 Classroom safe ty 408 Windows/blinds	- 1
211 Fencing	8	409 Classroom doors with a window	1
212 Student drop-off area	- 6	410 White boards	9
213 Traffic control	6		V ² 2 27
214 Bus Lane	8	5. Building Restrooms	8.3
215 ADA Side walks	8	501 ADA Compliant	9
216 ADA Access to building	8	502 Partitions	8
217 ADA Parking	9	503 Lavatories and faucets 504 Water closets with flush valves	
218 Adequate parking	7	505 Urinals with flush valves	<u> </u>
219 Stairs, ramps and hand railing	8	50 b Flooring	. 8
220 Storm drainage system	<u> </u>	507 Walls	8
		508 Cerlings	8
221 a. Site drainage	8	509 Exhaust fans	8
222 b. Storm water detention	8	510E mergency Lighting	9
223 Fire truck access	9	511 Floor Drains	3
224 Fire hydrant location and access	e		

Page 47

Middle Canyon Elementary



6. Life Safety	8.6	9. School Mechanical & Plumbing Systems	7.6
601 Fire alarm system	8	901Boiler	8
602 Proper egress	9	902 Chiller	8
603 Intercom system	7	903 Cooling towers	
604 Fire Extinguisher placement	9	904 Pumps	8
605 AED's	9	905 Water heaters	8
606 Fire Sprinkling systems	9	906 Hydronic components	
607 Emergency egress Lighting	9	907Temperature controls systems	
Fire department emergency radio & cell phone 608 buster		908 Air handling units/fans rooms	
L Company	I 8	909A/C units	
7. Kitchens/Serving	8.0	910 Air compressors	
701 Cooking equipment	8	911 Exhaust fans	
702 Refrigerating /freezing equipment	8		
703 Kitchen hood & suppression system		912 Unit heaters & Cabinet heaters	<u> </u>
704 Storage	8	913 Exterior hose bibs	8
705 Serving Counter	8	914 Roof drainage system	8
706 Fire Extinguishers K type where needed	8	915 Sewer drain lines	8
707 Make-up air systems	8	916 Grease interceptor	7
708 Exhaust Fans	8	917 Building water lines	8
		918 ADA Compliant Drinking fountain fixtures	9
8. School Electrical Systems	8.0	919 Soft water system	8
801 Lighting systems	8	920 Steam lines and traps	
802 Proper Exit Signs	9		
803 Building Power system		10. Future Needs	7.3
804 a. Main power service to building	9	1001 Capability for Expansion	6
805 b. Emergency generator	9	1002 Capability for Portables	7
806 c. Adequate classroom power	8	1003 Energy efficiency rating	8
807 Security system	9	1004Adaptability for Technology	
808 Clocks	9		
809 Access control system	9	Notes	
810 CCTV system	4		
811 Data systems	9	Special needs	
812 Wireless access	8	WeatherTrak Irrigation controller	
813MDF/IDF Room	8	ADA Upgrade to playground equipment	
814 Stage lighting/Sound systems	7	Install sidewalk on east side of driveway	
ton ton totale MA		remove part of the main canopy	

Northlake Elementary



268 North Coleman Street Tooele, Utah 84074 435-833-1943





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	73
Original Building	1993	72,590	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	521		 WeatherTrak Irrigation controller 	
Ideal Capacity	775		 ADA upgrade to playground equipment 	
Stretch Capacity	800		 Upgrade old T-12 lighting to T-8 	
Maximum Capacity	950		Install new FX controller for DDC to get rid phonoling	of
Maximum Capacity	950		 Install new FX controller for DDC to get rid phone line 	of

Northlake Elementary




			3. Interior		7.6
School Assessment Building Condition	Total Score	73.0	3.11101101	301 General Aesthetics	7
				302 Administration office complex	8
				303 Proper egress corridors/doors	9
Rating System 1 to 10 , 1=Poor 10=Excellent				304 Mult ⊢propose room	8
u ■ 200 ± 200 200 2	1 mar. 10 mm	600		305 Special needs rooms	8
Factors	Rating Score			30b Media Center	8
1. Exterior Building		7.5		307 Storage rooms 308 Computer labs	1
101 General Aesthetics	7			309 Windows/Glass	, , , , , , , , , , , , , , , , , , ,
102 Exterior walls	7			310 Doors	
103 Exterior Doors	7			311 a. Condition	- a
104 ADA Automatic door operators	8			312 b. ADA Door Hardware	
105 ADA complaint entrances	9			313 ADA Access to all spaces	9
106 Windows	8			314 Signage	8
107 Roofing	7			315 Flooring 315 a. carpet	
108 Flashing	8			317 b. VCT	
109 Canopies	3			318 c. Special type	7
	1 1			319 Walk	7
110 Vestibules				320 Ceiling	. 8
	8			321 Stairs, ramps and hand railing	N/A
2. Exterior Site		7.5		522 ADA Lifts	N/A
201 Landscaping				323 Seis mic needs	
202 a. Irrigation System	8			324 Adequacy of custodial spaces	
203 b. Turf	6		4. Teaching Environ	ment	7.7
204 c. Planting	6			401 Adequate heating, cooling and ventilation	8
205 Playgrounds				402 Proper lighting and lighting control	а
206 a. ADA compliant	7			403 Adequate power needs	ь
207 b. Equipment	7			404 Classroom sound systems	8
208 c. Playground safety	7			405 Classroom technology	8
209 d. Playfields	1 1			40b LDC projectors in classrooms 407 Classroom safety	1
	1			408 Windows/blinds	A
210 Asphalt condition	+			409 Classroom doors with a window	9
211 Fencing	8			410 White boards	а
212 Student drop-off area	7			411 Classroom furniture	6
213 Traffic control	7				
214 Bus Lane	7		 Building Restroom 		7.7
215 ADA Side walks	8			501 ADA Compliant 502 Partitions	
216 ADA Access to building	8			503 Lavatories and faucets	- 1
217 ADA Parking	9			504 Water closets with flush valves	
218 Adequate parking	7			505 Urinals with flush valves	7
219 Stairs, ramps and hand railing	7			506 Flooring	8
220 Storm drainage system				507 Walls	8
221 a. Site drainage	7			508 Cellings	8
222 b. Storm water detention	 			509 Exhaust fans	H
	<u> </u>			510 Emergency Lighting 511 Floor Drains	
223 Fire truck access	9			and delivery and the contract and	~
224 Fire hydrant location and access	9				

Page 50

Northlake Elementary





Overlake Elementary



2052 North 170 West Tooele, Utah 84074 435-843-3809






Facility Assessment Summary

Building Information			Facility Conditions Summary		
	Year	Square Feet			
			Facility Condition Score	80.3	
Original Building	2002	52,693	District Average	65.6	
Classrooms addition	2007	2,600	Rating System 1 to 100		
		55,293			
			Special Needs or Actions		
Current Student Enrollment	584		 ADA upgrade to playground equipment 		
Ideal Capacity	650				
Stretch Capacity	675				
Maximum Capacity	825				

Overlake Elementary





Page 53

Overlake Elementary



6. Life Safety 9. School Mechanical & Plumbing Systems		8.0
601 Fire alarm system 8 901 Boiler	3	
602 Proper egress 902 Chiller	3	
603 Intercom system		
604 Fire Extinguisher placement 9 904 Pumps	8	
605 AED's 9 905 Water heaters	8	
606 Fire Sprinkling systems 9 906 Hydronic components	8	
607 Emergency egress Lighting 9 907 Temperature controls systems	8	
608 Fire department emergency radio & cell phone buster 0 908 Air handling units/fans rooms	8	
909 A/C units	8	
7. Kitchens/Serving 8.d 910 Air compressors	8	
701Cooking equipment 8 911 Exhaust fans	8	
702 Refrigerating /freezing equipment 8 912 Unit heaters & Cabinet heaters	8	
703 Kitchen hood & suppression system 8 913 Exterior hose hibs	8	
704 Storage 914 Roof drainage system		
705 Serving Counter		
706 Fire Extinguishers K type where needed 8	- 3	
017 Pullding victor lines	<u> </u>	
708 Exhaust Fans 8 917 Bullung water lines 918 ADA Compliant Drinking fountain fixtures		
To a contract the contract to		
	1	
	4 <u> </u>	
802 Proper Exit Signs 9	Transfer of the second	7.1
803 Building Power system 10. Future Needs		7.5
804 a. Main power service to building 9 1001 Capability For Expansion	<u> </u>	
805 b. Emergency generator 9 1002 Capability For Portables	<u> </u>	
806 c. Adequate classroom power 8 1003 Energy efficiency rating	8	
807 Security system 9 1004 Adaptability for Technology	8	
808 Clocks 9		
809 Access control system 9 Notes		
810CCTV system 0		
811 Data systems Special needs		
812 Wireless access 8 WeatherTrak Irrigation controller		
813 MDF/IDF Room 8 ADA Upgrade to playground equipment		
814 Stage lighting/Sound systems 7 Install new CCTV system		

Rose Springs Elementary



5349 North Insbrook Place Stansbury Park, Utah 84074 435-833-1950





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	80.5
Original Building	2005	55,293	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	841		 ADA upgrade to the playground equipment 	
Ideal Capacity	650		 Install an WeatherTrak irrigation controller 	
Stretch Capacity	675		 Install CCTV system 	
Maximum Capacity	875		 Add one more bicycle pad and racks 	

Rose Springs Elementary



Rating Score	80.5 8.4	301 General Aesthetics 502 Administration office complex 503 Proper egiress corridora/doors 504 Multi-propose room 503 Special needs rooms 505 Media Ceriter 507 Storage rooms 508 Computer labs 509W indows/Glass 510 Doors 511 a. Condition 512 b. ADA Door hardware 513 ADA Access to all spaces 514 Signage	8 8 9 8 8 8 8 9 8
Rating Score 8 8 9 9 9 9	8.4	301 Proper agress corndors/doors 304 Multi-propose room 305 Special needs rooms 305 Media Center 307 Storage rooms 306Computer labs 309W indows/Class 310 Doors 311. a. Condition 31.2 b. ADA Door Hardware 313 AD Access to all spaces	8 9 8 8 8 9 8
8 8 9 9 9 9 9 8	8.4	304 Multi-propose room 305 Special needs rooms 306 Media Center 307 Storage rooms 308 Computer libbs 309W indows/Glass 310 Doors 311 a. Condition 312 b. ADA Door Hardware 313 ADA Access to all spaces	9 8 8 8 9 8
8 8 9 9 9 9 9 8	8.4	30.5 pecial needs rooms 30 bMedia Cainter 30 73 chage rooms 30.8 Computer labs 309W indows/Glass 31.0 Poors 31.1 a. Condition 31.2 b. ADA Door Hardware 31.3 ADA Access to all spaces	8 8 8 8 9 8
Rating Score	8.4	30 b Me dia Ce mer 30 7 30 dage rooms 30 8 Computer labs 30 9 W mdows/Cilass 31 0 Doors 31 1	8 8 9 8 8
8 9 9 9	8.4	307 Storage rooms 308 Computer labs 309 Windows/Class 310 Doors 31.1 a. Condition 31.2 b. ADA Door Hardware 31.3 ADA Access to all spaces	8 9 8 8
8 9 9 9 9		508Computer labs 509W indows/Class 310 Doors 51.1 a. Condition 31.2 b. ADA Door hardware 313 ADA Access to all spaces	8 8 9
න ඉ ඉ ඉ		309W indows/Glass 310 Doors 311 a. Condition 312 b. ADA Door Hardware 313 ADA Access to all spaces	
9 9 9		511 a. Condition 312 b. ADA Door Hardware 313 ADA Access to all spaces	
9 9 9		312 b. ADA Door Hardware 313 ADA Access to all spaces	9
9		313 A DA Access to all spaces	9
9			
8			
		315 Flooring	9
		315 nooning 316 a.carpet	
- 8			,
8			7
8		319 Walls	8
-		320Cerling	
	8.1	321Stairs, ramps and hand railing	N/A
		322ADA Lifts	N/A
9		323Seismic needs	9
8		324A dequacy of custodial spaces	
7		4 Teacher Francomant	E B
8		402 Proper lighting and lighting control	8
8		403 Adequate power needs	8
		404 Classroom sound systems	8
7		405 Classroom technology	
			8
			9
- 8			9
- 4			
7			8
8			W 32
8		5. Building Restrooms	8.3
9		501ADA Compliant	9
9		502 Partitions	8
8		503 Lavatories and faucets	
8			
8			
8		508 Cerlings	8
9		509 Exhaust fans	8
		510 Emergency Lighting	9
		511 floor Drains	9
	8 8 8 9 9 9 9 9 9 9 9 9	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 9 9 9 9 9 8	### 8.1 ### 32.00 ceiling ### 30.00 ceiling ###

Page 56

Rose Springs Elementary



6. Life Safety	7.9	9. School Mechanical & Plumbing Systems	8.1
601 Fire alarm system	9	901 Boiler	8
602 Proper egress	9	902 Chiller	8
603 Intercom system	9	903 Cooling towers	N/A
604 Fire Extinguisher placement	9	904 Pumps	8
605 AED's	9	905 Water heaters	8
606 Fire Sprinkling systems	9	906 Hydronic components	8
607 Emergency egress Lighting	9	907 Temperature controls systems	8
608 Fire department emergency radio & cell phone buster	О	908 Air handling units/fans rooms	8
	70	909 A/C units	8
7. Kitchens/Serving	8.0	910 Air compressors	8
701 Cooking equipment	8	911 Exhaust fans	8
702 Refrigerating /freezing equipment	- 8	912 Unit heaters & Cabinet heaters	8
703 Kitchen hood & suppression system	8	913 Exterior hose bibs	8
704 Storage	8	914 Roof drainage system	8
705 Serving Counter	8	915 Sewer drain lines	8
706 Fire Extinguishers K type where needed	8	916 Grease interceptor	8
707 Make-up air systems	8	917 Building water lines	8
708 Exhaust Fans	8	918 ADA Compliant Drinking fountain fixtures	9
		919 Soft water system	8
8. School Electrical Systems	7.6		N/A
801 Lighting systems	8		\$1.5
802 Proper Exit Signs	9	10. Future Needs	7.8
803 Building Power system		1001 Capability for Expansion	7
804 a. Main power service to building	9	1002 Capability for Portables	8
805 b. Emergency generator	9	1003 Energy efficiency rating	8
806 c. Adequate classroom power	9	1004 Adaptability for Technology	8
807 Security system	8		Al
808 Clocks	8	Notes	
809 Access control system	8		
810 CCTV system	0	Special needs	
811 Data systems	9	WeatherTrak Irrigation controller	
812 Wireless access	8	ADA Upgrade to playground equipment	
813 MDF/IDF Room		Install CCTV system	
814 Stage lighting/Sound systems	8	Add one more bicycle pad and racks	
		Add the more projule pad and racks	

Page 57

Stansbury Park Elementary

TEACH LEAD TOOLLE COUNTY SCHOOL DISTRICT CHARMAN CONTACT CHAR

485 Country Club Stansbury Park, Utah 84074 435-833-1968





• Replace glazing in foyer with insulated glass

Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score 64	1.1
Original Building	1978	45,105	District Average 65	.6
Classroom Addition	1997	14,791	Rating System 1 to 100	
Total School		59,896		
			Special Needs or Actions	
Current Student Enrollment	900		 New staff parking lot 	
Ideal Capacity	775		Seismic needs	
Stretch Capacity	800		Need to brace all parapet walls above the	
Maximum Capacity	900		roof line	
			 ADA upgrade to playground equipment 	
			 Add a one more set of faculty restrooms 	
			 Install power factor correction capacitor bank 	

Stansbury Park Elementary




School Assessment Building Condition Total Score 64.1 Section Sect		-	vi schools	
Part Total Store Total S		3.		6.7
Stating System 1 to 10.1 - Pro or 10-boxillers	School Assessment Building Condition	Total Score 64.1		
Section 10 10 1 - Price 10 - Decident				
Part 10 10 10 10 10 10 10 1				7
	Rating System 1 to 10, 1=Poor 10=Excellent			
1. Dit General Assistances 2 200				7
101. General Assembles	TO A LONG CONTROL OF A CONTROL	A CONTRACT OF THE PROPERTY OF	507 Storage rooms	7
100 Description Valle		6.9	308 Computer labs	7
100 Deterior Doors	101 General Aesthetics	7	309 Windows/Glass	
104 ADA Accounted Geory Corpettor's	102 Exterior walls	7	310 Doors	
13 AAA Complaint ent rances 1	103 Exterior Doors	6	311 a. Condition	Б
105 AUA complaint enterances 9	104 ADA Automatic door operators	- 6		5
100 Mindows	105 ADA complaint entrances	8		8
107 Roofing		7		Б
1.08 Flashing		- 7		
10 10 10 10 10 10 10 10				
110 Vestibules	10	1		
1.10 Vestibules		N/A		
1.1. 1.2.	110 Vestibules	7		Б
323 seams needs		(2		N/A
202 a. Irrigation System 203 b. Turf 204 c. Planting 205 Playgrounds 206 playgrounds 206 a. ADA compliant 207 b. Equipment 208 c. Playground safety 209 d. Playfrields 200 d. Playfrields 200 d. Playfrields 201 Asphalt condition 201 Playfrields 201 Asphalt condition 202 Flore in this play in the basids 203 flore in this play in the basids 203 flore in this play in the basids 204 b. Equipment 205 d. Playground safety 206 d. Playfrields 207 d. State on the shoolesy 209 d. Playfrields 208 c. Playground safety 209 d. Playfrields 209 d. Playfrields 200 d. Playfrields 200 d. Playfrields 200 d. Playfrields 201 Asphalt condition 201 depreciation in classooms 202 d. Playfrields 203 d. Playfrields 204 d. Playfrields 205 d. Playfrields 20	2. Exterior Site	6.2	522 ADA Lifts	
205 b. Turf	201 Landscaping		323 Seismic needs	ь
203 b. Turf 204 c. Planting 6	202 a. Irrigation System	5	324 Adequacy of custodial spaces	7
A Teaching		6		
205 Playgrounds		4.		6.8
ADA compliant 7	300.00 TO			- 7
207 b. Equipment 7 208 c. Playground safety 8 209 d. Playfields 6 210 Asphalt condition 7 211 Fencing 6 212 Student drop-off area 4 213 Traffic control 4 214 Bus Lane 6 215 ADA Side walks 6 216 ADA Parking 7 217 ADA Parking 7 218 Adequate parking 7 219 Adequate parking 7 219 Storm drainage system 8 210 Storm drainage system 8 210 Storm drainage system 9 211 Student drop-off area 9 212 Student drop-off area 9 213 Traffic control 9 214 Bus Lane 9 215 ADA Side walks 9 216 ADA Access to building 7 217 ADA Parking 7 218 Adequate parking 9 218 Adequate parking 9 219 Stairs, ramps and hand railing 9 210 Storm drainage system 9 211 a. Site drainage 9 212 a. Site drainage 9 213 Etruck access 9 214 Bus Lane 9 215 Storm water detention 9 215 Storm water detention 9 216 ADA Side walks 9 217 ADA Parking 9 218 Adequate parking 9 219 Stairs, ramps and hand railing 9 210 Storm water detention 9 211 ADA Side walks 9 212 a. Site drainage 9 213 Storm water detention 9 214 Storm water detention 9 215 Storm water detention 9 215 Storm water detention 9 216 Storm water detention 9 217 ADA Side walks 9 218 Adequate parking 9 219 Stairs, ramps and hand railing 9 210 Storm water detention 9 211 ADA Side water doze by the flush valves 9 212 a. Site drainage 9 213 Storm water detention 9 214 Storm water detention 9 215 Storm water detention 9 215 Storm water detention 9 216 Storm water detention 9 217 ADA Side water doze by the flush valves 9 218 Storm water detention 9 219 Storm water detention 9 219 Stairs drainage 9 220 Storm water detention 9 221 Storm water detention 9 222 Storm water detention 9 223 Fire truck access 9 224 Storm water detention 9 225 Storm water detention 9 226 Storm water detention 9 227 Storm water detention 9 228 Storm water detention 9 229 Storm water detention 9 230 Storm water detention 9 240 Storm water detention 9 250 Storm water detention 9 251 Storm water detention 9 252 Storm water detention 9 253 Storm water detention 9 254 Storm water detention 9 255 Storm water detention 9 255 Storm water detention 9				- 1
208 c. Playground safety 8 400 Classroom technology 7 209 d. Playfields 6 400 IDC projectors in classrooms 7 210 Asphalt condition 7 211 Fencing 6 400 Windows/Blinds 7 212 Student drop-off area 4 410 White boards 7 213 Traffic control 4 411 Classroom furniture 7 214 Bus Lane 6 5 . Building Restrooms 7 215 ADA Side walks 6 5 .00 Invitable 8 7 217 ADA Parking 7 500 Lavatores and faucets 4 7 218 Adequate parking 7 500 Ward closets with flush valves 7 219 Storin, ramps and hand railing N/A 500 Invitable walks 7 210 Storm drainage system 5 5 500 Ward closets with flush valves 7 210 Storm water detention 5 5 500 thaust fare 7 211 For Draine 7 212 Fire truck access 8 8 511 Hoof Draine 7 213 Fire truck access 9 511 Hoof Draine 7 214 For Draine 7 215 Fire truck access 9 5 511 Hoof Draine 7 217 Fire truck access 9 5 511 Hoof Draine 7 218 Fire truck access 9 5 511 Hoof Draine 7 219 Storm water detention 7 219 Storm water detention 7 210 Fire truck access 8 511 Hoof Draine 7 211 Hoof Draine 7 212 Fire truck access 9 5 510 Hoof rage 9 7 213 Fire truck access 9 7		4		-
208 c. Playground safety 209 d. Playfields 5		7		7
210 Asphalt condition	208 c. Playground safety	- 8		7
211 Fencing	209 d. Playfields	- 6	407 Classroom safety	8
212 Student drop-off area 4 41 Classroom furniture 213 Traffic control 4 411 Classroom furniture 214 Blus Lane 5 5 . Building Restrooms 7.1 215 ADA Side walks 6 5 . Building Restrooms 7.1 216 ADA Access to building 7 501 Lavatories and faucets 2 7 217 ADA Parking 7 501 Lavatories and faucets 2 7 218 Adequate parking 5 504 Water closets with flush valves 7 219 Stairs, ramps and hand railling N/A 5061 looring 907 walk 907 water detention 909 kthaust fans 900 kthaust fan	210 Asphalt condition	×7	408 Windows/blinds	7
A All Classroom furniture All Classroom furn	211 Fencing	- 6		<u> </u>
213 Tarfric control 214 Bus Lane 5	212 Student drop-off area	-4		7
215 ADA Side walks 6 SO1 ADA Complant 8 2 216 ADA Access to building 7 SO2 Partitions 7 SO2 Partitions 7 SO3 Water closets with flush valves 7 SO3 Water closets with flush valves 7 SO3 Water closets with flush valves 7 SO3 Urnals with flush v	213 Traffic control	4	411 Classroom furniture	<u> </u>
215 ADA Side walks 6 501.ADA Complaint 8 2 2 2 2 Fire truck access 6 building 7 501.ADA Complaint 8 2 2 2 2 2 2 2 5 501.ADA Complaint 8 2 5 501.ADA Complaint 8 2 5 501.ADA Complaint 8 2 5 502.ADA Complaint 8 2 502.ADA	214 Bus Lane		Bruddon Baston and	223
216 ADA Access to building 7 502 Partitions 7 217 ADA Parking 7 503 Lavatories and faucets 2 7 7 218 Adequate parking 5 504 Water close ts with flush valves 7 7 219 Stairs, ramps and hand railing N/A 504 Flooring 7 7 507 Walls 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7				, , , , , , , , , , , , , , , , , , ,
217 ADA Parking 7 505 Lavatories and faucets 2 2 218 Adequate parking 5 504 Water closets with flush valves 7 219 Stairs, ramps and hand railing N/A 506 Flooring 7 220 Storm drainage system 507 Wals 7 221 a. Site drainage 5 5 506 Callings 7 222 b. Storm water detention 5 509 Exhaust flans 7 223 Fire truck access 8 510 Fine rightly lightly or 7 210 Flooring 7 224 5 Storm water detention 5 500 Exhaust flans 7 225 Fire truck access 8 510 Fine rightly lighting 7				
217 AGR Farring	257	- 1		7
219 Stairs, ramps and hand railing	5 C C C C C C C C C C C C C C C C C C C	1		7
220 Storm drainage system		5	505 Urinals with flush valves	7
221 a. Site drainage 5 .508 Ceilings 2 222 b. Storm water detention 5 .500 Exhaust fans .7 223 Fire truck access 8 .510 Emergency Lighting .7 311 Floor Drains .7		N/A	506 Flooring	
222 b. Storm water detention 5 509 txhaust fans 7 223 Fire truck access 8 510 tree gency Lighting 7	220 Storm drainage system		507 Walls	<u> </u>
222 5. Storm water determine	221 a. Site drainage			<u> </u>
223 Fire truck access 8 511 foor Drains 7	222 b. Storm water detention	5		<u>├</u>
	223 Fire truck access	8		<u> </u>
	224 Fire hydrant location and access	8	511 Floor Drains	- 1
	## ## ## ## ## ## ## ## ## ## ## ## ##	×		

Page 59

Stansbury Park Elementary





Stansbury High School



5300 North Aberdeen Lane Stansbury Park, Utah 84074 435-882-2479






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	89.8
Original Building	2009	241,984	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	1597		 Addition to the lunchroom 	
Ideal Capacity	1313		 Expand welding shop 	
Stretch Capacity	1600		 Add a 12 classroom addition 	
Maximum Capacity	1800			

Stansbury High School






Page 62

Stansbury High School





Page 63

Settlement Canyon Elementary



935 West Timpie Road Tooele, Utah 84074 435-882-4597






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	85.4
Original Building	2008	57,268	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	673		 Install an WeatherTrak irrigation controller 	
Ideal Capacity	675		 No room for portables on this site 	
Stretch Capacity	700			
Maximum Capacity	700			

Settlement Canyon Elementary





Page 65

Settlement Canyon Elementary



6. Life Safety	9.13	9. School Mechanical & Plumbing Systems		9.06
601 Fire alarm system	10	901Boiler	9	
602 Proper egress	10	902 Chiller	9	
603 Intercom system	9	903 Cooling towers	N/A	
604 Fire Extinguisher placement	9	904 Pumps	9	
605 AED's	9	905 Water heaters	9	
606 Fire Sprinkling systems	10	906 Hydronic components	9	
607 Emergency egress Lighting	10	907Temperature controls systems	9	
608 Fire department emergency radio & cell phone buster	6	908 Air handling units/fans rooms	9	
discovered to the second secon	The second of	909 A/C units	9	
7. Kitchens/Serving	8.75	910 Air compressors	9	
701 Cooking equipment	8	911 Exhaust fans	9	
702 Refrigerating equipment	8	912 Unit heaters & Cabinet heaters	9	
703 Kitchen hood & suppression system	9	913 Exterior hose bibs	9	
704 Storage	8	914 Roof drainage system	9	
705 Serving Counter	9	915 Sewer drain lines	9	
706 Fire Extinguishers K type where needed	10	916 Grease interceptor	9	
707 Make-up air systems	9	917 Building water lines	9	
708 Exhaust Fans	<u> </u>	918ADA Compliant Drinking fountain fixtures	10	
and any testing of Cartilla to the Article Cartilla Carti		919Soft water system	9	
8. School Electrical Systems	8.82	920 Steam lines and traps	N/A	
801Lighting systems	9	Security of the Property of the American Control of Con		
802 Proper Exit Signs	10	10. Future Needs		5.50
803 Building Power system		1001 Capability for Expansion	3	
804 a. Main power service to building		1002 Capability for Portables	3	
805 b. Emergency generator	1	1003Energy efficiency rating	8	
806 c. Adequate classroom power		1004Adaptability for Technology	8	
807 Security system	1	, , , , , , , , , , , , , , , , , , , ,		
808 Clocks	1	Notes		
809Access control system	1	No room for portables on this site		
810 CCTV system	1	110 TOOM TOT POTEBBLES OF CHIS SICE		
811 Data systems	1	Special needs		
812 Wireless access	 	WeatherTrak Irrigation controller		
813MDF/IDF Room	1	ADA Upgrade to playground equipment		
814 Stage lighting/sound system	<u> </u>	ADA opgrade to playground equipment		

Tooele High School



301 West Vine Street Tooele, Utah 84074 435-833-1975





Facility Assessment Summary

Maximum Capacity

Building Information		
	Year	Square Feet
IA Building	1949	26,465
Auto Shop	1975	6,510
Auditorium	1969	37,495
New School	2003	168,714
Lunchroom Addition	2006	2,311
Total Building		241,495
Current Student Enrollment	1502	
Ideal Capacity	1317	
Stretch Capacity	1600	

1900

Facility Conditions Summary


Facility Condition Score	75.5
District Average	65.6
Rating System 1 to 100	

Special Needs or Actions

- The IA Building and Auditorium need a seismic upgrade
- The IA Building and Auditorium need a fire sprinkling system installed
- Fitness center addition
- Need to replace the tennis court
- Need to replace the restroom and concession building on the football field
- Major upgrade to the running track

Tooele High School





Page 68

Tooele High School



6. Life Safety		and a second	7.50	9. School Mecha	inkal& Plumbing Systems	7.74	
enconnicators.	601 Fire alarm system	9			901 Boiler		
	602 Proper egress				902 Chiller 903 Cooling tower	N/A	
	Published Company (Control of the Control of the Co	9			904 Pumps	N/A A	
	603 Intercom system	9			905 Water heaters	8	
	604 Fire Extinguisher placement	9			906 Hydronic components		
	605 AED's	8			907 Tem perature controls systems		
	606 Fire Sprinkling system ³	7			908 Air handling units/fan rooms 909 A/C units		
	607 Emergency egress Lighting	9			910 Air compressors	. 8	
	608 Fire department emergency radio & cell phone buster	D			911 Exhaust fans		
	out the department entre general reads at sent priorite season.				912 Unit heaters & cabinet heaters	- 8	
6	The state of the s		0.00		913 Dust Collectors 914 Roof drainage system	- B	
7. Kitchens/S			8.00		915 Sewer drain lines		
	701 Cooking equipment	8			916 Grease Interceptor	- 8	
	702 Refrigerating /freezing equipment	8			917 Building water lines	7	
	703 Hood suppression system	8			918 ADA Complaint Drinking fountain fixtures	8	
	704 Storage	8			919 Soft water system 920 Steam lines and traps	. 8	
	705 Serving Counter	8			Assistant lines and traffe		
	706 Fire Extinguishers K type where needed	8		10. Future Need		5.75	i
	707 Make-up air systems	8			1001 Capability for Expansion 1002 Capability for Portables	- 4	
	708 Exhaust fans				1003 Energy efficiency rating	7	
	706 Exhaust lans				1004 Adaptability for Technology		
8. School Elec	strical Systems		7.85	Notes			
	801 Lighting systems	8	700.00		The 2003 potion of the school is in great shape the older IA Building and		
	802 Proper Exit Signs	0			Auditorium are in ned of some work		
	803 Building Power system				² We need to have a Seismic upgrade to the IA Building and Auditorium		
	804 a. Main Power service to building				⁵ The IA Building and Auditorium are not fire sprinkled		
	Sense und Sense Se				*We have no back up power to the IA Building and Auditorium		
	805 b. Emergency generator ⁴	8		Special needs			
	806 c. Adequate classroom power	8			Sesmicity Needs from the Rapid Visual Screening of buildings done by Ens	gn Engineering	
	807 Security system	8			a. Detailed evaluation recommended		
	808 Clocks	8			b. The IA building and the auditorium need to be updated		
	809 Access control system	8			Fitness center addition Curtains in auditorium need to be replaced		
	810 CCTV system	7			Replace tennis courts		
	811 Data systems	7			Replace all the football field restroom and concessions building into one la	rge facility	
	812 Wireless access	7			Repair and resurface the running track		
	813 MDF/IDF Room	9			Upgrade the lighting to T8's where needed Upgrade lockers in the band room		
	The state of the s	-			Modernize the inside doors in the auditorium rooms		
	814 Stage Lighting /Sound	8			Adda gas fired kiln for the ceramic room		
					WeatherTrak water controller		

Tooele Jr. High School



411 West Vine Street Tooele, Utah 84074 435-833-1923






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	53.9
Original Building	1963	95,189	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	846		 Needs an upgrade to the fire alarm system 	
Ideal Capacity	600		 Install emergency backup power and lighting 	
Stretch Capacity	800		 Upgrade power to the school and classrooms 	
Maximum Capacity	1100		 Install a chiller for air conditioning 	
			 Upgrade DDC controls 	
			 ADA upgrade to all restrooms 	

Tooele Jr. High School





Page 71

Tooele Jr. High School



6. Life Safety		4,88	9. School Mei	chanical & Plumbing Systems	3.83
reaction unable to the extra	LANCON DIA MANDE DE PROPRIATA PROPRIATA PORTO	4.00		901 Boiler	5
	Fire alarm system	<u>6</u>		902 Chiller	N/A
6021	Proper egress	9		903 Cooling tower	N/A
6031	Intercom system	6		904 Pumps	4
6041	Fire Extinguisher placement	8		905 Water heaters	5
605 A	AED's	9		906 Hydronic components 907 Temperature controls systems	4
6061	Fire Sprinkling system	0		908 Air handling units/fan rooms	4
	Emergency egress Lighting	1		909 A/C units	3
				910 Air compressors	5
6081	Fire department emergency radio & cell phone buster			911 Exhaust fans	-4
		r		912 Unit heaters & cabinet heaters	4
7. Kitchens/Serving		5.25		913 Dust Collectors	3
7010	Cooking equipment	6		914 Roof drainage system 915 Sewer drain lines	4
702	Refrigerating /freezing equipment	6		916 Grease interceptor	0
7031	Hood suppression system	5		917 Building water lines	4
7045	Storage	6		918 ADA Complaint Drinking fountain fixtures	4
	Serving Counter	6		919 Soft water system	5
	Fire Extinguishers K type where needed			920 Steam lines and traps	
			10. Future Ne	and c	5.75
	Make-up air systems		ID. I DEBIE IVE	1001 Capability for expansion	6
7081	Exhaust fans	5		1002 Capability for portables	3
				1003 Energy efficiency rating (no refrigerated A/C)	8
8. School Electrical St	ystems	4.62		1004 Adaptability for Technology	6
8011	Lighting systems	6	Notes		
802 F	Proper Exit Signs	8			
8031	Building Power system		Special needs	€	
804	a. Main Power service to building	5		Seismicity Needs from the Rapid Visual Screening of buildings done	by Engine Engineering
805	b. Emergency generator	D		Detailed evaluation recommended, but is a low priority	E DY CHSIGH CHGINEETING
806	c. Adequate classroom power	4		Needs an upgrade to fire alarm system	
807	Security system	3		Classroom wing with ten classrooms	
808	Clocks	3		Install emergency backup power and lighting	
809	Access control system	О		Upgrade power to the school and restrooms Install a chiller	
810	CCTV system	4		ADA upgrade to restrooms	
	Data systems	8		Repair or replace water lines in the tunnels	
	Wireless access	8		Replace all the curtains in the classrooms with blinds	
	MDF/IDF Room			Install WeatherTrak water controller Install new FX controller for DC to get rid of phone line	
				Upgrade DDC controls	
814	Stage Lighting/Sound	4		10 EV	

Vernon Elementary School



70 North Main Vernon, Utah 84080 435-839-3433





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	36.3
Original Building	1929	5,521	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	21		 ADA upgrade to the restrooms 	
Ideal Capacity	50		 ADA upgrade to the playground equipment 	
Stretch Capacity	75		 Upgrade old T-12 lighting to T-8 	
Maximum Capacity	100		 Upgrade old coal stoker furnace 	
			 Bell tower is a falling hazard and 	
			needs to be reinforced	

Vernon Elementary School



			3. Interior	3.8
School Assessment Building Condition	Total Score	36.3	301 General Aesthetics	3
			302 Administration office complex	> 0
FORCE ST. 10 10075 S. 100 DE 1001			303 Proper egress corridors/doors	8
Rating System 1 to 10 , 1=Poor 10=Excellent			304 Multi-propose room	
Factors	Rating Sco		305 Special needs rooms	
Way the first the control of the con	Rating Stu	4.1	306 Media Center	
1. Exterior Building		4.1	307 Storage rooms 308 Computer labs	 :
101 General Aesthetics	3		309 Windows/Glass	
102 Exterior walls	3		310 Doors	1 Total
103 Exterior Doors	4		511 a. Condition	4
104 ADA Automatic door operators	3		312 b. ADA Door Hardware	2
105 ADA complaint entrances	6		3 15 ADA Access to all spaces	6
106 Windows	6		3 14 Signage	
107 Roofing			3 15 Flooring	<u> </u>
108 Flashing	1		51b a.carpet 317 b.VCT	- 1
	1		318 c. Special type	4
109 Canopies	<u> </u>		519 Walk	4
110 Vestibules	Ļ——Ļ		3 20 Ge iling	3
		-	5 21 Stairs, ramps and hand railing	N/A
2. Exterior Site		4.8	3 22 ADA Lifts	N/A
201 Landscaping			3 23 Seismic needs	3
202 a. Irrigation System	5		3 24 Adequacy of custodial spaces	. 3
203 b. Turf	5		3	
204 c. Planting	2		Teaching Environment 401 Adequate heating, cooling and ventilation	5.2
205 Playgrounds			402 Proper lighting and lighting control	4
206 a. ADA compliant			403 Adequate power needs	3
			404 Classroom sound systems	7
207 b. Equipment	<u>×</u>		405 Classroom technology	
208 c. Playground safety	8		406 LDC projectors in classrooms	7
209 d. Playfields	5		407 Classroom safety	6
210 Asphalt condition	5		408 Windows/blinds	- 8
211 Fencing	5		409 Classroom doors with a window 410 White boards	
212 Student drop-off area	3		411 Classroom Furniture	
213 Traffic control	3		422 CR33700747 BHILLIAC	
214 Bus Lane	9		5. Building Restrooms	1.8
215 ADA Side walks	3		501 ADA Compliant	
216 ADA Access to building			502 Partitions	2
9.5.9	- 3		503 Lavatories and faucets	
217 ADA Parking	6		504 Water closets with flush valves	2
218 Adequate parking	5		505 Urmals with flush valves	2
219 Stairs, ramps and hand railing	5		506 F boring 507 Walls	3
220 Storm drainage system			508 Ceilings	
221 a. Site drainage			509 Exhaust fans	3
222 b. Storm water detention	a		5 10 Emergency Lighting	
223 Fire truck access	6		511 Floor Drains	vo.
224 Fire hydrant location and access				
EZTITE TYDIBIL IDEBUDIT BIID BEEESS				

Page 74

Vernon Elementary School



6. Life Safety	5.1	9. School Mech	nanical & Plumbing Systems		2.5
601 Fire alarm system 9			901 Boiler	N/A	
602 Proper egress 8			902 Chiller	N/A	
603 Intercom system 2			903 Coolingtowers	N/A	
604 Fire Extinguisher placement 9			904 Pumps	N/A	
605 AED's			905 Water heaters	N/A	
CONTRACTOR			906 Hydronic components	19/24	
606 Fire Sprinkling systems	1		907 Temperature controls systems 908 Air handling units/fans rooms	3	
607 Emergency egress Lighting 4			909 A/C units	N/A	
608 Fire department emergency radio & cell phone buster	1		910Air compressors	N/A	
			911 Exhaust fans	4	
7. Kitchens/Serving	0.3		912 Unit heaters & Cabinet heaters	N/A	
701 Cooking equipment 0	1		913 Exterior hose bibs	2	
702 Refrigerating /freezing equipment 1			914 Roof drainage system	2	
703 Kitchen hood & suppression system 0			915 Sewer drain lines	3	
704 Storage 1			916 Grease interceptor	N/A	
705 Serving Counter 0			917 Building water lines	2	
706 Fire Extinguishers K type where needed 0	1		918 ADA Compliant Drinking fountain fixtures	2	
707 Make-up air systems	1		919 Soft water system	0	
708 Exhaust Fans	1		920 Steam lines and traps	N/A	
, oo Exhauser and	1	10. Future Nee	ds		5.8
8. School Electrical Systems	2.8		1001 Capability for Expansion	-4	310
801 Lighting systems 5			1002 Capability for Portables	্ব	
802 Proper Exit Signs 5	1		1003 Energy efficiency rating	. 8	
803 Building Power system	1		1004 Adaptability for Technology	-4	
10 15 16 16 16 16 16 16 16 16 16 16 16 16 16	İ				
804 a. Main power service to building 8	1	Notes			
805 b. Emergency generator	1				
806 c. Adequate classroom power 4	1	Special needs			
807 Security system 0	4		Seismicity Needs from the Rapid Visual Screening of buildings di		-1.3118
808 Clocks 5			a. Bell tower is a falling hazard and need to be reinforced	nus på Euzigu	Eugineering
809 Access control system 0			b. Detailed evaluation recommended		
810 CCTV system 0			Upgrade restroom to meet ADA requirements		
811 Data systems 7			WeatherTrak Irrigation controller		
812 Wireless access 6			ADA Upgrade to playground equipment		
813 MDF/IDF Room 2			Upgrade old T-12 lighting to T-8		
814 Stage lighting/Sound systems 2			Replace old coal stoker furnace		
######################################	•,		Touch point all the masonry on the outside of the building		
			Add additional insulation in the attic		

Wendover High School



110 South Wildcat Blvd. Wendover, Utah 84083 435-665-7706






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
Shop area	1943	4,147	Facility Condition Score	48.6
Building ¹	1966	36,789	District Average	65.6
Locker room/clasroom addition	1989	14,121	Rating System 1 to 100	
New Gym	1971	9,216		
Total Building		64,282	Special Needs or Actions	
			 The front entrance needs a ADA upg 	grade
Current Student Enrollment	194		 The front entrance needs a vestibul 	e
Ideal Capacity	338		 Need to upgrade ADA parking in fro 	nt of the school
Stretch Capacity	450		 Several of the restroom need an AD 	A upgrade
Maximum Capacity	625		 Install fire sprinklers in the rest of the 	ne school
			 Install emergency power and lighting 	g

¹This school has had several more additions

Wendover High School





Page 77

Wendover High School



6. Life Safety	6.25	9. School Mechanical & Plumbing Systems	3.59
601 Fire alarm system	0.23	901 Boiler	3
The residue of the re	3	902 Chiller	N/A
602 Proper egress		903 Cooling tower	N/A
603 Intercom system	 '	904 Pumps	4
604 Fire Extinguisher placement	8	905 Water heaters	5
605 AED's	- 8	906 Hydronic components	
606 Fire Sprinkling system ⁶	. 5	907 Temperature controls systems 908 Air handling units/fan rooms	
607 Emergency egress Lighting	5	909 A/C units	
608 Fire department emergency radio & cell phone buster	0	910 Air compressors	s
	<u>.</u> :	911 Exhaust fans	5
7. Kitchens/Serving	3.50	912 Unit heaters & cabinet heaters	3
701 Cooking equipment	3	913 Dust Collectors	3
702 Refrigerating /freezing equipment	3	914 Roof drainage system	3
703 Hood suppression system		915 Sewer drain lines	4
		916 Grease interceptor	N/A
704 Storage	- 3	917 Building water lines 918 ADA Complaint Drinking fountain fixtures	
705 Serving Counter	3	919 Soft water system	2
706 Fire Extinguishers K type where needed	. 5	920 Steam lines and traps	3
707 Make-up air systems	3		
708 Exhaust fans	4	10. Future Needs	4. 25
	<u> </u>	1001 Capability for expansion	4
8. School Electrical Systems	4.62	1002 Capability for portables	3
801 Lighting systems	9	1003 Energy efficiency rating 1004 Adapta bility for Technology	
802 Proper Exit Signs	9	1004 Adapta bility for Technology	
803 Building Power system		Notes	
804 a. Main Power service to building	9	¹ The front doors need some attention for ADA	
805 b. Emergency generator 7	О	² The main entrance to the school needs vestibule	
806 c. Adequate classroom power	4	³ Need to install better ADA parking at the main entrance	
807 Security system	2	4 Need to upgrade the whole school for seismic	
808 Clocks	3	⁵ Several of the restrooms need ADA upgrades	
809 Access control system	0	Only part of the school is currently covered with fire sprinklers	
810 CCTV system	1	⁷ This school does not have a emergency generator	
811 Data systems	7	\$6000000000000000000000000	
		Special needs	
812 Wireless access	8		
812 Wireless access 813 MDF/IDF Room	<u>8</u>		ngineering
813 MDF/IDF Room	8 6 2	Seismicity Needs from the Rapid Visual Screening of buildings done by Ensign E a. Detailed evaluation recommended	ingineering
	8 6 2	Seismicity Needs from the Rapid Visual Screening of buildings done by Ensign E	ingineering

West Elementary School



451 West 300 South Tooele, Utah 84074 435-833-1931






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
Original Building	1959	39,599	Facility Condition Score	51.5
Media center addition	1968	6,200	District Average	65.6
Classroom addition	1989	18,171	Rating System 1 to 100	
Kitchen Addition	1990	1,200		
Total Building		65,170	Special Needs or Actions	
			Seismic needs	
Current Student Enrollment	386		Reduce the height of the tall chimney	
Ideal Capacity	535		Long walls of glass panels need reinforcement	
Stretch Capacity	560		 Upgrade all exterior windows in the school 	
Maximum Capacity	660		 ADA upgrade to the playground equipment 	
			 Install emergency power and lighting 	

West Elementary School






Page 80

West Elementary School





Willow Elementary School



439 South Willow Street Grantsville, Utah 84029 435-884-4527






Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	79.4
Total Building	2002	55,392	District Average	65.6
			Rating System 1 to 100	
			Special Needs or Actions	
Current Student Enrollment	657		 ADA upgrade to playground equipment 	
Ideal Capacity	675		 Install CCTV system 	
Stretch Capacity	700			
Maximum Capacity	850			

Willow Elementary School





Willow Elementary School



Section	6. Life Safety	7.6	9. School Mechanical & Plumbing Systems		8.0
603 Intercom system	601 Fire alarm system	8	901 Boiler	8	~
Soft Fire Extinguisher placement	602 Proper egress	9	902 Chiller	8	
S03 Fire Extinguisher placement 9 904 Pumps 8 8 905 Fixed Part 9 905 Water heaters 9 905 Water heaters 9 905 Water heaters 8 9 905 Fixed Part 9 905 Water heaters 9 905 Fixed Part 9 905 Fixed Part 9 905 Fixed Part 9 905 Fixed Part 9 907 Temperature controls systems 3 907 Temperature controls systems 3 907 Fixed Part 9 90	603 Intercom system	8	903 Cooling towers		
So	604 Fire Extinguisher placement	9	DEPOSITOR OF THE PROPERTY OF T	8	
606 Fire Sprinkling systems	605 AED's	9	200 00 00 00 00 00 00 00 00 00 00 00 00	9	
697 Emergency egress Lighting 9 907 Temperature controls systems 8 8 908 Air handling units/fans rooms 9 909 Air handl	606 Fire Sprinkling systems	9		- 3	
908 Air handling units/fans rooms 8 909A/C units 8 910 Air compressors 9 910 Air compressors 910 Air compressors 910 Air compressors 910 Air compressors 910 Air compres	607 Emergency egress Lighting	9		0	
8.0 909A/Cunits 8.0 909A/Cunits 8.0 909A/Cunits 8.0 909A/Cunits 8.0 909A/Cunits 8.0 909A/Cunits 8.0 910Air compressors 9.0 910Air compressors 9.0 910Air compressors 9.0 9	608 Fire department emergency radio & cell phone buster	О		8	
701 Cooking equipment				8	
702. Refrigerating /freeing equipment 8 911. Exhaust fans 9 8 912. Unit heaters & Cabinet heaters 9 8 913. Exterior hose bibs 9 8 913. Exterior hose bibs 9 913. Exterior hose	7. Kitchens/Serving	8.0		8	
703 Kitchen hood & suppression system	701 Cooking equipment	8		8	
704 Storage	702 Refrigerating /freezing equipment	- 8	911 Exhaust fans	8	
705 Serving Counter 8 914 Roof drainage system 9 8 706 Fire Extinguishers K type where needed 8 91.5 Sewer drain lines 9 8 91.5 Sewer drain lines 9 91.5 Sewer lines 9 91.5 Building water lines 9 91.5 Building water lines 9 91.5 Sewer lines and traps 9 91.5 Sewer lines and traps 9 91.5 Sewer lines and traps 9 91.5 Future Needs 9 92.5 Sewer lines and traps 9 10.5 Future Needs 9 10.5 Future	703 Kitchen hood & suppression system	8	912 Unit heaters & Cabinet heaters	8	
706 Fire Extinguishers K type where needed 8 915 Sewer drain lines 3 707 Make-up air systems 8 916 Grease interceptor 7 7 7 7 7 7 7 7 7	704 Storage	8	913 Exterior hose bibs	8	
707 Make-up air systems	705 Serving Counter	- 8	914 Roof drainage system	8	
Society Soci	706 Fire Extinguishers K type where needed	8	915 Sewer drain lines	8	
8. School Electrical Systems 918 ADA Compliant Drinking fountain fixtures 9 801 Lighting systems 8 802 Proper Exit Signs 9 803 Building Power system 920 Steam lines and traps 7.5 804 a. Main power service to building 9 10. Future Needs 7.5 805 b. Emergency generator 9 1001 Capability for Expansion 7 806 c. Adequate classroom power 8 1002 Capability for Portables 7 807 Security system 9 1003 Energy efficiency rating 8 808 Clocks 9 1004 Adaptability for Technology 8 809 Access control system 9 810 CCTV system 0 Notes 811 Data systems 9 812 Wireless access 8 813 MDF/IDF Room 8 814 Space lighting/Sound systems 7	707 Make-up air systems	8	916 Grease interceptor	7	
8. School Electrical Systems 801 Lighting systems 802 Proper Exit Signs 803 Building Power system 804 a. Main power service to building 805 b. Emergency generator 806 c. Adequate classroom power 807 Security system 909 1002 Capability for Expansion 7003 Energy efficiency rating 808 Clocks 909 1004 Adaptability for Technology 809 Access control system 900 Notes 810 Data systems 919 Notes 812 Wireless access 813 MDF/IDF Room 814 Stage lighting found systems 71 ADA Upgrade to playground equipment	708 Exhaust Fans	- 8	917 Building water lines	8	
8. School Electrical Systems 801 Lighting systems 802 Proper Exit Signs 803 Building Power system 804 a. Main power service to building 805 b. Emergency generator 806 c. Adequate classroom power 807 Security system 909 1002 Capability for Expansion 7003 Energy efficiency rating 808 Clocks 909 1004 Adaptability for Technology 809 Access control system 900 Notes 810 Data systems 919 Notes 812 Wireless access 813 MDF/IDF Room 814 Stage lighting found systems 71 ADA Upgrade to playground equipment		1		9	
801 lighting systems 802 Proper Exit Signs 903 Building Power system 804 a. Main power service to building 905 b. Emergency generator 806 c. Adequate classroom power 807 Security system 908 Access control system 909 Access control system 9100 CCTV system 9100 CCTV system 9100 CCTV system 9100 CCTV system 9100 Access control system 9100 Access		7.6		8	
802 Proper Exit Signs 803 Building Power system 804 a. Main power service to building 805 b. Emergency generator 806 c. Adequate classroom power 807 Security system 9 1001 Capability for Expansion 7 807 Security system 9 1003 Energy efficiency rating 808 Clocks 9 1004 Adaptability for Technology 809 Access control system 9 1004 Adaptability for Technology 810 CCTV system 9 Notes 811 Data systems 9 Notes 812 Wireless access 813 MDF/IDF Room 814 Stage lighting (Sound systems 814 Stage lighting (Sound systems 815 ADA Upgrade to playground equipment	801 Lighting systems	8	PROPERTY OF THE SECOND		
10. Future Needs 7.5 804 a. Main power service to building 805 b. Emergency generator 9 1001 Capability for Expansion 7 806 c. Adequate classroom power 807 Security system 9 1002 Capability for Portables 7 808 Clocks 9 1003 Energy efficiency rating 88 808 Clocks 9 1004 Adaptability for Technology 809 Access control system 9 1004 Adaptability for Technology 810 CCTV system 9 Notes 811 Data systems 812 Wireless access 813 MDF/IDF Room 814 Stage lighting (Sound systems 815 ADA Upgrade to playground equipment	802 Proper Exit Signs	9	520 Steam lines and traps		
805 b. Emergency generator 9 1001 Capability for Expansion 7 806 c. Adequate classroom power 8 1002 Capability for Portables 7 807 Security system 9 1003 Energy efficiency rating 8 808 Clocks 9 1004 Adaptability for Technology 8 809 Access control system 9 810 CCTV system 9 Notes 811 Data systems 9 812 Wireless access 8 Special needs 813 MDF/IDF Room 8 ADA Upgrade to playground equipment	19 (2) 20 (2) 10 (10 (10 (10 (10 (10 (10 (10 (10 (10		10. Future Noods	16	7.5
806 c. Adequate classroom power 8 1002 Capability for Portables 7 807 Security system 9 1003 Energy efficiency rating 8 808 Clocks 9 1004 Adaptability for Technology 8 809 Access control system 9 1004 Adaptability for Technology 8 810 CCTV system 9 Notes 811 Data systems 9 Special needs 812 Wireless access 813 MDF/IDF Room 814 Stage lighting (Sound systems 815 ADA Upgrade to playground equipment	a. Main power service to building	9			7.5
807 Security system 9 1003 Energy efficiency rating 808 Clocks 9 1004 Adaptability for Technology 809 Access control system 9 Notes 810 CCTV system 9 Notes 811 Data systems 9 Special needs 812 Wireless access 813 MDF/IDF Room 814 Stage lighting (Sound systems 814 Stage lighting (Sound systems 815 ADA Upgrade to playground equipment		9	1020 10	<u> </u>	
808 Clocks 9 1004 Adaptability for Technology 8 809 Access control system 9 810 CCTV system 0 Notes 811 Data systems 9 812 Wireless access 8 813 MDF/IDF Room 8 814 Stage lighting (Sound systems 7	The state of the s	8	1 € MODE AND A TOTAL POLICE MODE AND A TOTAL AND A TOTAL AND A SAND A TOTAL AND A TOTAL A	7	
809 Access control system 9 810 CCTV system 0 Notes 811 Data systems 9 812 Wireless access 813 MDF/IDF Room 814 Stage lighting (Sound systems 7	807 Security system	9		8	
810 CCTV system 0 Notes 811 Data systems 9 812 Wireless access 8 Special needs 813 MDF/IDF Room 8 ADA Upgrade to playground equipment	808 Clocks	9	1004 Adaptability for Technology	8	
811 Data systems 9 812 Wireless access 8 Special needs 813 MDF/IDF Room 8 ADA Upgrade to playground equipment	The part of the property of the part of th	9			
812 Wireless access 813 MDF/IDF Room 814 Stage lighting/Sound systems 7	810 CCTV system	0	Notes		
813 MDF/IDF Room 814 Stage lighting/Sound systems 7		9			
81/4 Stage lighting/Sound systems 7		8	Special needs		
814 Stage lighting/Sound systems		8	ADA Upgrade to playground equipment		
	814 Stage lighting/Sound systems	7	Install new CCTV system		

Page 84

Food Service/Maintenance

TOOLE COUNTY SCHOOL DISTRICT CHANNEY OR ALL

76 South 1000 West Tooele, Utah 84074 435-833-1992





Facility Assessment Summary

Building Information			Facility Conditions Summary	
	Year	Square Feet		
			Facility Condition Score	73.1
Original Building	2000	18,500	District Average	58.8
			Rating System 1 to 100	
Building Occupancy				
Conference Room	40		Special Needs or Actions	
Special Ed Office	16		 Needs more freezer space 	
Food Service Warehouse	8			
Maintenance shop	18			
	82			

Food Service/Maintenance



Support Building Assessment Condition	Total Score	73.1	3. Interior 301 General Aesthetics 302 Proper egress corridors/doors 303 Storage rooms	7.4 8 9
Rating System 1 to 10 , 1=Poor 10=Excellent			305 a. Condition	8
Factors 1. Exterior Building	Rating Sco	ore 6.6	307 b. ADA Door Hardware	8
101 General Aesthetics	7	2	308 ADA Access to all spaces	9
102 Exterior walls	7		309 Signage 310 Flooring	8
103 Exterior Doors	7		310 Hooring 311 a. carpet	7
104 ADA Automatic door operators	7		312 b. VCT	N/A
105 ADA complaint entrances	8		313 c. Special type	7
106 Windows	3		314 Walls	7
107 Roofing	7		315 Ceiling	7
108 Flashing	1		316 Stairs, ramps and hand railing	N/A
	1		317 ADA Lifts	N/A
109 Canopies	<u> </u>		318 Seismic needs	9
110 Vestibules	8		319 Adequacy of custodial spaces 320 Proper work spaces	8
111 Stairs/ramps			320110021100111304225	
			4. Working Environment	8.0
2. Exterior Site	ř –	7.2	401 Adequate heating, cooling and	
201 Landscaping	-		402 Proper lighting and lighting cor	trol 8
202 a. Irrigation System	7		403 Adequate power needs	8
203 b. Turf	7		404 Building safety 405 Windows/blinds	- 5
204 c. Planting	7		406 Proper equipment	8
205 Fencing	7			
206 ADA Side walks	8			
207 ADA Access to building	8		5. Building Restrooms	7.5
208 ADA Parking			501 ADA Compliant	9
209 Condition of asphalt on parking lots	7		502 Partitions	8
210 Adequate parking	8		503 Lavatories and faucets	7
211 Stairs, ramps and hand railing	N/A		504 Water closets with flush valves 505 Urinals with flush valves	7
212 Storm drainage system			506 Flooring	7
213 a. Site drainage	8		507 Walls	7
214 b. Storm water detention	8		508 Ceilings	7
215 Fire truck access	9		509 Exhaust fans	7
216 Fire hydrant location and access	9		510 Emergency Lighting	8
Edding hydralle location and access			511 Floor Drains	8
	<u> </u>			

Page 86

Food Service/Maintenance



6. Life Safety	8.8	9.Special Needs	8
601 Fire alarm system 602 Proper egress 603 Intercom system 604 Fire Extinguisher placement 605 AED's 606 Fire Sprinkling systems 607 Emergency egress Lighting	9 N/A 9 9	901 Emergency Radio 902 Shop Equipment	9 I/A 8 7
7. Building Electrical Systems 701 Lighting systems 702 Proper Exit Signs 703 Building Power system 704 a. Main power service to building 705 b. Emergency generator	7.0 8 9 9	906	\exists
706 c. Adequate A/C power outlets 707 Security system 708 Access control system 709 CCTV system 710 Data systems 711 Wireless access 712 MDF/IDF Room	8 8 N/A N/A 8 8	10. Future Needs 1001 Capability for Expansion 1002 Capability for Portables 1003 Energy efficiency rating 1004 Adaptability for Technology	6.3 5 5 8 7
8. Building Mechanical & Plumbing Systems 801 Boiler 802 Pumps 803 Water heaters 804 Hydronic components 805 Temperature controls systems 806 Air handling units/fans rooms 807 A/C units 808 Air compressors 809 Exhaust fans 810 Unit heaters & Cabinet heaters 811 Exterior hose bibs 812 Roof drainage system 813 Sewer drain lines 814 Building water lines	5.4 N/A N/A 7 N/A 7 7 7 7	Notes 1 Needs more freezer space	
815 ADA Compliant Drinking fountain fixtures 816 Soft water system			

District Office



92 South Lodestone Way Tooele, Utah 84074 435-833-1900





Facility Assessment Summary

Maximum building occupancy

Overstock side

Building Information			Facility Con
	Year	Square Feet	
Tooele County School District	1990	15,320	Facility Cond
Overstock	1990	13,780	District Aver
Total Building		29,100	Rating Syste
Building Occupancy			Special Nee
Board Room	106		 Lighting no
Front Office	48		 Carpet in t
Back Office area	64		

133

351

acility Conditions Summary

Facility Condition Score	70.1
District Average	58.8
Rating System 1 to 100	

Special Needs or Actions

Lighting needs to be upgraded from T-12 to T-8
Carpet in the back section needs to be replaced





Support Building Condition	Total Score	68.2	3. Interior		5.7
				301 General Aesthetics	. 7
Total Building Area SQ.FT	29,100			302 Proper egress corridors/doors	7
Total Building Capacity				303 Storage rooms 304 Windows/Glass	- 4
Total Building Capacity				305 Doors	
Year Constructed	1990			306 a Condition	ς.
				307 b. ADA Door Hardware	7
				308 ADA Access to all spaces	8
Rating System 1 to 10 , 1=Poor 10=Excellent				309 Signage	- 7
Factors	Rating So	ore		310 Flooring	
1. Exterior Building	715	5.9		311 a. carpet ^s	5
101 General Aesthetics	6			312 b. VCT	N/A
102 Exterior walls ¹	5			313 c. Special type	6
103 Exterior Doors	6			314 Walls	6
104 ADA Automatic door operators	8			315 Ceiling	6
105 ADA complaint entrances	8			316 Stairs, ramps and hand railing	N/A
106 Windows ²	5			317 ADA Lifts	N/A
107 Roofing	8			318 Seismic needs	8
108 Flashing	N/A			319 Adequacy of custodial spaces	5
109 Canopies ³	6			320 Proper work spaces	- 5
110 Vestibules	7				
111 Stairs/ramps	N/A		4 Working I	Environment	6.7
	6 71			401 Adequate heating, cooling and ventilation	5
	10			402 Proper lighting and lighting control	6
2. Exterior Site	<u> </u>	6.1		403 Adequate power needs	6
201 Landscaping ⁴	- 4			404 Building safety	
202 a. Irrigation System	5			405 Windows/blinds	8
203 b. Turf	. 5			406 Proper equipment	7
204 c. Planting					
205 Fencing					
206 ADA Side walks	<u> </u>		Building F		7.0
207 ADA Access to building	8			501 ADA Compliant	9
208 ADA Parking	8			502 Partitions	8
209 Condition of asphalt on parking lots	<u> </u>			503 Lavatories and faucets	<u> </u>
210 Adequate parking				504 Water closets with flush valves 505 Urinals with flush valves	4
211 Stairs, ramps and hand railing	N/A			505 Orinals With Tiush Valves 506 Flooring	- 4
212 Storm drainage system				507 Walls	- 4
213 a. Site drainage 214 b. Storm water detention	⊢			508 Ceilings	- 2
214 b. Storm water detention 215 Fire truck access	8			509 Exhaust fans	7
	~				
	8				4
216 Fire hydrant location and access	8			510 Emergency Lighting 511 Floor Drains	4 7





6. Life Safety 9. Special 601 Fire alarm system Needs 8.5 602 Proper egress 603 Intercom system 901 Emergency Radio 604 Fire Extinguisher placement 605 AED's 902 Equipment 606 Fire Sprinkling systems 607 Emergency egress Lighting 903 Lifts N/A 904 N/A 7. Building Electrical Systems 905 N/A 701 Lighting systems6 702 Proper Exit Signs 703 Building Power system 10. Future Needs 7.7 704 a. Main power service to building 705 b. Emergency generator 1001 Capability for Expansion 706 c. Adequate A/C power outlets 707 Security system 1002 Capability for Portables N/A 708 Access control system 709 CCTV system 1003 Energy efficiency rating 710 Data systems 711 Wireless access 1004 Adaptability for Technology 712 MDF/IDF Room Notes 6.5 8. Building Mechanical & Plumbing Systems 801 Boiler 1 Walls lack proper insulation 802 Pumps 2 Windows are not energy efficient 803 Water heaters 804 Hydronic components 3 Front Canopy needs to be painted 805 Temperature controls systems 806 Air handling units/fans rooms 4 TCSD is not reasonable for the landscaping around 807 A/Cunits the building 808 Air compressors 809 Exhaust fans 5 Capet in the back section of the office is in needs 810 Unit heaters & Cabinet heaters to be replaced 812 Roof drainage system 6 Lighting needs to be upgraded from T-813 Sewer drain lines 814 Building water lines 12 to T-8 815 ADA Compliant drinking fountain fixtures

TOOLLE COUNTY SCHOOL DISTRICT ORATION GUELLE OF

Transportation/Bus Garage

975 South Coleman Street Tooele, Utah 84074 435-833-1917





Facility Assessment Summary

Year	Square Feet	Facility Conditions Summary
1967	5,022	
1983	808	Facility Condition Score 41
1986	980	District Average 58.8
1974	768	Rating System 1 to 100
	750	
_	900	
	9,228	Special Needs or Actions
		Parking, the lot is full, in need of additional parking for
		the school busses
25		parking for the school buses and driver's personal cars
25		 ADA upgrade to the facility
38		 The shop is just too small, too short, not enough bays
9		 Two of the bus lifts are almost worn out
97		 Needs a seismic upgrade to the building
	1967 1983 1986 1974 - 25 25 38 9	1967 5,022 1983 808 1986 980 1974 768 750 900 9,228



Transportation/Bus Garage

Support Building Assessment Condition	Total Score 41.0		
Rating System 1 to 10, 1=Poor 10=Excellent			
Factors	Rating Score		-
1. Exterior Building 101 General Aesthetics 102 Exterior walls¹ 103 Exterior Doors 104 ADA Automatic door operators 105 ADA complaint entrances 106 Windows 107 Roofing 108 Flashing 109 Canopies 110 Vestibules 111 Stairs/ramps	3.4 4 4 0 0 4 4 5 5 N/A 4	3. Interior 301 General Aesthetics 302 Proper egress corridors/doors 303 Storage rooms 304 Windows/Glass 305 Doors 306 a. Condition 307 b. ADA Door Hardware 308 ADA Access to all spaces 309 Signage 310 Flooring 311 a. carpet 312 b. VCT 313 c. Special type 314 Walls	4 4 4 4 4 4 4 4 9 N/A 3 N/A
2. Exterior Site 201 Landscaping 202 a. Irrigation System 203 b. Turf 204 c. Planting 205 Fencing 206 ADA Side walks 207 ADA Access to building 208 ADA Parking 209 Condition of asphalt on parking lots 210 Adequate parking²	4.4 5 N/A 4 4 4 4 4 4 4 4 4 4 2	315 Ceiling 315 Stairs, ramps and hand railing 317 ADA Lifts 318 Seismic needs 319 Adequacy of custodial spaces 320 Proper work spaces ⁴ 4. Working Environment 40.1 Adequate heating, cooling and ventilation 40.2 Proper lighting and lighting control 40.3 Adequate power needs 40.4 Building safety 40.5 Windows/blinds 40.5 Proper equipment ⁸	4
211 Stairs, ramps and hand railing 212 Storm drainage system 213 a. Site drainage 214 b. Storm water detention 215 Fire truck access 216 Fire hydrant location and access ²	N/A 6 6 7 5	5. Building Restrooms 501ADA Compliant 502 Partitions 503 Lavatories and faucets 504 Water closets with flush valves 505 Urinals with flush valves 506 Flooring 507 Walls 508 Cellings 509 Exhaust fans 510 Emergency Lighting 511 Floor Drains	3.6 N/A 4 4 N/A 4 4 4 5

Page 92



Transportation/Bus Garage

6. Life Safety	4.4	9.Special Needs	5.7
601 Fire alarm system®	d	901 Emergency Radio	9
602 Proper egress	6	902 Equipment	
603 Intercom system	4		
604 Fire Extinguisher placement	9	903 Lifts ⁹	4
605 AED's	9	904	
606 Fire Sprinkling systems ⁷	O	905	
607 Emergency egress Lighting	3		——
		906	
7. Building Electrical Systems	4.8		
701 Lighting systems	6		
702 Proper Exit Signs	7	10. Future Needs	2.3
703 Building Power system			2.3
704 a. Main power service to building	8	1001 Capability for Expansion	0
705 b. Emergency generator	0	1002 Capability for Portables	o
706 c. Adequate A/C power outlets	1	1003 Energy efficiency rating	4
707 Security system ⁸	0		
708 Access control system	N/A	1004 Adaptability for Technology	5
709 CCTV system	1		
710 Data systems 711 Wireless access	- 1		1.
712 MDF/IDF Room	N/A	Marcala?	
/12 IVIDE/IDE ADDIT	19/2	Notes	
		1⊤he exterior walls do not have any insulation it them	
8. Building Mechanical & Plumbing Systems	4.8	2 Parking is a great need for both school buses and driver's	cars
901 Boiler	N/A	3 The only fire hydrants on this site are on Coleman	
802 Pumps	N/A	10명이 없었다. 보고 보고 있었다면 없는 보고 보고 보고 있습니다. 보고	
903 Water heaters	5	4 Too tight and not enough working bays	
804 Hydronic components	N/A N/A	5 The shop needs a lot of equipment upgraded	
805 Temperature controls systems 806 Air handling units/fans rooms	N/A N/A	6⊤he shop does not have a fire alarm system	
807 A/C units	N/A		
808 Air compressors	6	7⊤he shop does not have a fire sprinkling system	
809 Exhaust fans	N/A	8⊤he shop does not have a security system	
810 Unit heaters & Cabinet heaters	5	9Two of the bus lift are about worn out!!!!	
811 Exterior hose bibs	- 4		
812 Roof drainage system	6	SE VINDO N	
813 Sewer drain lines	6	Special Needs	
814 Building water lines	- 6	The shop needs a seismic upgrade	
815 ADA Compliant Drinking fountain fixtures	N/A N/A	The whole facility needs a ADA upgrade	
816 Soft water system	N/A	The whole facility freeds a ADA appliane	

Warehouse #2



92 South Milburn Drive Tooele, Utah 84074





Facility Assessment Summary

Building Information			Facility Conditions Summary		
		Year	Square Feet		
				Facility Condition Score	50.9
	Original Building	2001	12,000	District Average	58.8
				Rating System 1 to 100	
	Building Occupancy				
	Office area	12		Special Needs or Actions	
	Warehouse area	22		 Needs a loading dock 	
	Total	34		 Heat in the warehouse 	

Warehouse #2



Support Building Assessment Condition	Total Score	50.9	3. Interior		5.2
				301 General Aesthetics 302 Proper egress corridors/doors	<u>5</u>
Rating System 1 to 10, 1=Poor 10=Excellent				303 Storage rooms	
71 30 40				304 Windows/Glass	5
Factors	Rating So	core		305 Doors	
1. Exterior Building		5.1		306 a. Condition	5
101 General Aesthetics				307 b. ADA Door Hardware	8
102 Exterior walls	5			308ADA Access to all spaces	<u> </u>
103 Exterior Doors	8			309 Signage 310 Flooring	4
104ADA Automatic door operators	N/A			311 a carpet	6
105 ADA complaint entrances	8			312 b. VCT	N/A
106 Windows	5			313 c. Special type ²	7
107 Roofing	5			314 Walls	5
108 Flashing	5			315 Ceiling	5
109 Canopies	N/A			316 Stairs, ramps and hand railing 317 ADA Lifts	N/A
110Vestibules	N/A			318 Seismic needs	17/0
111 Stairs/ramps	N/A			319 Adequacy of custodial spaces	4
TIT Stall Sylamps	1475			320 Proper work spaces	7
2. Exterior Site	1	5.1	4. Working E	nvironment	4.8
201 Landscaping				401 Adequate heating, cooling and ventilation3	3
202 a. Irrigation System	5			402 Proper lighting and lighting control	5
203 b. Turf	N/A			403 Adequate power needs	5
	177			404 Building safety	6
204 c. Planting				405 Windows/blinds 406 Proper equipment	- 3
205 Fending	1 4			450110per equipment	
206 ADA Side walks	— 4				
207 ADA Access to building	7		5. Building Re	estrooms	7.0
208 ADA Parking ¹	a			501 ADA Compliant	7
209 Condition of asphalt on parking lots	5			502 Partitions	N/A
210 Adequate parking	5			503 Lavatories and faucets 504 Water closets with flush valves	7 7
211 Stairs, ramps and hand railing	N/A			505 Urinals with flush valves	N/A
212 Storm drainage system				506 Flooring	7
213 a. Site drainage	6			507 Walls	7
214 b. Storm water detention	6			508 Ceilings	7
215 Fire truck access	7			509 Exhaust fans	7
216Fire hydrant location and access	7			510 Emergency Lighting 511 Floor Drains	 2
2101 THE THY ALBIE TO COROLOTT BITCH BCCC233	 1				

Page 95

Warehouse #2



6. Life Safety		4.2	9.Special Needs	4.3
601 Fire alar	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	9	901 Emergency Radio	3
602 Proper a		N/A	301 Emergency Radio	<u> </u>
603 Intercor	m system inguisher placement	N/A	902 Equipment ⁵	5
605 AED's	migdistrer pracement	N/A	903 Lifts	5
	inkling systems	p		<u> </u>
	ncy egress Lighting4	5	904	
oo Emerge	The regions beginning		905	
		N	906	
7. Building Electrical System	ns	3.7	300	
701 Lighting	systems	5		
702 Proper I	Exit Signs*			
703 Building	g Power system		10 E N	
704 a. Ma	in power service to building	8	10. Future Needs	7.3
	ergency generator	0	1001 Capability for Expansion	9
	equate A/C power outlets	5	1002 Capability for Portables	0
707 Security		- 0	3.5 PE	- 3
709 CCTV sy	control system	N/A N/A	1003 Energy efficiency rating	5
710 Data sys		N/A	1004 Adaptability for Technology	6
711 Wireles:		6	,	
712 MDF/ID		N/A		
,,,-,,-	* WEEKS			
8. Building Mechanical & Plu	umbing Systems	4.1		
801 Boiler	ambing dystems	N/A	Notes	
802 Pumps		N/A	1 This site does not have any ADA	norling
903 Water h	neaters	6		
904 Hydroni	ic components	N/A	2 The restroom have ceramic title	on the floor
805 Temper	rature controls systems	N/A	The warehouse does not have a	ny heating or
806 Air hand	dling units/fans rooms	N/A	3 cooling	ily ricating of
907 A/C unit	ts	N/A	<u> </u>	
908 Air com	pressors	N/A	4 Egress lighting is not working, do	ead batteries
809 Exhaust		N/A	5 This building need an loading do	irk
	aters & Cabinet heaters	5	5 This building fieed all loading de	· Cit
811 Exterior		0		
	ainage system	4		
813 Sewer d		· · · · · · · · · · · · · · · · · · ·		
814 Building		N/2		
815 ADA Col 816 Soft wat	mpliant Drinking fountain fixtures	N/A N/A		
810 20μ Mat	rei system	N/A		

Portable #100



Located at Wendover High

Portable Assessment Building Condition Tot		Total Score	25.4	3. Teaching Environment		3.0
Total Building Are	≥a SQ.FT	900		Adequate heating, cooling and ventilation	5	
Total building Cap	pacity	30		Proper lighting and lighting control	- 3	
Portable Number	· · · · · · · · · · · · · · · · · · ·	100		Adequate power needs	4	
Sasian Sasana 1 a	to 10 , 1=Poor 10=Excellent			Classroom sound systems	0	
Harring System I r	.D 10, 1=PODY 10=EXCENEAL			Classroom technology	2	
Factors		Rating Scor	the second of	LDC projectors in classrooms	0	
Exterior Buildir	ng General Aesthetics	 	3.5	Classroom safety	6	
	Exterior walls	4		Windows/blinds	4	
	Exterior Doors	4		Classroom doors with a window		
	Windows	4			H 4	
	Roofing 1	4		White boards	4	
	Skirting	-4				
	Canopies	O.		4. Building Restrooms		0.0
	Stairs, ramps and hand railing	4		ADA Compliant	0	
				Partitions	0	
2. Interior			4.4	Lavatories and faucets	1	
	General Aesthetics	5			\vdash	
	Proper egress corridors/doors	7		Water closets with flush valves	0	
	Windows/Glass	4		Urinals with flush valves	0	
	Doors	,		Flooring	0	
	a. Condition b. ADA Door Hardware	5		Walls	0	
	ADA Access to all spaces	- 3		Ceilings		
	Signage	3			1	
	Flooring			Exhaust fans	0	
	a. carpet	4		Emergency Lighting	0	
	b. VCT	N/A		Floor Drains	0	
	c. Special type	N/A				
	Walls	4				
	Ceiling Stairs, ramps and hand railing	N/A				
	Seismic needs	N/A 4				

Portable #100



Located at Wendover High

5.	Life	Safety	

Fire alarm system

Proper egress


Intercom system

Fire Extinguisher placement

AED's

Fire Sprinkling systems

Emergency egress Lighting



8. Building Mechanical & Plumbing Systems

Wall mounted A/C heating units

Evaporative cooling

Base Board heating

Water heaters


A/C units

Exhaust fans

Roof drainage system/rain gutters

Sewer drain lines

Building water lines



Notes

4.4

1 Metal Roof

6. Building Electrical Systems

Lighting systems

Proper Exit Signs

Building Power system

a. Main power service to

building

c. Adequate classroom power

Clocks

Data systems

Wireless access

5 7 8 5
8
5
5 0

Portable # 101



Located at Tooele Jr. High School

Portable Asse	essment Building Condition	Total Score	41.1	3. Teaching Environment	Г	4.2
	N. C.			Adequate heating, cooling and		
Total Building Are	a SQ.FT	1,800		ventilation	6	
Total building Cap	ecity	60		Proper lighting and lighting control	6	
Portable Number		101		Adequate power needs	5	
Rating System 1 to	o 10 , 1=Poor 10=Excellent			Classroom sound systems	o	
Factors		Rating Score		Classroom technology	7	
1. Exterior Buildin	g	20 C	5.0	LDC projectors in classrooms	0	
	General Aesthetics	6			-	
	Exterior walls	6		Classroom safety	4	
	Exterior Doors	6		Windows/blinds	6	
	Windows	6		Classroom doors with a window	O	
	Roofing ¹	6		White boards	5	
	Skirting	6				
	Canopies Stairs, ramps and hand railing	0			т-	
	stairs, ramps and nand railing	4		4. Building Restrooms		5.5
		. 		ADA Compliant	7	
2. Interior		es la	5.6	Partitions	6	
	General Aesthetics	5		Lavatories and faucets	5	
	Proper egress corridors/doors	7		Water closets with flush valves	5	
	Windows/Glass	6		Urinals with flush valves	<u> </u>	
	Doors	 				
	a. Condition b. ADA Door Hardware	- 6		Flooring	5	
	ADA Access to all spaces	1 3		Walls	5	
	Signage	6		Ceilings	5	
	Flooring			Exhaust fans	5	
	a. carpet	6				
	b. VCT	N/A		Emergency Lighting	5	
	c. Special type	N/A		Floor Drains	7	
	Walls	5				
	Ceiling Stairs, ramps and hand railing	N/A			(2) 	
	Seismic needs	14/4				
	Section 1 (1) (1) (1) (1) (1) (1) (1) (1) (1) (

Portable # 101



Located at Tooele Jr. High School

5. Life Safety	8	7.8	8. Building Mechanical & Plumbing Systems	6.2
Fire alarm system	8		Wall mounted A/C heating units 7	
Proper egress	8		Evaporative cooling N/A	
Intercom system	8		Base Board heating N/A	
Fire Extinguisher placement	8		Water heaters 6	
AED's	N/A		A/C units N/A	
Fire Sprinkling systems	N/A		Exhaust fans 5 Roof drainage system/rain gutters 5	
Emergency egress Lighting	7		Sewer drain lines 7	
			Building water lines 7	
6. Building Electrical Systems Lighting systems		6.8	Notes 1 Metal Roof, with roof leaking on north side	
Proper Exit Signs	7			
Building Power system				
a. Main power service to building	8			
c. Adequate classroom power	1			
Clocks	4			
Data systems	7			
Wireless access	7			

Portable #102



Located at Tooele Jr. High School

Portable Assessment Building Condition		Total Score	40.9	3. Teaching Environment		4.2
				Adequate heating, cooling and		
Total Building	Area SQ.FT	1,800		301 ventilation	6	
Total building Capacity		60		302 Proper lighting and lighting control	6	
Portable Number		102		303 Adequate power needs	5	
Boting System	1 to 10 , 1=Poor 10=Excellent			304 Classroom sound systems	О	
Nating System	Tto 10, 1-root 10-extensit			305 Classroom technology	7	
Factors		Rating Score		306 LDC projectors in classrooms	О	
1. Exterior Buil		1	5.0	307 Classroom safety	7	
	101 General Aesthetics 102 Exterior walls	- 3		308 Windows/blinds		
	103 Exterior Doors	3		Page 6 (4 to 1 to	<u> </u>	
	104 Windows	6		309 Classroom doors with a window	0	
	105 Roofing ¹	6		310 White boards	5	
	106 Skirting	6				
	107 Canopies	o		4. Building Restrooms	etper.	5.5
	108 Stairs, ramps and hand railing ²	4		401 ADA Compliant	7	
		NA.		402 Partitions	6	
2. Interior			5.5	403 Lavatories and faucets	5	
Z. IIICEI IDI	201 General Aesthetics	5	3.3	404 Water closets with flush valves	5	
	202 Proper egress corridors/doors	7		405 Urinals with flush valves	N/A	
	203 Windows/Glass	16			14/4	
	204 Doors			406 Flooring	5	
	205 a. Condition			407 Walls	5	
	206 b. ADA Door Hardware	- 6		408 Ceilings	5	
	207 ADA Access to all spaces	<u> </u>		409 Exhaust fans	5	
	208 Signage			410 Emergency Lighting	5	
	209 Flooring 210 a. carpet			411 Floor Drains	<u> </u>	
	210 a. carpet 211 b. VCT	N/A		411 Floor Drains		
	212 c. Special type	N/A				
	213 Walls	5				
	214 Ceiling	5				
	215 Stairs, ramps and hand railing	N/A				
	216 Seismic needs	3				
		4				

Portable #102



Located at Tooele Jr. High School

5. Life Safety		7.8	7. Buildir	ng Mechanical & Plumbing Systems		6.2
501 Fire alarm system	8			701 Wall mounted A/C heating units	7	
502 Proper egress	8			702 Evaporative cooling	N/A	
503 Intercom system	8			703 Base Board heating	N/A	
504 Fire Extinguisher placement	8			704 Water heaters	6	
505 AED's	N/A			705 A/C units	N/A	
506 Fire Sprinkling systems	N/A			706 Exhaust fans	5	
507 Emergency egress Lighting	7			707 Roof drainage system/rain gutters	5	
				708 Sewer drain lines	7	
_				709 Building water lines	7	
6. Building Electrical Systems		6.8				
601 Lighting systems	6		Notes			
602 Proper Exit Signs	7			1 Metal roofing		
603 Building Power system				2 The ramp is not ADA complaint, it needs	some wor	k
a. Main power service to				it is over 30" high and needs, a guard rail	at 42" hig	gh,
604 building	8					
605 c. Adequate classroom power	7			a rail at 4" from the ramp surface and the	e hand rai	ls need
606 Clocks	4			to extend 12" past the bottom of the ram	np.	
607 Data systems	7					
608 Wireless access	7					

Portable #103



Located at Tooele Jr. High School


Portable	Assessment Building Condition	Total Score	39.9	3. Teaching Environment		4.5
	AND STATE OF THE S	20.000		Adequate heating, cooling and		
lotal Buildii	ng Area SQ.FT	1,800		301 ventilation	6	
Total buildi	ng Capacity	60		302 Proper lighting and lighting control	6	
Portable Nu	mber	103		303 Adequate power needs	5	
Rating Syste	em 1 to 10 , 1=Poor 10=Excellent			304 Classroom sound systems	0	
Factors		Rating Score		305 Classroom technology	7	
1. Exterior E	Building	Taking Sebie	5.0	306 LDC projectors in classrooms	n	
	101 General Aesthetics	6			<u> </u>	
	102 Exterior walls	6		307 Classroom safety		
	103 Exterior Doors	- 6		308 Windows/blinds	6	
	104Windows	- 6		309 Classroom doors with a window4	3	
	105 Roofing ¹	- 6		310 White boards	5	
	106 Skirting	6		3 To Willed Boards		
	107 Canopies	- 9		The Production of the Control of the	î	
	108 Stairs, ramps and hand railing ²	4		4. Building Restrooms	· ·	5.5
				401 ADA Compliant	7	
2. Interior			4.9	402 Partitions	6	
	201 General Aesthetics	5		403 Lavatories and faucets	5	
	202 Proper egress corridors/doors	5		404 Water closets with flush valves	5	
	203 Windows/Glass	- 6		405 Urinals with flush valves	N/A	
	204 Doors				IV/A	
	205 a. Condition	6		406 Flooring	- 5	
	206 b. ADA Door Hardware ^a	5		407 Walls	5	
	207 ADA Access to all spaces	- 6		408 Ceilings	5	
	208 Signage 209 Flooring	1		409 Exhaust fans	5	
	210 a carpet	4		410 Emergency Lighting	5	
	211 b. VCT	N/A			3	
	212 c. Special type	N/A		411 Floor Drains	4	
	213Walls	5			. ,	
	214 Ceiling	3				
	215 Stairs, ramps and hand railing	N/A				
	216 Seismic needs	3				

Portable #103



Located at Tooele Jr. High School

5. Life Safety		7.6
501 Fire alarm system	8	
502 Proper egress	8	
503 Intercom system	8	
504 Fire Extinguisher placement	8	
505AED's	N/A	
506 Fire Sprinkling systems	N/A	
507 Emergency egress Lighting	6	



7. Building Mechanical & Plumbing Systems	30	6.2
701 Wall mounted A/C heating units	7	
702 Evaporative cooling	N/A	
703 Base Board heating	N/A	
704 Water heaters	6	
705 A/C units	N/A	
706 Exhaust fans	- 5	
707 Roof drainage system/rain gutters	5	
708 Sewer drain lines	7	
709 Building water lines	7	

Notes

6.2

- 1 Metal roofing
- 2 The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.
- 3 Door hardware is not ADA compliant
- 4 Classroom doors just have a peep hole in them

Portable #104



Located at Tooele Jr. High School

Portable Assessment Building Condition	Total Score 40.	3. Teaching Environment 5.5
Total Building Area SQ.FT Total building Capacity Portable Number	1,900 60 104	301 Adequate heating, cooling and ventilation 7 302 Proper lighting and lighting control 7 303 Adequate power needs 6 304 Classroom sound systems 0
Rating System 1 to 10 , 1=Poor 10=Excellent	13,	305 Classroom technology 7
Factors	Rating Score	306 LDC projectors in classrooms ³ 5
1. Exterior Building 101 General Aesthetics 102 Exterior walls 103 Exterior Doors 104 Windows 105 Roofing ¹ 106 Skirting	5. 6 6 6 6	
107 Canopies 108 Stairs, ramps and hand railing ¹	4	4. Building Restrooms 5.5 401 ADA Compliant 7 402 Partitions 6
2. Interior 201 General Aesthetics 202 Proper egress corridors/doors 203 Windows/Glass 204 Doors 205 a. Condition 206 b. ADA Door Hardware 207 ADA Access to all spaces 208 Signage 209 Flooring 210 a. carpet 211 b. VCT 212 c. Special type 213 Walls 214 Ceiling 215 Stairs, ramps and hand railing 216 Seismic needs	5. 6 6 6 5 7 7 5 3 N/A N/A N/A S	403 Lavatories and faucets 404 Water closets with flush valves 405 Urinals with flush valves 406 Flooring 5 407 Walls 408 Ceilings 409 Exhaust fans 410 Emergency Lighting 5 411 Floor Drains

Portable #104



N/A

N/A

N/A

6.2

Located at Tooele Jr. High School

- 5. Life Safety
 - 501 Fire alarm system
 - 502 Proper egress
 - 503 Intercom system
 - 504 Fire Extinguisher placement
 - 505 AED's
 - 506 Fire Sprinkling systems
 - 507 Emergency egress Lighting


200	
	7.0
8	
8	
8	
8	
N/A	
N/A	
6	

5.6

Notes

- 7. Building Mechanical & Plumbing Systems
 - 701 Wall mounted A/C heating units
 - 702 Evaporative cooling
 - 703 Base Board heating
 - 704 Water heaters
 - 705 A/C units
 - 706 Exhaust fans
 - 707 Roof drainage system/rain gutters
 - 708 Sewer drain lines
 - 709 Building water lines

- 6. Building Electrical Systems
 - 601 Lighting systems
 - 602 Proper Exit Signs⁵
 - 603 Building Power system
 - 604 a. Main power service to building
 - 605 c. Adequate classroom power
 - 606 Clocks
 - 607 Data systems
 - 608 Wireless access



- 1 Metal roofing
 - 2The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.
 - 3 Only one LCD projector is mounted to the ceiling
 - 4Classroom doors just have a peep hole in them

Portable #105



Located at Tooele Jr. High School

Portable Assessment Building Condition	Total Score 25.1	3. Teaching Environment	3.8
Total Building Area SQ.FT	1,800	Adequate heating, cooling and 301 ventilation	5
Total building Capacity	60	302 Proper lighting and lighting control	5
Portable Number	105	303 Adequate power needs	5
Rating System 1 to 10 , 1=Poor 10=Excellent		304 Classroom sound systems	0
— 10 W	100 A DO CO AND	305 Classroom technology	3
Factors 1. Exterior Building	Rating Score	306 LDC projectors in classrooms	3
1.01 General Aesthetics	4	307 Classroom safety	7
102 Exterior walls	4	308 Windows/blinds	4
103 Exterior Doors	4		
104 Windows	4	309 Classroom doors with a window	2
105 Roofing ¹	3	310 White boards	4
106 Skirting	4		
107 Canopies	<u> </u>	4. Building Restrooms	0.0
108 Stairs, ramps and hand railing ²	4	401 ADA Compliant	0
		402 Partitions	0
2. Interior	4.5	403 Lavatories and faucets	o
201 General Aesthetics	4		
202 Proper egress corridors/doors	7	404 Water closets with flush valves	0
203 Windows/Glass	4	405 Urinals with flush valves	0
204 Doors		406 Flooring	О
205 a. Condition	4	407 Walls	o
206 b. ADA Door Hardware ^a	3	408 Ceilings	0
207 ADA Access to all spaces	7	409 Exhaust fans	
208 Signage	5		0
209 Flooring 210 a. carpet	5	410 Emergency Lighting	0
210 a. carpet 211 b. VCT	N/A	411 Floor Drains	0
212 c. Special type	N/A		
213 Walls	4		
214 Ceiling	3		
215 Stairs, ramps and hand railing	N/A		
216 Seismic needs	3		

Portable #105



Located at Tooele Jr. High School

- 5. Life Safety
 5.4

 501 Fire alarm system
 0

 502 Proper egress
 7

 503 Intercom system
 6

 504 Fire Extinguisher placement
 8

 505 AED's
 N/A

 506 Fire Sprinkling systems
 N/A

 507 Emergency egress Lighting
 6
- 6. Building Electrical Systems
 601 Lighting systems
 602 Proper Exit Signs
 603 Building Power system
 a. Main power service to
 604 building
 c. Adequate classroom
 605 power
 606 Clocks
 607 Data systems
 608 Wireless access

	3.5
5	
6	
8	
6	
6	
6 0 4	
4	
0	

7. Building Mechanical & Plumbing Systems		4.5
701 Wall mounted A/C heating units	5	
702 Evaporative cooling	N/A	
703 Base Board heating	N/A	
704 Water heaters	N/A	
705 A/C units	N/A	
706 Exhaust fans	N/A	
707 Roof drainage system/rain gutters	4	
708 Sewer drain lines	N/A	
709 Building water lines	N/A	

Notes

- 1 Asphalt shingled roof
- 2 The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need

to extend 12" past the bottom of the ramp.

3 Door hardware is not ADA complaint

Portable #106



Located at Tooele Jr. High School

Portable Ass	sessment Building Condition	Total Score	25.8		5-	
				3. Teaching Environment		4.1
Total Building Ar	ea SQ.FT	1,800		Adequate heating, cooling and	200	
Total building Ca	macity	60		ventilation	5	
300 m				Proper lighting and lighting control	5	
Portable Numbe	ir.	106		Adequate power needs	4	
Rating System 1	to 10, 1=Poor 10=Excellent			Classroom sound systems	О	
Factors		Rating Scor	·e	Classroom technology	5	
1. Exterior Buildi	18 T	Transition of the second	4.1	LDC projectors in classrooms	0	
	General Aesthetics	5		Classroom safety	6	
	Exterior walls Exterior Doors	5		Windows/blinds	3	
	Windows	5				
	Roofing	5		Classroom doors with a window	9	
	Skirting			White boards	4	
	Canopies	0			20	
	Stairs, ramps and hand railing ¹	3		4. Building Restrooms	·-	0.0
				ADA Compliant	0	
2. Interior		700	4.8	Partitions	0	
	General Aesthetics	4		Lavatories and faucets	0	
	Proper egress corridors/doors	6		Water closets with flush valves	0	
	Windows/Glass Doors	5		Urinals with flush valves	0	
	a. Condition	5				
	b. ADA Door Hardware	0		Flooring	0	
	ADA Access to all spaces	9		Walls	0	
	Signage			Ceilings	О	
	Flooring			Exhaust fans	О	
	a. carpet b. VCT	N/A		Emergency Lighting	O	
	c. Special type	N/A		Floor Drains	0	
	Walls	4		FIOOI DIAINS	<u> </u>	
	Ceiling	4				
	Stairs, ramps and hand railing	N/A				
	Seismic needs	3				

Portable #106



Located at Tooele Jr. High School

5. Life Safe	ty	6.5	8. Building	g Mechanical & Plumbing Systems		2.3
	Fire alarm system	9		Wall mounted A/C heating units	0	
	Proper egress	9		Evaporative cooling	4	
	Intercom system	7		Base Board heating	4	
	Fire Extinguisher placement	8		Water heaters	0	
	AED's	0		A/C units	N/A	
	Fire Sprinkling systems	N/A		Exhaust fans	N/A	
	Emergency egress Lighting	6		Roof drainage system/rain gutters	5	
				Sewer drain lines	N/A	
				Building water lines	N/A	
6. Building	Electrical Systems	4.0				
	Lighting systems	5	Notes			
	Proper Exit Signs	N/A		1 The ramp is not ADA complaint, it need	s some wor	k
	Building Power system			it is over 30" high and needs, a guard ra	ail at 42" hig	h,
	a. Main power service to	2.2		a rail at 4" from the ramp surface and t	the hand rail	ls need
	building	8		to extend 12" past the bottom of the ra	amp.	
	c. Adequate classroom power	6				
	Clocks	3				
	Data systems	5				
	Wireless access	0				

Portable #107



Located at Tooele High School

Portable Assessment Building Condition	Total Score	38.7	3. Teaching Environment	5	5.0
Total Building Area SQ.FT Total building Capacity	1,800		301 Adequate heating, cooling and ventilation 302 Proper lighting and lighting control	5 5	
			303 Adequate power needs	<u> </u>	
Portable Number	107		304 Classroom sound systems	0	
Rating System 1 to 10, 1=Poor 10=Excellent			305 Classroom technology	8	
Factors	Rating Score	<u>e</u>	306 LDC projectors in classrooms	8	
1. Exterior Building		4.1	307 Classroom safety	8	
101 General Aesthetics	6		308 Windows/blinds	5	
102 Exterior walls	5		309 Classroom doors with a window	0	
103 Exterior Doors	5		2000		
104 Windows	4		310 White boards	5	
105 Roofing ¹ 106 Skirting	5				
107 Canopies			4. Building Restrooms	6	5.0
108 Stairs, ramps and hand railing ²			401 ADA Compliant	6	
			402 Partitions		
			403 Lavatories and faucets		
2. Interior		5.3			
201 General Aesthetics	5		404 Water closets with flush valves	6	
202 Proper egress corridors/doors	5		405 Urinals with flush valves	N/A	
203 Windows/Glass 204 Doors	5		406 Flooring	6	
205 a. Condition	5		407 Walls	6	
206 b. ADA Door Hardware	8		408 Ceilings	- 6	
207 ADA Access to all spaces	8		409 Exhaust fans		
208 Signage	s				
209 Flooring			410 Emergency Lighting	6	
210 a. carpet ³	5		411 Floor Drains	6	
211 b. VCT	5				
212 c. Special type 213 Walls	N/A				
214 Ceiling					
215 Stairs, ramps and hand railing	N/A				
216 Seismic needs	3				

Page 111

Portable #107



N/A N/A

N/A

N/A

5.8

Located at Tooele High School

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement⁴

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

a. Main power service to


604 building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters


705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines



- 1 Metal Roof
- 2The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.
- 3 Carpet on one side is good the other side is bad
- 4 Fire extinguisher is missing

Portable #108



Located at Tooele High School

Portable Assessment Building Condition	Total Score 33.5	3. Teaching Environment 4.6
Total Building Area SQ.FT Total building Capacity Portable Number Rating System 1 to 10 , 1=Poor 10=Excellent Factors 1. Exterior Building 101 General Aesthetics	1,800 60 108 Rating Score	301 Adequate heating, cooling and ventilation 302 Proper lighting and lighting control 303 Adequate power needs 5 304 Classroom sound systems 0 305 Classroom technology 6 306 LDC projectors in classrooms
102 Exterior walls 103 Exterior Doors 104 Windows 105 Roofing ¹ 106 Skirting 107 Canoples 108 Stairs, ramps and hand railing ¹	5 5 5 5 5 5	308 Windows/blinds 5 309 Classroom doors with a window 7 310 White boards 5 4. Building Restrooms 0.0 401 ADA Compliant 0
2. Interior 201 General Aesthetics 202 Proper egress corridors/doors 203 Windows/Glass 204 Doors 205 a. Condition 206 b. ADA Door Hardware 207 ADA Access to all spaces 208 Signage 209 Flooring 210 a. carpet 211 b. VCT 212 c. Special type 213 Walls 214 Ceiling 215 Stairs, ramps and hand railing 216 Seismic needs	5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	402 Partitions 403 Lavatories and faucets 404 Water closets with flush valves 405 Urinals with flush valves 406 Flooring 407 Walls 408 Ceilings 409 Exhaust fans 410 Emergency Lighting 411 Floor Drains

Portable #108



6.0

Located at Tooele High School

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

6 N/A N/A N/A N/A N/A 6 N/A N/A

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system


604 a. Main power service to building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



5559669669 V

Notes

1 Metal roof

2The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high,

a rail at 4" from the ramp surface and the hand rails

need

to extend 12" past the bottom of the ramp.

Portable #109

Portable Assessment Building Condition



Located at Tooele High School

Total Score

31.7

		3. Teaching Environment	4.5
Total Building Area SQ.FT	1,800	301 Adequate heating, cooling and ventilation 6	
Total building Capacity	60	302 Proper lighting and lighting control 5	
Portable Number	109	303 Adequate power needs 7	
Rating System 1 to 10 , 1=Poor 10=Excellent		304 Classroom sound systems 0	
Nating System Tito 10 , 1-Pool 10-Extensit		305 Classroom technology 5	
Factors	Rating Score	306 LDC projectors in classrooms 0	
Exterior Building 101 General Aesthetics	4.3	307 Classroom safety 6	
102 Exterior walls	5	at the property of the control of th	
103 Exterior Doors	5	308 Windows/blinds 5	
104 Windows	5	309 Classroom doors with a window 6	
105 Roofing ¹	5	310 White boards 5	
106 Skirting 107 Canopies			
108 Stairs, ramps and hand railing ²	<u> </u>	4. Building Restrooms	0.0
		401 ADA Compliant 0	
	-	402 Partitions 0	
2. Interior	5.4	403 Lavatories and faucets	
201 General Aesthetics 202 Proper egress corridors/doors	5	2015 CAMPAN W AND CAS PR 10	
203 Windows/Glass	- 3	404 Water closets with flush valves 0	
204 Doors		405 Urinals with flush valves 0	
205 a. Condition	6	406 Flooring 0	
206 b. ADA Door Hardware ³	5	407 Walls	
207 ADA Access to all spaces	<u> </u>	408 Ceilings 0	
208 Signage	5	409 Exhaust fans	
209 Flooring 210 a. carpet			
211 b. VCT	N/A	410 Emergency Lighting 0	
212 c. Special type	N/A	411 Floor Drains 0	
213 Walls	5		
214 Ceiling	5	· 	
215 Stairs, ramps and hand railing	N/A		
216 Seismic needs			

Portable #109



N/A

N/A

N/A

N/A

N/A

N/A

N/A

5.0

Located at Tooele High School

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

a. Main power service to

604 building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access

5.8	
	8
	8
	О
	8
	N/A N/A
	N/A
	5

7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters


705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines



Notes

1 Metal roof

² The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need

to extend 12" past the bottom of the ramp.

³One door meets ADA and the other does not

Portable #110



Located at Tooele High

Portable Assessment Building Condition	Total Score 34.0		
		3. Teaching Environment	5.0
Total Building Area SQ.FT	1,800	301 Adequate heating, cooling and ventilation	6
Total building Capacity	60	302 Proper lighting and lighting control	6
		303 Adequate power needs	6
Portable Number	110	304 Classroom sound systems	n
Rating System 1 to 10 , 1=Poor 10=Excellent		305 Classroom technology	
Factors	Rating Score		<u> </u>
1. Exterior Building	4.3	306 LDC projectors in classrooms	
101 General Aesthetics	5	307 Classroom safety	_6
102 Exterior walls	5	308 Windows/blinds	6
103 Exterior Doors	5	309 Classroom doors with a window	8
104 Windows 105 Roofing ¹		310 White boards	6
106 Skirting		AND COURTS OF A PARTICULAR CONTROL AND CON	
107 Canopies	0	4. Building Restrooms	0.0
108 Stairs, ramps and hand railing ²	4	401 ADA Compliant	0
		402 Partitions	0
	1	403 Lavatories and faucets	<u> </u>
Interior 201 General Aesthetics	5.6		— ്⊣
201 General Aesthetics 202 Proper egress corridors/doors		404 Water closets with flush valves	0
203 Windows/Glass	s	405 Urinals with flush valves	O
204 Doors		406 Flooring	0
205 a. Condition	5	407 Walls	o
206 b. ADA Door Hardware	<u> </u>	408 Ceilings	0
207 ADA Access to all spaces 208 Signage	1	409 Exhaust fans	0
209 Flooring		410 Emergency Lighting	
210 a. carpet	7	411 Floor Drains	
211 b. VCT	N/A	411 Floor Drains	
212 c. Special type	N/A	<u></u>	
213 Walls 214 Ceiling			
214 CEIIING 215 Stairs, ramps and hand railing	N/A		
216 Seismic needs	4		

Portable #110



Located at Tooele High

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

8 8 0 8 N/A N/A 6

7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters


705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines



6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system


604 a. Main power service to building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



Notes

¹ Asphalt Shingles

² The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.

Portable #111



Located at Tooele High

Portable Assessment Building Condition	Total Score	32.9 3. Teaching Environment	5.3
Total Building Area SQ.FT	1,800	301 Adequate heating, cooling and ventilation 6	
Total building Capacity	60	302 Proper lighting and lighting control 6	,
Portable Number	111	303 Adequate power needs 6	
Rating System 1 to 10 , 1=Poor 10=Excellent		304 Classroom sound systems 5	
1000 COM A 2005	B.200	305 Classroom technology 6	
Factors 1. Exterior Building	Rating Score	4.3 306 LDC projectors in classrooms 0)
101 General Aesthetics	5	307 Classroom safety 7	,
102 Exterior walls	5	308 Windows/blinds 5	1
103 Exterior Doors	5		1
104 Windows		309 Classroom doors with a window 7	4
105 Roofing ¹ 106 Skirting		310 White boards 5	4
107 Canopies	0		
108 Stairs, ramps and hand railing ²	4	4. Building Restrooms	0.0
		401 ADA Compliant 0)
2. Interior		5.3 402 Partitions 0	,
201 General Aesthetics	5	403 Lavatories and faucets 0	1
202 Proper egress corridors/doors	6		<u> </u>
203 Windows/Glass	5	404 Water closets with flush valves 0	4
204 Doors 205 a. Condition		405 Urinals with flush valves 0	4
206 b. ADA Door Hardware		406 Flooring 0	,
207 ADA Access to all spaces	7	407 Walls	d
208 Signage	5	408 Ceilings 0	
209 Flooring	-	A PROGRAM AND	†
210 a. carpet	7	409 Exhaust fans 0	4
211 b. VCT 212 c. Special type	N/A N/A	410 Emergency Lighting 0	1
213 Walls	5	411 Floor Drains 0	,
214 Ceiling	5		1
215 Stairs, ramps and hand railing	N/A		1
216 Seismic needs	3		

Portable #111



Located at Tooele High

Life Safet	5.	Life	Sa	f	et
------------------------------	----	------	----	---	----

501 Fire alarm system

502 Proper egress


503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting



7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

	6.5
7	
N/A	
6	
N/A	
N/A N/A	

Notes

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

604 a. Main power service to building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



¹ Asphalt Shingles

² The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.

Portable #112



Located at Tooele High

Portable Assessment Building Condition	Total Score	40.8	3. Teaching Environment		5.4
Total Building Area SQ.FT	1,800		301 Adequate heating, cooling and ventilation	7	5.4
			302 Proper lighting and lighting control	7	
Total building Capacity	60		303 Adequate power needs	-	
Portable Number	112			- 0	
Rating System 1 to 10 , 1=Poor 10=Excellent			304 Classroom sound systems	<u> </u>	
	1001101 001		305 Classroom technology	7	
Factors 1. Exterior Building	Rating Sco	re 4.9	306 LDC projectors in classrooms ³	5	
101 General Aesthetics	6	4.5	307 Classroom safety	7	
102 Exterior walls	6		308 Windows/blinds	-	
103 Exterior Doors	6				
104 Windows	6		309 Classroom doors with a window ⁴	4	
105 Roofing ¹	s		310 White boards	5	
106 Skirting	6			(
107 Canopies	0		4. Building Restrooms	Ī	5.5
108 Stairs, ramps and hand railing ²	4		4. Building Restrooms 401 ADA Compliant		3.3
	<u> </u>		parties of properties and properties of the prop	4	
2. Interior	T-	5.7	402 Partitions	6	
201 General Aesthetics		5.7	403 Lavatories and faucets	.5	
202 Proper egress corridors/doors	8		404 Water closets with flush valves	5	
203 Windows/Glass	6		405 Urinals with flush valves	N/A	
204 Doors			406 Flooring	11/7	
205 a. Condition	6		Part Charles College County Charles County -		
206 b. ADA Door Hardware	8		407 Walls	- 5	
207 ADA Access to all spaces			408 Ceilings	5	
208 Signage	- 6		409 Exhaust fans	5	
209 Flooring			410 Emergency Lighting	- 5	
210 a. carpet	3				
211 b. VCT	N/A N/A		411 Floor Drains	4	
212 c. Special type 213Walls	N/A				
214 Ceiling	4				
215 Stairs, ramps and hand railing	N/A				
216 Seismic needs	3				

Portable #112



Located at Tooele High

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

6.3

7

N/A

N/A

6

N/A

6

7

7

7

6. Building Electrical Systems

601 Lighting systems4

602 Proper Exit Signs⁵

603 Building Power system

a. Main power service to


604 building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



Notes

1 Metal roofing

2 The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.

3 Only one LCD projector is mounted to the ceiling

4 The outside light over the door is not working

5 The battery is not working on the exit light

Portable #113



Located at Bus Garage

Portable Assessment Building Condition	Total Score	26.7	3. Teaching Environment	5.1
Total Building Area SQ.FT	750		301 Adequate heating, cooling and ventilation 4	
Total building Capacity	25		302 Proper lighting and lighting control 4	
Portable Number	113		303 Adequate power needs 4	
	113		304 Classroom sound systems 7	
Rating System 1 to 10 , 1=Poor 10=Excellent			305 Classroom technology 7	
Factors	Rating Scor	1.000		
Exterior Building 101 General Aesthetics		5.3	306 LDC projectors in classrooms 7	
102 Exterior walls	4		307 Classroom safety 7	
103 Exterior Doors	4		308 Windows/blinds 5	
104Windows 105Roofing ¹			309 Classroom doors with a window 3	
106 Skirting	6		310 White boards	
107 Canopies	8		310 Write boards	
108 Stairs, ramps and hand railing ²	-4		r	
			4. Building Restrooms	0.0
2. Interior	-	4.3	401 ADA Compliant 0	
201 General Aesthetics	5		402 Partitions 0	
202 Proper egress corridors/doors	6		403 Lavatories and faucets 0	
203 Windows/Glass 204 Doors	- 5		200 200 00	
205 a. Condition	5		404 Water closets with flush valves 0	
206 b. ADA Door Hardware ³	2		405 Urinals with flush valves 0	
207 ADA Access to all spaces	4		406 Flooring 0	
208 Signage	3		407 Walls	
209 Flooring 210 a. carpet			entage gardeners	
211 b. VCT	N/A		408 Ceilings 0	
212 c. Special type	N/A		409 Exhaust fans 0	
213 Walls	S		410 Emergency Lighting 0	
214 Ceiling	5		APPENDED CONTROL OF THE PROPERTY OF THE PROPER	
215 Stairs, ramps and hand railing	N/A		411 Floor Drains 0	
216 Seismic needs	⊢ †			

Portable #113



Located at Bus Garage

5. Life Safety		4.5	7. Build	ing Mechanical & Plumbing Systems		4.0
501 Fire alarm system	N/A			701 Wall mounted A/C heating units	N/A	
502 Proper egress	5			702 Evaporative cooling	4	
503 Intercom system	3			703 Base Board heating	4	
504 Fire Extinguisher placement	5			704 Water heaters	N/A	
505 AED's	N/A			705 A/C units	N/A	
506 Fire Sprinkling systems	N/A			706 Exhaust fans	N/A	
Emergency egress Lighting	5			707 Roof drainage system/rain gutters	4	
				708 Sewer drain lines	N/A	
	-1			709 Building water lines	N/A	
6. Building Electrical Systems		3.6				
601 Lighting systems	5					
602 Proper Exit Signs	4		Notes	4		
603 Building Power system				¹ This portable was re-shingled last yea		
604 a. Main power service to building	5			² This portable only has stairs not ADA compliant		
605 c. Adequate classroom power	5			³ The door hardware is not ADA compl	iant	
606 Clocks	5					
607 Data systems	4					
608 Wireless access	0					

Portable #114



Located at Bus Garage

Portable Assessment Building Condition

Portable	Assessment Building Condition	Total Score	34.6	3. Teaching Environment	6.3
Total Buildir	ng Area SQ.FT	900		301 Adequate heating, cooling and ventilation	6
Total buildir	ag Canacity	30		302 Proper lighting and lighting control	6
				303 Adequate power needs	6
Portable Nu		114		304 Classroom sound systems N	/A
Rating Syste	em 1 to 10 , 1=Poor 10=Excellent			305 Classroom technology	6
Factors		Rating Score	2	And described the Annual Conference of the Confe	
1. Exterior B	Building		5.5	306 LDC projectors in classrooms N	<u>/A</u>
	101 General Aesthetics	5		307 Classroom safety	6
	102 Exterior walls 103 Exterior Doors	5		308 Windows/blinds	6
	104 Windows	- 3		309 Classroom doors with a window	8
	105 Roofing	5			
	106 Skirting	5		310 White boards	6
	107 Canopies	7			
	108 Stairs, ramps and hand railing	7		4. Building Restrooms	0.0
				401 ADA Compliant	0
2. Interior			5.3	402 Partitions	n
	201 General Aesthetics	6		200	-
	202 Proper egress corridors/doors 203 Windows/Glass	- 7		403 Lavatories and faucets	비
	204 Doors	N/A		404 Water closets with flush valves	0
	205 a. Condition	5		405 Urinals with flush valves	0
	206 b. ADA Door Hardware ¹	3		406 Flooring	0
	207 ADA Access to all spaces	5		800 4 Mag 2 8 Mag 2	-
	208 Signage	5		407 Walls	0
	209 Flooring	- 3		408 Ceilings	0
	210 a. carpet 211 b. VCT	8 N/A		409 Exhaust fans	O
	211 B. VCT 212 c. Special type	N/A			
	213 Walls	5		410 Emergency Lighting	<u> </u>
	214 Ceiling	6		411 Floor Drains	0
	215 Stairs, ramps and hand railing	N/A			o
	216 Seismic needs	3			
		<u> </u>			

34.6

Portable #114



Located at Bus Garage

	5.	Life	Safety
--	----	------	--------

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

_	
	P
N/A	
8	
- 5	
7	
N/A	
N/A	
6	

7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

5.5	
	.5
	N/A
	6
	N/A
	N/A

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

a. Main power service to


604 building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



Notes

1 The hardware on this door is not ADA compliant

Portable #115



Located at West Elementary

Portable Assessment Building Condition	Total Score	28.4	3. Teaching Environment	3.3
Total Building Area SQ.FT Total building Capacity	750 25		Adequate heating, cooling and ventilation Proper lighting and lighting control Adequate power needs	5 5 4
Rating System 1 to 10 , 1=Poor 10=Excellent	115		Classroom sound systems Classroom technology	<u>0</u> 3
Factors 1. Exterior Building General Aesthetics Exterior walls Exterior Doors Windows Roofing Skirting Canopies	Rating Scc 4 4 4 4 5 5	4.4	LDC projectors in classrooms Classroom safety Windows/blinds Classroom doors with a window White boards 4. Building Restrooms	7A 5 4 0 4
2. Interior General Aesthetics Proper egress corridors/doors Windows/Glass Doors a. Condition b. ADA Door Hardware¹ ADA Access to all spaces Signage Flooring a. carpet b. VCT c. Special type Walls Ceiling Stairs, ramps and hand railing	5 7 5 7 5 4 4 3 7 4 4 7 N/A 3 5 N/A 3	4.8	ADA Compliant Partitions Lavatories and faucets Water closets with flush valves Urinals with flush valves Flooring Walls Ceilings Exhaust fans Emergency Lighting Floor Drains	0 0 0 0 0 0 0 0 0

Portable #115



Located at West Elementary

Safety		7.2
Fire alarm system	8	
Proper egress	8	
Intercom system	7	
Fire Extinguisher placement	8	
AED's	N/A	
Fire Sprinkling systems	N/A	
Emergency egress Lighting	5	
	Fire alarm system Proper egress Intercom system Fire Extinguisher placement AED's Fire Sprinkling systems	Fire alarm system 8 Proper egress 8 Intercom system 7 Fire Extinguisher placement 8 AED's N/A Fire Sprinkling systems N/A

3. Building Me	chanical & Plumbing Systems		4.5
,	Wall mounted A/C heating units	5	
Ī	Evaporative cooling	N/A	
Ī	Base Board heating	N/A	
,	Water heaters	N/A	
7	A/C units	N/A	
1	Exhaust fans	N/A	
1	Roof drainage system/rain gutters	4	
5	Sewer drain lines	N/A	
1	Building water lines		

		_	
6. Building	Electrical Systems		4.
	Lighting systems	5	
	Proper Exit Signs	5	
	Building Power system a. Main power service to building	8	
	c. Adequate classroom power	6	
	Clocks	4	
	Data systems	5	
	Wireless access	0	

1The door hardware is not ADA compliant

Notes

Portable #116



Located at Stansbury Park Elementary

Portable Assessment Building Condition	Total Score	29.4	3. Teaching Environment	4.5
Total Building Area SQ.FT Total building Capacity Portable Number Rating System 1 to 10, 1=Poor 10=Excellent Factors 1. Exterior Building 101 General Aesthetics 102 Exterior walls	1,800 60 116 Rating Score		301 Adequate heating, cooling and ventilation 5 302 Proper lighting and lighting control 5 303 Adequate power needs 4 304 Classroom sound systems 0 305 Classroom technology 5 306 LDC projectors in classrooms ³ 5 307 Classroom safety 5	i. <u>5</u>
103 Exterior Walls 103 Exterior Doors 104 Windows 105 Roofing* 106 Skirting 107 Canopies 108 Stairs, ramps and hand railing*	5 5 5 5 0		308 Windows/blinds 4 309 Classroom doors with a window 6 310 White boards 6 4. Building Restrooms	0.0
2. Interior 201 General Aesthetics 202 Proper egress corridors/doors 203 Windows/Glass 204 Doors 205 a. Condition 206 b. ADA Door Hardware 207 ADA Access to all spaces 208 Signage 209 Flooring 210 a. carpet 211 b. VCT 212 c. Special type 213 Walls 214 Celling 215 Stairs, ramps and hand railing 216 Seismic needs	4 6 5 7 7 7 5 4 N/A N/A 4 4	4.8	401 ADA Compliant 0 402 Partitions 0 403 Lavatories and faucets 0 404 Water closets with flush valves 0 405 Urinals with flush valves 0 406 Flooring 0 407 Walls 0 408 Ceilings 0 409 Exhaust fans 0 410 Emergency Lighting 0 411 Floor Drains 0	

Portable #116



5.0

N/A

N/A

N/A

N/A

N/A

N/A

Located at Stansbury Park Elementary

- 5. Life Safety
 - 501 Fire alarm system
 - 502 Proper egress
 - 503 Intercom system
 - 504 Fire Extinguisher placement
 - 505 AED's
 - 506 Fire Sprinkling systems
 - 507 Emergency egress Lighting
- 6.6

 8

 7

 7

 6

 N/A

 N/A

 5
- 7. Building Mechanical & Plumbing Systems
 - 701 Wall mounted A/C heating units
 - 702 Evaporative cooling
 - 703 Base Board heating
 - 704 Water heaters
 - 705 A/C units
 - 706 Exhaust fans
 - 707 Roof drainage system/rain gutters
 - 708 Sewer drain lines
 - 709 Building water lines

- 6. Building Electrical Systems
 - 601 Lighting systems
 - 602 Proper Exit Signs
 - 603 Building Power system
 - a. Main power service to
 - 604 building
 - 605 c. Adequate classroom power
 - 606 Clocks
 - 607 Data systems
 - 608 Wireless access

- 5 7 5 4 4 5 0
- Notes

4.2

- ¹ Asphalt Shingles
- ² Ramp is not ADA compliant, needs some work over 30" high needs guard rail, 42" hand rails and 4" rail at the bottom
- ³ LCD Projector not mounted to the ceiling

Portable #117



Located at Stansbury Park Elementary

Portable Assessment Building Condition	Total Score	28.4	3. Teaching Environment	4.7
Total Building Area SQ.FT	900		301 Adequate heating, cooling and ventilation 5	
Total building Capacity	30		302 Proper lighting and lighting control 4	
Portable Number	117		303 Adequate power needs 4	
Rating System 1 to 10 , 1=Poor 10=Excellent			304 Classroom sound systems 0	
Nating System 1 to 10, 1-room to-excellent			305 Classroom technology 5	
Factors	Rating Sco	5.0	306 LDC projectors in classrooms ³ 4	
Exterior Building 101 General Aesthetics	s	5.0	The state of the s	
102 Exterior walls	5		307 Classroom safety 6	
103 Exterior Doors	5		308 Windows/blinds 5	
104 Windows	5		309 Classroom doors with a window 9	
105 Roofing ¹	9		310 White boards 5	
106 Skirting	6		STO WITE DOLLARS	I.
107 Canopies	- 0			
108 Stairs, ramps and hand railing ²	<u> </u>		4. Building Restrooms	0.0
	L		401 ADA Compliant 0	
2. Interior		6.0	402 Partitions 0	
201 General Aesthetics	7		403 Lavatories and faucets 0	
202 Proper egress corridors/doors	7			
203 Windows/Glass 204 Doors	5		404 Water closets with flush valves 0	
204 Doors 205 a. Condition	6		405 Urinals with flush valves 0	
206 b. ADA Door Hardware	7		406 Flooring 0	
207 ADA Access to all spaces	7		122	
208 Signage	4		407 Walls 0	
209 Flooring			408 Ceilings 0	
210 a. carpet	9		409 Exhaust fans 0	
211 b. VCT	N/A N/A		410 Emergency Lighting 0	
212 c. Special type 213 Walls	IN/A		AND THE CONTROL OF TH	
214 Ceiling	4		411 Floor Drains 0	
215 Stairs, ramps and hand railing	5			
216 Seismic needs	3			•
	(5			

Page 131

Portable #117



N/A

N/A

N/A

N/A

N/A

N/A

N/A

6.0

Located at Stansbury Park Elementary

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

6 0 6 N/A N/A 5

0

7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

604 a. Main power service to building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



3.3

3.4

- 1 New Metal Roof
- 2 Ramp is not ADA compliant, needs some work over 30" high needs guard rail, 42" hand rails and 4" rail at the bottom
- 3 LCD Projector is not mounted

Portable #118



Located at Rose Springs Elementary

Portable A	Assessment Building Condition	TotalScore	28.4	3. Teaching Environment		4.7
Total Building	Area SQ.FT	900		301 Adequate heating, cooling and ventilation	5	
Total building	Capacity	30		302 Proper lighting and lighting control	4	
Portable Num	ber	118		303 Adequate power needs 304 Classroom sound systems	0	
Rating System	1 to 10 , 1=Poor 10=Excellent			305 Classroom technology	5	
Factors		Rating Scor	re	306 LDC projectors in classrooms ³	4	
1. Exterior Bui	ilding	-	5.0	2000 + 1000 0 0 1000 0 100 0		
	101 General Aesthetics	5		307 Classroom safety	- 6	
	102 Exterior walls	5		308 Windows/blinds	5	
	103 Exterior Doors	5		309 Classroom doors with a window	9	
	104 Windows	5		310 White boards	-5	
	105 Roofing ¹	- 3		310 Write Boards		
	106 Skirting 107 Canopies	- 3				
		9		4. Building Restrooms		0.0
	108 Stairs, ramps and hand railing ²	1		401 ADA Compliant	О	
		· · · · · · · · · · · · · · · · · · ·		402 Partitions	О	
2. Interior			6.0	403 Lavatories and faucets	0	
	201 General Aesthetics	4		404 Water closets with flush valves	0	
	202 Proper egress corridors/doors				<u> </u>	
	203 Windows/Glass 204 Doors			405 Urinals with flush valves	0	
	204 Doors 205 a. Condition			406 Flooring	0	
	206 b. ADA Door Hardware			407 Walls	0	
	207 ADA Access to all spaces	7		408 Ceilings	n	
	208 Signage	4		The second secon		
	209 Flooring			409 Exhaust fans	<u> </u>	
	210 a. carpet	9		410 Emergency Lighting	0	
	211 b. VCT	N/A		411 Floor Drains	0	
	212 c. Specialtype	N/A				
	213 Walls	8			0	
	214 Ceiling	4				
	215 Stairs, ramps and hand railing 216 Seismic needs					
	ZIO JEISINIC NEEDS					
		34				

Portable #118



Located at Rose Springs Elementary

		· ·	
5. Life S	afety		3.4
	501 Fire alarm system	0	
	502 Proper egress	6	
	503 Intercom system	0	
	504 Fire Extinguisher placement	6	
	505 AED's	N/A	
	506 Fire Sprinkling systems	N/A	
	507 Emergency egress Lighting	5	

7. Building Mechanical & Plumbing Systems		6.0
701 Wall mounted A/C heating units	4	
702 Evaporative cooling	N/A	
703 Base Board heating	N/A	
704 Water heaters	N/A	
705 A/C units	N/A	
706 Exhaust fans	N/A	
707 Roof drainage system/rain gutters	8	
708 Sewer drain lines	N/A	
709 Building water lines	N/A	

	6	29
6. Building Electrical Systems		3.3
601 Lighting systems	4	
602 Proper Exit Signs	6	
603 Building Power system	0	
604 a. Main power service to building	7	
605 c. Adequate classroom power	5	
606 Clocks	5	
607 Data systems	5	
608 Wireless access	О	

Notes

- 1 New Metal Roof
- 2 Ramp is not ADA compliant, needs some work over 30" high needs guard rail, 42" hand rails and 4" rail at the bottom
- 3 LCD Projector is not mounted

Special needs

Portable #119



Located at Rose Springs Elementary

Portable Assessment Building Condition	Total Score	26.4	3. Teaching Environment		4.4
Total Building Area SQ.FT	1, 320		301 Adequate heating, cooling and ventilation	5	
Total building Capacity	60		302 Proper lighting and lighting control	5	
Portable Number	119		303 Adequate power needs	4	
Rating System 1 to 10 , 1=Poor 10=Excellent			304 Classroom sound systems	О	
252 23	B		305 Classroom technology	4	
Factors 1. Exterior Building	Rating Scor	4.0	306 LDC projectors in classrooms ³	4	
101 General Aesthetics	5		Support State Course Annual Communication Communication Annual Communication Communica	-	
102 Exterior walls			307 Classroom safety	- 6	
103 Exterior Doors			308 Windows/blinds	5	
104 Windows	- 4		309 Classroom doors with a window	7	
105 Roofing ¹	- 4		310 White boards	4	
106 Skirting 107 Canopies	3		310 Willie boards		
108 Stairs, ramps and hand railing ²	4				
,			4. Building Restrooms		0.0
	5		401 ADA Compliant		
2. Interior	9	4.9	402 Partitions	0	
201 General Aesthetics	4		403 Lavatories and faucets	0	
202 Proper egress corridors/doors 203 Windows/Glass	- 5		SA TELEFORM TO THE CONTROL OF THE CO		
204 Doors	-4		404 Water closets with flush valves	0	
205 a. Condition	- 5		405 Urinals with flush valves	0	
206 b. ADA Door Hardware	9.7		406 Flooring	0	
207 ADA Access to all spaces	8		407 Walls		
208 Signage	S			<u> </u>	
209 Flooring			408 Ceilings	0	
210 a. carpet 211 b. VCT	N/A		409 Exhaust fans	0	
212 c. Special type	N/A		410 Emergency Lighting	О	
213 Walls	4		411 Floor Drains		
214 Ceiling	- 24		411 Floor Drains	<u> </u>	
215 Stairs, ramps and hand railing	N/A				
216 Seismic needs	े 3				

Portable #119



Located at Rose Springs Elementary

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

- 4.6
 0
 7
 7
 4
 N/A
 N/A
 5
- 7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

	4.5
	5
N/	A
N// N//	A
N/A	A
N/A	A
N/A	A

N/A

N/A

Notes

4.0

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

a. Main power service to

604 building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access

- 1 This portable has asphalt shingled roof
- 2 The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high,

a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.

3 Sitting on a cart not ceiling mounted

Page	-	20
Page		31
1 440	- 1	\sim

Portable #120



Located at Rose Springs Elementary

Portable Ass	sessment Building Condition	Total Score	20.5	3. Teaching Environment	2.9
Total Building Ar	rea SO.FT	1,290		301 Adequate heating, cooling and ventilation	3
				302 Proper lighting and lighting control	3
Total building Ca	apacity "	60		303 Adequate power needs	3
Portable Numbe	er	120		304 Classroom sound systems	0
Rating System 1	to 10 , 1=Poor 10=Excellent			305 Classroom technology	4
Factors		Rating Score	e	306 LDC projectors in classrooms ³	4
1. Exterior Buildi	ling	<u> </u>	2.8		
	101 General Aesthetics	3		307 Classroom safety	_6
	102 Exterior walls	3		308 Windows/blinds	3
	103 Exterior Doors	3		309 Classroom doors with a window	O
	104 Windows	3		310 White boards	2
	105 Roofing ¹	3		310 Writte Boards	
	106 Skirting	4			-
	107 Canopies	- 0		4. Building Restrooms	0.0
	108 Stairs, ramps and hand railing ²	3		401 ADA Compliant	0
		, <u>L</u>		402 Partitions	0
2. Interior		32	4.0	403 Lavatories and faucets	0
	201 General Aesthetics	3		404 Water closets with flush valves	0
	202 Proper egress corridors/doors	5		ACCOMPANIES OF ACCOUNTS OF THE STATE OF THE	
	203 Windows/Glass	4		405 Urinals with flush valves	0
	204 Doors			406 Flooring	0
	205 a. Condition	4		407 Walls	O
	206 b. ADA Door Hardware 207 ADA Access to all spaces	5		408 Ceilings	
	208 Signage	3			
	209 Flooring			409 Exhaust fans	<u> </u>
	210 a carpet	4		410 Emergency Lighting	0
	211 b. VCT	N/A		411 Floor Drains	o
	212 c. Special type	N/A		Seed of the State	O
	213 Walls	3		<u></u>	
	214 Ceiling	3			
	215 Stairs, ramps and hand railing	N/A			
	Seismic needs	3			

Portable #120

606 Clocks 607 Data systems 608 Wireless access



3.3

Located at Rose Springs Elementary

FILIF C-f-mil		0.5.00	**************************************	
5. Life Safety	4.4	8. Bullai	ing Mechanical & Plumbing Systems	
501 Fire alarm system	<u> </u>		801 Wall mounted A/C heating units	
502 Proper egress	7		802 Evaporative cooling	3
503 Intercom system	5		803 Base Board heating	3
S.*			804 Water heaters	N/A
504 Fire Extinguisher placement	5		805 A/C units	6
505 AED's	N/A		806 Exhaust fans	N/A
506 Fire Sprinkling systems	N/A		807 Roof drainage system/rain gutters	4
507 Emergency egress Lighting	5		808 Sewer drain lines	N/A
	80		809 Building water lines	N/A
6. Building Electrical Systems	3.2	Notes		
601 Lighting systems	3		1 This portable has asphalt shingles in bac	shape
602 Proper Exit Signs			2 The ramp is not ADA complaint, it needs	s some work
50 (1987 U.B. 1995 M. 1997 U.B. 199			it is over 30" high and needs, a guard ra	il at 42" high,
603 Building Power system	—		a rail at 4" from the ramp surface and th	ne hand rails need
a. Main power service to			to extend 12" past the bottom of the ra	
604 building	7		3 LCD projector setting on a cart not mou	ALIGNOT TO SOME
				inca to
605 c. Adequate classroom power	4		the ceiling	

Portable #121



Located at Rose Springs Elementary

Portable Assessment Building Condition	Total Score	24.9	3. Teaching Environment		3.4
Total Building Area SQ.FT	900		301 Adequate heating, cooling and ventilation	5	
Total building Capacity	30		302 Proper lighting and lighting control	5	
Portable Number	121		303 Adequate power needs	4	
	121		304 Classroom sound systems	0	
Rating System 1 to 10 , 1=Poor 10=Excellent			305 Classroom technology	4	
Factors 1. Exterior Building	Rating Sco	4.9	306 LDC projectors in classrooms ⁴	3	
101 General Aesthetics			307 Classroom safety	5	
102 Exterior walls 103 Exterior Doors	5		308 Windows/blinds	4	
104 Windows	4		309 Classroom doors with a window	0	
105 Roofing ¹	7		310 White boards	4	
106 Skirting 107 Canopies	- /		310 Willed Boulds		
108 Stairs, ramps and hand railing ²	4		4. Building Restrooms		0.0
	<u> </u>		401 ADA Compliant	0	
2. Interior		4.1	402 Partitions	0	
201 General Aesthetics	4			3.0	
202 Proper egress corridors/doors 203 Windows/Glass	6		403 Lavatories and faucets	0	
204 Doors	<u> </u>		404 Water closets with flush valves	0	
205 a. Condition	5		405 Urinals with flush valves	0	
206 b. ADA Door Hardware ³			406 Flooring	0	
207 ADA Access to all spaces 208 Signage	5		407 Walls	0	
209 Flooring	and the same of th		408 Ceilings	O	
210 a. carpet	3		80 C 20 C 7 C 1 C 1 C 1 C 1 C 1 C 1 C 1 C 1 C 1		
211 b. VCT	N/A		409 Exhaust fans	0	
212 c. Special type	3		410 Emergency Lighting	0	
213 Walls 214 Ceiling	3		411 Floor Drains	0	
215 Stairs, ramps and hand railing	N/A			0	
216 Seismic needs	3				

Portable #121



Located at Rose Springs Elementary

5. Life Safety		4.2	7. Buildi	ng Mechanical & Plumbing Systems	5.0
501 Fire alarm system	0			701 Wall mounted A/C heating units	5
502 Proper egress	6			702 Evaporative cooling	N/A
503 Intercom system	4			703 Base Board heating	N/A
504 Fire Extinguisher placement	5			704 Water heaters	N/A
505 AED's	N/A			705 A/C units	N/A
506 Fire Sprinkling systems	N/A			706 Exhaust fans	N/A
507 Emergency egress Lighting	6			707 Roof drainage system/rain gutters	5
5 , 5 5				708 Sewer drain lines	N/A
	3 S			709 Building water lines	N/A
6. Building Electrical Systems 601 Lighting systems 602 Proper Exit Signs 603 Building Power system a. Main power service to 604 building 605 c. Adequate classroom power 606 Clocks 607 Data systems 608 Wireless access	5 5 3 3 4 0	3.4	Notes	¹ Metal Roof ² The ramp is not ADA complaint, it needs it is over 30" high and needs, a guard ra a rail at 4" from the ramp surface and the to extend 12" past the bottom of the ra ³ The classroom door is not ADA complained ⁴ LCD Projector needs to be mounted to the complained	il at 42" high, ne hand rails need mp. nt

Portable #123



Located at Rose Springs Elementary

Portable Assessment Building Condition	Total Score	23.4	3. Teaching Environment		3.5
Total Building Area SQ.FT	900		301 Adequate heating, cooling and ventilation	5	70
Total building Capacity	30		302 Proper lighting and lighting control	5	
Portable Number	123		303 Adequate power needs	4	
	123		304 Classroom sound systems	0	
Rating System 1 to 10 , 1=Poor 10=Excellent			305 Classroom technology	4	
Factors	Rating Score		306 LDC projectors in classrooms ⁴	5	
Exterior Building 101 General Aesthetics		4.1	307 Classroom safety	6	
102 Exterior walls	5		308 Windows/blinds	3	
103 Exterior Doors ¹	4		309 Classroom doors with a window		
104 Windows	4		310 White boards	3	
105 Roofing ²	5		310 White boards	3	
106 Skirting 107 Canopies	 				
108 Stairs, ramps and hand railing ^a	4		4. Building Restrooms	-	0.0
			401 ADA Compliant	0	
			402 Partitions	0	
Interior 201 General Aesthetics		4.5	403 Lavatories and faucets	0	
202 Proper egress corridors/doors	5		404 Water closets with flush valves	0	
203 Windows/Glass	s		405 Urinals with flush valves	О	
204 Doors			406 Flooring		
205 a. Condition 206 b. ADA Door Hardware	4		407 Walls		
207 ADA Access to all spaces	a				
208 Signage	4		408 Ceilings	0	
209 Flooring			409 Exhaust fans	0	
210 a. carpet	8		410 Emergency Lighting	0	
211 b. VCT 212 c. Special type	N/A N/A		411 Floor Drains	0	
213 Walls	5				
214 Ceiling	3				
215 Stairs, ramps and hand railing	N/A				
216 Seismic needs	3				

Portable #123



Located at Rose Springs Elementary

ife Safety	3.8	7. Building Mechanical & Plumbing Systems	
501 Fire alarm system	0	701 Wall mounted A/C heating units	4
MACHINE WA		702 Evaporative cooling	N/A
502 Proper egress	- 9	703 Base Board heating	N/A
503 Intercom system	3	704 Water heaters	N/A
504 Fire Extinguisher placement	5	705 A/C units	N/A
505 AED's	N/A	706 Exhaust fans	N/A
506 Fire Sprinkling systems	N/A	707 Roof drainage system/rain gutters	4
507 Emergency egress Lighting	5	708 Sewer drain lines	N/A
337 2		709 Building water lines	N/A

6. Building	Electrical Systems	
6	01 Lighting systems	
6	02 Proper Exit Signs	
6	03 Building Power system	
6	04 a. Main power service to b	uilding
6	05 c. Adequate classroom po	wer
6	06 Clocks	
6	07 Data systems	
6	08 Wireless access	

9	
	3.4
5	
4	
5	
4	
3	
4	
0	

- 1 Doors are not ADA complaint
- ² Metal Roofing
- ³The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need to extend 12" past the bottom of the ramp.
- ⁴ LCD projector needs to be mounted

Portable #124

Portable Assessment Building Condition



Located at Stansbury High School

Total Score

29.5


	101111010111	3. Teaching Environment		4.6
Total Building Area SQ.FT	1800	301 Adequate heating, cooling and ventilation	5	
Total building Capacity	60	302 Proper lighting and lighting control	5	
Portable Number	124	303 Adequate power needs	5	
Rating System 1 to 10 , 1=Poor 10=Excellent		304 Classroom sound systems	0	
Factors	Rating Score	305 Classroom technology	4	
1. Exterior Building	4.8	306 LDC projectors in classrooms ³	4	
101 General Aesthetics	5	307 Classroom safety	6	
102 Exterior walls	5	308 Windows/blinds	7	
103 Exterior Doors	4		4	
104 Windows	4	309 Classroom doors with a window	5	
105 Roofing ¹	5	310 White boards		
106 Skirting 107 Canopies	5			
108 Stairs, ramps and hand railing	4	4. Building Restrooms	o	0.0
		401 ADA Compliant	0	
2. Interior	4.0	402 Partitions	0	
201 General Aesthetics	6	403 Lavatories and faucets		
202 Proper egress corridors/doors	6	404 Water closets with flush valves		
203 Windows/Glass	5	PER MICHENNASCHER AND AND AND SAME SAME TO THE SAME THE S		
204 Doors		405 Urinals with flush valves	0	
205 a. Condition	4	406 Flooring	0	
206 b. ADA Door Hardware ²	3	407 Walls	0	
207 ADA Access to all spaces	- 6	408 Ceilings	0	
208 Signage	3	on the control of th	H 3	
209 Flooring	1	409 Exhaust fans	0	
210 a. carpet 211 b. VCT	N/A	410 Emergency Lighting	0	
212 c. Special type	N/A	411 Floor Drains	0	
213 Walls	3			
214 Ceiling	3			
215 Stairs, ramps and hand railing	N/A			
216 Seismic needs	3			

Portable #124




Located at Stansbury High School

5. Life S	afety
	501 Fire alarm system
	502 Proper egress
	503 Intercom system
	504 Fire Extinguisher placement
	505 AED's
	506 Fire Sprinkling systems
	507 Emergency egress Lighting



7. Building Mechanical & Plumbing Systems
701 Wall mounted A/C heating units
702 Evaporative cooling
703 Base Board heating
704 Water heaters
705 A/C units
706 Exhaust fans
707 Roof drainage system/rain gutters
708 Sewer drain lines
709 Building water lines



Notes

3.8

6.	Building	Electrical	Systems
----	----------	------------	---------

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

a. Main power service to

604 building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



1 Metal Roof

2 Door hardware not ADA complaint

3 LCD Projector not mounted to the ceiling

Portable #125



Located at Stansbury High

Portable Assessment Building Condition	Total Score	30.6	3. Teaching Environment		4.2
Total Building Area SQ.FT	900		301 Adequate heating, cooling and ventilation	5	
Total building Capacity	30		302 Proper lighting and lighting control	5	
			303 Adequate power needs	5	
Portable Number	125		304 Classroom sound systems	0	
Rating System 1 to 10 , 1=Poor 10=Excellent			305 Classroom technology	5	
Factors	Rating Score		306 LDC projectors in classrooms		
1. Exterior Building	6 6	5.0			
101 General Aesthetics	5		307 Classroom safety	7	
102 Exterior walls 103 Exterior Doors	5		308 Windows/blinds	5	
104 Windows	5		309 Classroom doors with a window	О	
105 Roofing ¹	7		310 White boards	5	
106 Skirting	3			250	
107 Canopies			4. Building Restrooms	1	0.0
108 Stairs, ramps and hand railing ²	4		87.6 	192	0.0
	<u> </u>		401 ADA Compliant	0	
2. Interior		5.0	402 Partitions	0	
201 General Aesthetics	5		403 Lavatories and faucets	0	
202 Proper egress corridors/doors	6		404 Water closets with flush valves	О	
203 Windows/Glass	5		405 Urinals with flush valves	O	
204 Doors	-		406 Flooring	o	
205 a. Condition	4				
206 b. ADA Door Hardware ³ 207 ADA Access to all spaces	3		407 Walls	0	
208 Signage	5		408 Ceilings	0	
209 Flooring			409 Exhaust fans	О	
210 a. carpet			410 Emergency Lighting	О	
211 b. VCT	N/A		411 Floor Drains	0	
212 c. Special type 213 Walls	N/A		411 Hoor Brains	— ĭ	
214 Celling	3				
215 Stairs, ramps and hand railing	N/A				
216 Seismic needs	3				

Portable #125



Located at Stansbury High

J. LIIC DUICE	5.	Life	Saf	ety
---------------	----	------	-----	-----

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

5.4 2 6 7 7 7 N/A N/A 5

7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

	6.
5	
N/A	

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system


604 a. Main power service to building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



Notes

- ¹ Metal roof
- 2 The ramp is not ADA complaint, it needs some work it is over 30" high and needs, a guard rail at 42" high, a rail at 4" from the ramp surface and the hand rails need
- 3 LCD Projector not mounted to the ceiling

to extend 12" past the bottom of the ramp.

Portable #126



Located at Stansbury High

Portable Assessment Building Condition	Total Score	32.6	74 ** Provide ACC ** no potantici (ACC **)
			3. Teaching Environment 4.5
Total Building Area SQ.FT	2,050		301Adequate heating, cooling and ventilation 5
Total building Capacity	60		302 Proper lighting and lighting control 5
Portable Number	126		303 Adequate power needs 5
	120		304 Classroom sound systems 0
Rating System 1 to 10 , 1=Poor 10=Excellent			305 Classroom technology 4
Factors	Rating Score		306 LDC projectors in classrooms ⁴ 4
1. Exterior Building	-	6.1	
101 General Aesthetics 102 Exterior walls	- 1		307 Classroom safety 6
103 Exterior Doors	6		308Windows/blinds 5
104 Windows	5		309 Classroom doors with a window 7
105 Roofing ¹	8		310 White boards 4
106 Skirting	8		Sea free delivered indicate and other above.
107 Canopies	0		4. Building Restrooms 0.0
108 Stairs, ramps and hand railing ²			A STATE OF THE STA
			401 ADA Compliant 0
	ř—		402 Partitions 0
Interior 201 General Aesthetics		6.0	403 Lavatories and faucets 0
202 Proper egress corridors/doors	7		404 Water closets with flush valves 0
203 Windows/Glass	5		405 Urinals with flush valves 0
204 Doors			406 Flooring 0
205 a. Condition	4		407 Walls 0
206 b. ADA Door Hardware ³	3		408 Ceilings 0
207 ADA Access to all spaces	7		AND THE PARTY OF T
208 Signage	5		409 Exhaust fans 0
209 Flooring 210 a. carpet	- 3		410 Emergency Lighting0
211 b.VCT	N/A		411 Floor Drains 0
212 c. Special type	N/A		0
213 Walls	7		
214 Ceiling	6		
215 Stairs, ramps and hand railing	N/A		
216 Seismic needs	3		

Portable #126



6.0

Located at Stansbury High

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

- 3.8
 0
 8
 0
 N/A
 N/A
 3
- 7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

N/A N/A N/A N/A N/A 7 N/A N/A

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system

a. Main power service to


604 building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access



Notes

6.2

1 Metal Roof

2 Ramp not ADA complaint

3 50% ADA complaint

4 LCD Projectors not mounted

Portable # 127



Located at Grantsville High

Portable Assessment Building Condition	Total Score	23.5	3. Teaching Environment	3	.7
			301 Adequate heating, cooling and ventilation	5	
Total Building Area SQ.FT	900		302 Proper lighting and lighting control	.5	
Total building Capacity	30		303 Adequate power needs	4	
Portable Number	127		304 Classroom sound systems	0	
Rating System 1 to 10 , 1=Poor 10=Excellent			305 Classroom technology	4	
Factors	Rating Scor		427 92 56		
1. Exterior Building	Rating Scot	3.4	306 LDC projectors in classrooms	0	
101 General Aesthetics	4		307 Classroom safety	7	
102 Exterior walls	4		308 Windows/blinds	5	
103 Exterior Doors 104 Windows	4		309 Classroom doors with a window	3	
105 Roofing ¹	4				
106 Skirting	4		310 White boards	5	
107 Canopies	0				20
108 Stairs, ramps and hand railing ²	3		4. Building Restrooms	О	.0
	<u> </u>		401 ADA Compliant	0	_
2. Interior		4.1	402 Partitions	n	
201 General Aesthetics	4		403 Lavatories and faucets		
202 Proper egress corridors/doors	5				
203 Windows/Glass 204 Doors	4		404 Water closets with flush valves	0	
205 a. Condition	3		405 Urinals with flush valves	O	
206 b. ADA Door Hardware ³	3		406 Flooring	n	
207 ADA Access to all spaces			99 8		
208 Signage	4		407 Walls		
209 Flooring 210 a. carpet			408 Ceilings	0	
211 b. VCT	N/A		409 Exhaust fans	O	
212 c. Special type	N/A		410 Emergency Lighting	0	
213 Walls	4				
214 Ceiling	3		411 Floor Drains	0	
215 Stairs, ramps and hand railing 216 Seismic needs	N/A				
STO SEIZUIC LIERD?	3		•		

Portable # 127



Located at Grantsville High School

5. Life Safety

501 Fire alarm system

502 Proper egress

503 Intercom system

504 Fire Extinguisher placement

505 AED's

506 Fire Sprinkling systems

507 Emergency egress Lighting

- 0 7 5 5 N/A N/A 4
- 7. Building Mechanical & Plumbing Systems

701 Wall mounted A/C heating units

702 Evaporative cooling

703 Base Board heating

704 Water heaters

705 A/C units

706 Exhaust fans

707 Roof drainage system/rain gutters

708 Sewer drain lines

709 Building water lines

4.5	
	5
	N/A
	4
	N/A
	N/A

6. Building Electrical Systems

601 Lighting systems

602 Proper Exit Signs

603 Building Power system


604 a. Main power service to building

605 c. Adequate classroom power

606 Clocks

607 Data systems

608 Wireless access⁴



1 Metal Roof

Notes

3.6

- 2 Someone has added a set of stairs to this building with out handrails, this need to be repaired
- 3 Door hardware in not ADA complaint
- 4 This building only has wireless data

Portable #128



Located at Grantsville High

Portable Assessment Building Condition	Total Score	24.5			
Total Building Area SQ.FT	900			ž.	
Total building Capacity	30		3. Teaching Environment		4.4
Portable Number	128		301 Adequate heating, cooling and ventilation	5	
			302 Proper lighting and lighting control	5	
Rating System 1 to 10, 1=Poor 10=Excellent			303 Adequate power needs	5	
Factors	Rating Scor		304 Classroom sound systems	N/A	
1. Exterior Building	- 	3.5	305 Classroom technology	N/A	
101 General Aesthetics 102 Exterior walls	4		SPECIFICATION OF SPECIF	The second second	
103 Exterior Doors	4		306 LDC projectors in classrooms	N/A	
104 Windows	- 4		307 Classroom safety	5	
105 Roofing ¹	4		308 Windows/blinds	4	
106 Skirting	4		309 Classroom doors with a window	3	
107 Canopies	0		310 White boards	4	
108 Stairs, ramps and hand railing ²	4		310 Willes Boulds		
	. 		4. Building Restrooms	o	0.0
2. Interior	8	3.9	401 ADA Compliant	n	
201 General Aesthetics	4		402 Partitions		
202 Proper egress corridors/doors	4			<u> </u>	
203 Windows/Glass 204 Doors	4		403 Lavatories and faucets	0	
205 a. Condition	4		404 Water closets with flush valves	О	
206 b. ADA Door Hardware ³	4		405 Urinals with flush valves	0	
207 ADA Access to all spaces	:4		406 Flooring	0	
208 Signage	4		407 Walls	n	
209 Flooring					
210 a. carpet	- 4		408 Ceilings	0	
211 b. VCT	N/A N/A		409 Exhaust fans	О	
212 c. Special type 213 Walls	N/A		410 Emergency Lighting	0	
214 Ceiling	4		411 Floor Drains	0	
215 Stairs, ramps and hand railing	N/A				
216 Seismic needs	3				

Portable #128



Located at Grantsville High School

5. Life Safety	3.	4 7. Build	ing Mechanical & Plumbing Systems	Γ	4.5
501 Fire alarm system	0		701 Wall mounted A/C heating units	5	
502 Proper egress	5		702 Evaporative cooling	N/A	
503 Intercom system	0		703 Base Board heating	N/A	
504 Fire Extinguisher placement	7		704 Water heaters	N/A	
505 AED's	N/A		705 A/C units	N/A	
506 Fire Sprinkling systems	N/A		706 Exhaust fans	N/A	
507 Emergency egress Lighting	5		707 Roof drainage system/rain gutters	4	
			708 Sewer drain lines	N/A	
			709 Building water lines	N/A	
6. Building Electrical Systems	4.	8			
601 Lighting systems	5				
602 Proper Exit Signs	5	Notes	:•		
603 Building Power system			¹ Metal Roof		
a. Main power service to			² The ramp is missing the bottom part and	d makes	this
604 building	5		ramp not ADA complaint		
605 c. Adequate classroom power	5		³ Door hardware is not ADA complaint		
606 Clocks	4		⁴ This building only has wireless data		
607 Data systems	4				
608 Wireless access ⁴	5				

Portable #129



Located at Vernon Elementary

Portable As	ssessment Building Condition	Total Score	31.6	3. Teaching Environment		4.1
Total Building A	Area SO.FT	900		301 Adequate heating, cooling and ventilation	5	
CO. CONTROL SANGE - CO.				302 Proper lighting and lighting control	5	
Total building C	Capacity	30		303 Adequate power needs	5	
Portable Numb	per	129		304 Classroom sound systems		
Rating System :	1 to 10 , 1=Poor 10=Excellent			305 Classroom technology	H	
Factors		Rating Sco	are.	anness transfer on the second of the second	31/4	
1. Exterior Build	ding		4.4	306 LDC projectors in classrooms	N/A	
	101 General Aesthetics	5		307 Classroom safety	7	
	102 Exterior walls	5		308 Windows/blinds	5	
	103 Exterior Doors	5		309 Classroom doors with a window	О	
	104 Windows	- 5		310 White boards	5	
	105 Roofing ¹	- 5				
	106 Skirting 107 Canopies	3		4 Polision Polision	-	
	108 Stairs, ramps and hand railing	5		4. Building Restrooms	1 - L	0.0
	980 B) 179			401 ADA Compliant	0	
				402 Partitions	0	
2. Interior		r	5.2	403 Lavatories and faucets	0	
	201 General Aesthetics	5		404 Water closets with flush valves	0	
	202 Proper egress corridors/doors 203 Windows/Glass			405 Urinals with flush valves	0	
	204 Doors	1		406 Flooring		
	205 a. Condition	5		407 Walls	\vdash	
	206 b. ADA Door Hardware				-	
	207 ADA Access to all spaces	7		408 Ceilings	0	
	208 Signage	N/A		409 Exhaust fans	0	
	209 Flooring 210 a. carpet			410 Emergency Lighting	0	
	211 b. VCT	N/A		411 Floor Drains	0	
	212 c. Special type	N/A				
	213 Walls	5				
	214 Ceiling	5				
	215 Stairs, ramps and hand railing	N/A				
	216 Seismic needs	- 3				

Portable #129



Located at Vernon Elementary

5. Life Safety	28	6
501 Fire alarm system	9	
502 Proper egress	8	
503 Intercom system	0	
504 Fire Extinguisher placement	8	
505 AED's	N/A	
506 Fire Sprinkling systems	N/A	
507 Emergency egress Lighting	6	

7. Build	ing Mechanical & Plumbing Systems
	701 Wall mounted A/C heating units
	702 Evaporative cooling
	703 Base Board heating
	704 Water heaters
	705 A/C units
	706 Exhaust fans
	707 Roof drainage system/rain gutters
	708 Sewer drain lines
	709 Building water lines

	5.5
.5	
N/A N/A N/A	
N/A	
N/A	
N/A N/A	
N/A	
6	
N/A N/A	
N/A	

6. Building Electrical Systems
601 Lighting systems
602 Proper Exit Signs
603 Building Power system a. Main power service to 604 building
605 c. Adequate classroom power
606 Clocks
607 Data systems
608 Wireless access


	6.3
5	
6	
7	
7	
7	
7	

1 Metal roof

Notes

APPENDIX H:





APPENDIX I:



\$17,440,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Table of Contents

Report

Prior Original Debt Service	1
Debt Service To Maturity And To Call	2
Summary Of Bonds Refunded	3
Debt Service Schedule	4
Pricing Summary	5
Sources & Uses	6
Net Debt Service Schedule	7
Gross Debt Service Comparison	8
Francis Fund Golden	0

GO Ref 09 MBA all mats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM





Municipal Building Authority of Tooele County School District, Utah

\$21,545,000 Lease Revenue Bonds Series 2009

Prior Original Debt Service

DATE	PRINCIPAL	COUPON	INTEREST	TOTAL P+I	Fiscal Total
06/01/2015	890,000.00	4.000%	418,371.88	1,308,371.88	1,308,371.88
12/01/2015	90000 0000000 000000000000000000000000	550 4000 m 140 C 4 100	400,571.88	400,571.88	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
06/01/2016	930,000.00	4.000%	400,571.88	1,330,571.88	1,731,143.76
12/01/2016	748	8	381,971.88	381,971.88	-
06/01/2017	965,000.00	4.000%	381,971.88	1,346,971.88	1,728,943.76
12/01/2017	1828	4	362,671.88	362,671.88	
06/01/2018	1,005,000.00	4.000%	362,671.88	1,367,671.88	1,730,343.76
12/01/2018			342,571.88	342,571.88	-
06/01/2019	1,045,000.00	4.000%	342,571.88	1,387,571.88	1,730,143.76
12/01/2019	15-2	100	321,671.88	321,671.88	-
06/01/2020	1,085,000.00	4.250%	321,671.88	1,406,671.88	1,728,343.76
12/01/2020	57 No.	2	298,615.63	298,615.63	2 2
06/01/2021	1,130,000.00	4.500%	298,615.63	1,428,615.63	1,727,231.26
12/01/2021			273,190.63	273,190.63	
06/01/2022	1,185,000.00	4.500%	273,190.63	1,458,190.63	1,731,381.26
12/01/2022			246,528.13	246,528.13	-
06/01/2023	1,235,000.00	4.625%	246,528.13	1,481,528.13	1,728,056.26
12/01/2023	240	*	217,968.75	217,968.75	14
06/01/2024	1,295,000.00	4.875%	217,968.75	1,512,968.75	1,730,937.50
12/01/2024	AS 93 (ME)	4	186,403.13	186,403.13	
06/01/2025	1,355,000.00	4.875%	186,403.13	1,541,403.13	1,727,806.26
12/01/2025	14 Televisia (14	2000 CO.	153,375.00	153,375.00	
06/01/2026	1,425,000.00	5.000%	153,375.00	1,578,375.00	1,731,750.00
12/01/2026	18-13	10 00000 00000000000000000000000000000	117,750.00	117,750.00	-
06/01/2027	1,495,000.00	5.000%	117,750.00	1,612,750.00	1,730,500.00
12/01/2027	1020	Si Si	80,375.00	80,375.00	E .
06/01/2028	1,570,000.00	5.000%	80,375.00	1,650,375.00	1,730,750.00
12/01/2028			41,125.00	41,125.00	
06/01/2029	1,645,000.00	5.000%	41,125.00	1,686,125.00	1,727,250.00
Total	\$18.255.000.00	(2)	\$7.267.953.22	\$25,522,953.22	

Yield Statistics

Base date for Avg. Life & Avg. Coupon Calculation	2/01/2015_
Average Life	8.150 Years
Average Coupon	4.7912999%
Weighted Average Maturity (Par Basis)	8.150 Years

Refunding Bond Information

Refunding Dated Date	2/01/2015
Refunding Delivery Date	2/01/2015

Series 2009 MBA | SINGLE PURPOSE | 3/18/2014 | 11:04 AM

ZIONS BANK



Municipal Building Authority of Tooele County School District, Utah

\$21,545,000 Lease Revenue Bonds Series 2009

Debt Service To Maturity And To Call

Date	Refunded Bonds	Refunded Interest	D/S To Call	Principal	Coupon	Interest	Refunded D/S	Fiscal Total
06/01/2015	890,000.00	418,371.88	1,308,371.88	890,000.00	4.000%	418,371.88	1,308,371.88	1,308,371.88
12/01/2015	±9	400,571.88	400,571.88	=	9	400,571.88	400,571.88	
06/01/2016	930,000.00	400,571.88	1,330,571.88	930,000.00	4.000%	400,571.88	1,330,571.88	1,731,143.76
12/01/2016	₹0 43	381,971.88	381,971.88	Al 2	2	381,971.88	381,971.88	86 DO 1
06/01/2017	965,000.00	381,971.88	1,346,971.88	965,000.00	4.000%	381,971.88	1,346,971.88	1,728,943.76
12/01/2017	20	362,671.88	362,671.88			362,671.88	362,671.88	
06/01/2018	15,470,000.00	362,671.88	15,832,671.88	1,005,000.00	4.000%	362,671.88	1,367,671.88	1,730,343.76
12/01/2018	- 15		0.100.00 to 0.500.00 to 0.000.00	-	1-100 March 100	342,571.88	342,571.88	
06/01/2019	-28		1/48	1,045,000.00	4.000%	342,571.88	1,387,571.88	1,730,143.76
12/01/2019	-11	-	100	-		321,671.88	321,671.88	
06/01/2020	=3	9	(18)	1,085,000.00	4.250%	321,671.88	1,406,671.88	1,728,343.76
12/01/2020	-9	=	568	÷		298,615.63	298,615.63	5
06/01/2021	-9	~	2920	1,130,000.00	4.500%	298,615.63	1,428,615.63	1,727,231.26
12/01/2021	48	€	020	20 AG	12	273,190.63	273,190.63	80 90
06/01/2022	-93	© .	828	1,185,000.00	4.500%	273,190.63	1,458,190.63	1,731,381.26
12/01/2022	26		223	-		246,528.13	246,528.13	-
06/01/2023	=0		3.5¢	1,235,000.00	4.625%	246,528.13	1,481,528.13	1,728,056.26
12/01/2023	-16	ž.	200		12	217,968.75	217,968.75	
06/01/2024	-11		199	1,295,000.00	4.875%	217,968.75	1,512,968.75	1,730,937.50
12/01/2024	7.0	-	1170		in the	186,403.13	186,403.13	-
06/01/2025	-3	-	5 9 8	1,355,000.00	4.875%	186,403.13	1,541,403.13	1,727,806.26
12/01/2025	49	~	589			153,375.00	153,375.00	
06/01/2026	20	S.	1920	1,425,000.00	5.000%	153,375.00	1,578,375.00	1,731,750.00
12/01/2026	48	©	828	20 AS 20	16	117,750.00	117,750.00	80 90 2
06/01/2027	51	~	888	1,495,000.00	5.000%	117,750.00	1,612,750.00	1,730,500.00
12/01/2027	26		2023	=		80,375.00	80,375.00	AND DESCRIPTIONS
06/01/2028	5.0		9.50	1,570,000.00	5.000%	80,375.00	1,650,375.00	1,730,750.00
12/01/2028	71		200	-	15	41,125.00	41,125.00	-2
06/01/2029	70	-	87.7	1,645,000.00	5.000%	41,125.00	1,686,125.00	1,727,250.00
Total	\$18,255,000.00	\$2,708,803.16	\$20,963,803.16	\$18,255,000.00	2	\$7,267,953.22	\$25,522,953.22	_

Yield Statistics

Base date for Avg. Life & Avg. Coupon Calculation	2/01/2015
Average Life	8.150 Years
Average Coupon	4.7912999%
Weighted Average Maturity (Par Basis)	8.150 Years

Refunding Bond Information

Refunding Dated Date Refunding Delivery Date

Series 2009 MBA | SINGLE PURPOSE | 3/18/2014 | 11:04 AM



\$17,440,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Summary Of Bonds Refunded

					Maturity		
Issue	Maturity	Type	of Bond	Coupon	Value	Call Date	Call Price
Dated 6/02/2009 Deliver	ed 6/02/2009						32
Series 2009 MBA	06/01/2015	Serial	Coupon	4.000%	890,000	æ	= =
Series 2009 MBA	06/01/2016	Serial	Coupon	4.000%	930,000	20	20
Series 2009 MBA	06/01/2017	Serial	Coupon	4.000%	965,000	×	
Series 2009 MBA	06/01/2018	Term 1	Coupon	4.000%	1,005,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2019	Term 1	Coupon	4.000%	1,045,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2020	Serial	Coupon	4.250%	1,085,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2021	Term 2	Coupon	4.500%	1,130,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2022	Term 2	Coupon	4.500%	1,185,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2023	Serial	Coupon	4.625%	1,235,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2024	Term 3	Coupon	4.875%	1,295,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2025	Term 3	Coupon	4.875%	1,355,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2026	Serial	Coupon	5.000%	1,425,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2027	Serial	Coupon	5.000%	1,495,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2028	Serial	Coupon	5.000%	1,570,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2029	Serial	Coupon	5.000%	1,645,000	06/01/2018	100.000%
Subtotal	(2 <u>1</u>		100000	891	\$18,255,000	=	4
Total	10 0			% = 1	\$18,255,000	=	=

GO Ref 09 MBA all mats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM





\$17,440,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Debt Service Schedule

Fisc al Total	TOTAL P+I	INTEREST	COUPON	PRINCIPAL	DATE
	-	-,	·-		02/01/2015
1,134,416.67	1,134,416.67	204,416.67	2.000%	930,000.00	06/01/2015
50	297,325.00	297,325.00	07	To consider the consideration of the constant	12/01/2015
1,559,650.00	1,262,325.00	297,325.00	2.000%	965,000.00	06/01/2016
	287,675.00	287,675.00	9 -	500 man a constraint and	12/01/2016
1,555,350.00	1,267,675.00	287,675.00	2.000%	980,000.00	06/01/2017
	277,875.00	277,875.00	N=	2	12/01/2017
1,560,750.00	1,282,875.00	277,875.00	2.000%	1,005,000.00	06/01/2018
-	267,825.00	267,825.00	No.	-	12/01/2018
1,555,650.00	1,287,825.00	267,825.00	3.000%	1,020,000.00	06/01/2019
-	252,525.00	252,525.00	87	-	12/01/2019
1,555,050.00	1,302,525.00	252,525.00	3.000%	1,050,000.00	06/01/2020
	236,775.00	236,775.00	17	-	12/01/2020
1,553,550.00	1,316,775.00	236,775.00	3.000%	1,080,000.00	06/01/2021
	220,575.00	220,575.00	-	-	12/01/2021
1,561,150.00	1,340,575.00	220,575.00	4.000%	1,120,000.00	06/01/2022
	198,175.00	198,175.00	· ·		12/01/2022
1,556,350.00	1,358,175.00	198,175.00	4.000%	1,160,000.00	06/01/2023
	174,975.00	174,975.00	7 -		12/01/2023
1,559,950.00	1,384,975.00	174,975.00	5.000%	1,210,000.00	06/01/2024
	144,725.00	144,725.00			12/01/2024
1,554,450.00	1,409,725.00	144,725.00	5.000%	1,265,000.00	06/01/2025
	113,100.00	113,100.00		32 - 25 	12/01/2025
1,561,200.00	1,448,100.00	113,100.00	4.000%	1,335,000.00	06/01/2026
# # # T	86,400.00	86,400.00		A 2	12/01/2026
1,557,800.00	1,471,400.00	86,400.00	4.000%	1,385,000.00	06/01/2027
	58,700.00	58,700.00	3½	** *** ***	12/01/2027
1,557,400.00	1,498,700.00	58,700.00	4.000%	1,440,000.00	06/01/2028
	29,900.00	29,900.00	-		12/01/2028
1,554,800.00	1,524,900.00	29,900.00	4.000%	1,495,000.00	06/01/2029
	\$22,937,516.67	\$5,497,516.67	;=	\$17,440,000.00	Total

Yield Statistics

Bond Year Dollars	\$139,178.33
Average Life	7.980 Years
Average Coupon	3.9499802%
Net Interest Cost (NIC)	2.9223275%
Net Interest Cost (NIC) True Interest Cost (TIC)	2.9223275% 2.7465267%
Net Interest Cost (NIC) True Interest Cost (TIC) Bond Yield for Arbitrage Purposes	

 IRS Form 8038
 2.6106189%

 Net Interest Cost
 2.610 82 82

 Weighted Average Maturity
 8.063 Years

GO Ref 09 MBA all mats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM

ZIONS BANK



\$17,440,000 General Obligation Refunding Bonds Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Pricing Summary

Maturity	Type of Bond	Coupon	Yield	Maturity Value	Price		YTM	Call Date	Call Price	Dollar Price
06/01/2015	Serial Coupon	2.000%	0.400%	930,000.00	100.532%		2	(42)	E	934,947.60
06/01/2016	Serial Coupon	2.000%	0.430%	965,000.00	102.084%			(17)	5.	985,110.60
06/01/2017	Serial Coupon	2.000%	0.560%	980,000.00	103.333%		18	5@3	=	1,012,663.40
06/01/2018	Serial Coupon	2.000%	0.760%	1,005,000.00	104.073%		32	123	완	1,045,933.65
06/01/2019	Serial Coupon	3.000%	1.080%	1,020,000.00	108.106%			1354	=	1,102,681.20
06/01/2020	Serial Coupon	3.000%	1.360%	1,050,000.00	108.408%		2	(43)	2	1,138,284.00
06/01/2021	Serial Coupon	3.000%	1.770%	1,080,000.00	107.337%		i s	(27)	ē.	1,159,239.60
06/01/2022	Serial Coupon	4.000%	2.160%	1,120,000.00	112.414%		19	199	<u>=</u>	1,259,036.80
06/01/2023	Serial Coupon	4.000%	2.470%	1,160,000.00	111.457%		10	1626	8	1,292,901.20
06/01/2024	Serial Coupon	5.000%	2.680%	1,210,000.00	119.041%			10-1	-	1,440,396.10
06/01/2025	Serial Coupon	5.000%	2.820%	1,265,000.00	119.419%		¥	7920	2	1,510,650.35
06/01/2026	Serial Coupon	4.000%	2.970%	1,335,000.00	109.104%	c	3.044%	06/01/2025	100.000%	1,456,538.40
06/01/2027	Serial Coupon	4.000%	3.100%	1,385,000.00	107.902%	С	3.218%	06/01/2025	100.000%	1,494,442.70
06/01/2028	Serial Coupon	4.000%	3.230%	1,440,000.00	106.715%	С	3.370%	06/01/2025	100.000%	1,536,696.00
06/01/2029	Serial Coupon	4.000%	3.350%	1,495,000.00	105.634%	С	3.497%	06/01/2025	100.000%	1,579,228.30
Total	3 - 8		-	\$17.440.000.00	-		-	8-8		\$18,948,749,90

Bid Information

Par Amount of Bonds	\$17,440,000.00
Reoffering Premium or (Discount)	1,508,749.90
Gross Production	\$18,948,749.90
Total Underwriter's Discount (0.450%)	\$(78,480.00)
Bid (108.201%)	18,870,269.90
Total Purchase Price	\$18,870,269.90
Bond Year Dollars	\$139,178.33
Average Life	7.980 Years
Average Coupon	3.9499802%
Net Interest Cost (NIC)	2.9223275%
True Interest Cost (TIC)	2.7465267%

GO Ref 09 MBA all mats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM



\$17,440,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Sources & Uses

Dated 02/01/2015 | Delivered 02/01/2015

Sources	Of Funds

Par Amount of Bonds	\$17,440,000.00
Transfers from Prior Issue DSR Funds	1,731,750.00
Reoffering Premium	1,508,749.90

Total Sources \$20,680,499.90

Uses Of Funds

Deposit to Net Cash Escrow Fund	20,515,863.78
Costs of Issuance	85,000.00
Total Underwriter's Discount (0.450%)	78,480.00
Rounding Amount	1,156.12

Total Uses \$20,680,499.90

GO Ref 09 MBA all mats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM





\$17,440,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Net Debt Service Schedule

Fiscal Total	NET NEW D/S	TOTAL P+I	INTEREST	COUPON	PRINCIPAL	DATE
		2			2000	02/01/2015
1,134,416.67	1,134,416.67	1,134,416.67	204,416.67	2.000%	930,000.00	06/01/2015
20 C C C C C C C C C C C C C C C C C C C	297,325.00	297,325.00	297,325.00	2	** \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	12/01/2015
1,559,650.00	1,262,325.00	1,262,325.00	297,325.00	2.000%	965,000.00	06/01/2016
	287,675.00	287,675.00	287,675.00	-		12/01/2016
1,555,350.00	1,267,675.00	1,267,675.00	287,675.00	2.000%	980,000.00	06/01/2017
	277,875.00	277,875.00	277,875.00		-	12/01/2017
1,560,750.00	1,282,875.00	1,282,875.00	277,875.00	2.000%	1,005,000.00	06/01/2018
	267,825.00	267,825.00	267,825.00	.=		12/01/2018
1,555,650.00	1,287,825.00	1,287,825.00	267,825.00	3.000%	1,020,000.00	06/01/2019
15	252,525.00	252,525.00	252,525.00		=	12/01/2019
1,555,050.00	1,302,525.00	1,302,525.00	252,525.00	3.000%	1,050,000.00	06/01/2020
12	236,775.00	236,775.00	236,775.00	1000 (Contractor of Contractor	Novel years or one of the control of	12/01/2020
1,553,550.00	1,316,775.00	1,316,775.00	236,775.00	3.000%	1,080,000.00	06/01/2021
24 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	220,575.00	220,575.00	220,575.00	400000 EX 1000000 C	TO THE PARTY OF TH	12/01/2021
1,561,150.00	1,340,575.00	1,340,575.00	220,575.00	4.000%	1,120,000.00	06/01/2022
175	198,175.00	198,175.00	198,175.00			12/01/2022
1,556,350.00	1,358,175.00	1,358,175.00	198,175.00	4.000%	1,160,000.00	06/01/2023
(8)	174,975.00	174,975.00	174,975.00	*	=	12/01/2023
1,559,950.00	1,384,975.00	1,384,975.00	174,975.00	5.000%	1,210,000.00	06/01/2024
880	144,725.00	144,725.00	144,725.00	**	€	12/01/2024
1,554,450.00	1,409,725.00	1,409,725.00	144,725.00	5.000%	1,265,000.00	06/01/2025
190	113,100.00	113,100.00	113,100.00	*	¥	12/01/2025
1,561,200.00	1,448,100.00	1,448,100.00	113,100.00	4.000%	1,335,000.00	06/01/2026
190	86,400.00	86,400.00	86,400.00	29	¥	12/01/2026
1,557,800.00	1,471,400.00	1,471,400.00	86,400.00	4.000%	1,385,000.00	06/01/2027
190	58,700.00	58,700.00	58,700.00	(2	=	12/01/2027
1,557,400.00	1,498,700.00	1,498,700.00	58,700.00	4.000%	1,440,000.00	06/01/2028
79	29,900.00	29,900.00	29,900.00	~	a	12/01/2028
1,554,800.00	1,524,900.00	1,524,900.00	29,900.00	4.000%	1,495,000.00	06/01/2029
(=)	\$22,937,516.67	\$22,937,516.67	\$5,497,516.67	_	\$17,440,000.00	Total

GO Ref 09 MBA all mats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM

ZIONS BANK

Z B PUBLIC FINANCE

\$17,440,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Gross Debt Service Comparison

DATE	PRINCIPAL	COUPON	INTEREST	New D/S	OLD D/S	SAVINGS	Fiscal Total
02/01/2015	-	-6	1111111111111111	= 1	-		-
06/01/2015	930,000.00	2.000%	204,416.67	1,134,416.67	1,308,371.88	173,955.21	173,955.21
12/01/2015	-	71	297,325.00	297,325.00	400,571.88	103,246.88	7070
06/01/2016	965,000.00	2.000%	297,325.00	1,262,325.00	1,330,571.88	68,246.88	171,493.76
12/01/2016		50	287,675.00	287,675.00	381,971.88	94,296.88	
06/01/2017	980,000.00	2.000%	287,675.00	1,267,675.00	1,346,971.88	79,296.88	173,593.76
12/01/2017	2		277,875.00	277,875.00	362,671.88	84,796.88	
06/01/2018	1,005,000.00	2.000%	277,875.00	1,282,875.00	1,367,671.88	84,796.88	169,593.76
12/01/2018	t as trouverse on a seguin	594-000-004-001-005-0 	267,825.00	267,825.00	342,571.88	74,746.88	1.000 AND 1197 (1997) 1.00 1.000
06/01/2019	1,020,000.00	3.000%	267,825.00	1,287,825.00	1,387,571.88	99,746.88	174,493.76
12/01/2019			252,525.00	252,525.00	321,671.88	69,146.88	-
06/01/2020	1,050,000.00	3.000%	252,525.00	1,302,525.00	1,406,671.88	104,146.88	173,293.76
12/01/2020	W W		236,775.00	236,775.00	298,615.63	61,840.63	
06/01/2021	1,080,000.00	3.000%	236,775.00	1,316,775.00	1,428,615.63	111,840.63	173,681.26
12/01/2021	S0 40	-9	220,575.00	220,575.00	273,190.63	52,615.63	20
06/01/2022	1,120,000.00	4.000%	220,575.00	1,340,575.00	1,458,190.63	117,615.63	170,231.26
12/01/2022	-	-3	198,175.00	198,175.00	246,528.13	48,353.13	080
06/01/2023	1,160,000.00	4.000%	198,175.00	1,358,175.00	1,481,528.13	123,353.13	171,706.26
12/01/2023	-		174,975.00	174,975.00	217,968.75	42,993.75	
06/01/2024	1,210,000.00	5.000%	174,975.00	1,384,975.00	1,512,968.75	127,993.75	170,987.50
12/01/2024	-	-4	144,725.00	144,725.00	186,403.13	41,678.13	
06/01/2025	1,265,000.00	5.000%	144,725.00	1,409,725.00	1,541,403.13	131,678.13	173,356.26
12/01/2025		30	113,100.00	113,100.00	153,375.00	40,275.00	1900
06/01/2026	1,335,000.00	4.000%	113,100.00	1,448,100.00	1,578,375.00	130,275.00	170,550.00
12/01/2026		1000 to the total of the total	86,400.00	86,400.00	117,750.00	31,350.00	1987 PART AND
06/01/2027	1,385,000.00	4.000%	86,400.00	1,471,400.00	1,612,750.00	141,350.00	172,700.00
12/01/2027			58,700.00	58,700.00	80,375.00	21,675.00	2.24.00 Carrier (12.44)
06/01/2028	1,440,000.00	4.000%	58,700.00	1,498,700.00	1,650,375.00	151,675.00	173,350.00
12/01/2028	W. W.		29,900.00	29,900.00	41,125.00	11,225.00	A
06/01/2029	1,495,000.00	4.000%	29,900.00	1,524,900.00	1,686,125.00	161,225.00	172,450.00
Total	\$17,440,000,00		\$5,497,516,67	\$22,937,516.67	\$25.522.953.22	\$2.585,436.55	

PV Analysis Summary (Gross to Gross)

Gross PV Debt Service Savings	2,165,932.61
Transfers from Prior Issue DSR Fund	(1,731,750.00)
Contingency or Rounding Amount	1,156.12
Net Present V alue Benefit	\$435,338.73
Net PV Benefit / \$18,255,000 Refunded Principal	2.385%
Net PV Benefit / \$17,440,000 Refunding Principal	2.496%
Average Annual Cash Flow Savings	180,379.29

CHARLES OF SEC. PROTEIN

Refunding Dated Date	2/01/2015
Refunding Delivery Date	2/01/2015

GO Ref 09 MBA allmats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM





\$17,440,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 1)

Escrow Fund Cashflow

Date	Principal	Rate	Interest	Receipts	Disbursem ents	Cash Balance	Fiscal Total
02/01/2015	(8 7 1	ā.	150	0.78	p .	0.78	
06/01/2015	1,262,698.00	0.050%	45,673.23	1,308,371.23	1,308,371.88	0.13	1,308,371.88
12/01/2015	331,368.00	0.090%	69,203.86	400,571.86	400,571.88	0.11	
06/01/2016	1,261,616.00	0.160%	68,956.29	1,330,572.29	1,330,571.88	0.52	1,731,143.76
12/01/2016	314,025.00	0.270%	67,947.00	381,972.00	381,971.88	0.64	
06/01/2017	1,279,449.00	0.430%	67,523.07	1,346,972.07	1,346,971.88	0.83	1,728,943.76
12/01/2017	297,899.00	0.610%	64,772.26	362,671.26	362,671.88	0.21	=
06/01/2018	15,768,808.00	0.810%	63,863.67	15,832,671.67	15,832,671.88		16,195,343.76
Total	\$20,515,863.00	=	\$447,939.38	\$20,963,803.16	\$20,963,803.16	=	

Investment Parameters

nvestment Model [PV, GIC, or Securities]	Securities Securities Securities Securities
Default investment yield target	Bond Yield
Cash Deposit	0.78
Cost of Investments Purchased with Bond Proceeds	20,515,863.00
Total Cost of Investments	\$20,515,863.78
Farget Cost of Investments at bond yield	\$19,487,484.10
Actual positive or (negative) arbitrage	(1,028,379.68)
Yield to Receipt	0.7545139%
Yield for Arbitrage Purposes	2.5693226%

GO Ref 09 MBA all mats | SINGLE PURPOSE | 3/18/2014 | 11:04 AM





\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Table of Contents

Report

Prior Original Debt Service	1
Debt Service To Maturity And To Call	2
Summary Of Bonds Refunded	3
Debt Service Schedule	4
Pricing Summary	6
Sources & Uses	7
Net Debt Service Schedule	8
Gross Debt Service Comparison	9
Eccour Fund Cachflour	11

GO Ref 09 MB A all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM





Municipal Building Authority of Tooele County School District, Utah

\$21,545,000 Lease Revenue Bonds Series 2009

Prior Original Debt Service

DATE	PRINCIPAL	COUPON	INTEREST	TOTAL P+I	Fiscal Total
06/01/2015	890,000.00	4.000%	418,371.88	1,308,371.88	1,308,371.88
12/01/2015	1000 CONTRACTOR OF THE STATE OF	200 ACCOUNT ADDRESS ACCOUNT	400,571.88	400,571.88	VIEW POLICE 100 PC VIEW POLICE
06/01/2016	930,000.00	4.000%	400,571.88	1,330,571.88	1,731,143.76
12/01/2016	9 <u>0</u>	8	381,971.88	381,971.88	=
06/01/2017	965,000.00	4.000%	381,971.88	1,346,971.88	1,728,943.76
12/01/2017	7 (22)	4	362,671.88	362,671.88	
06/01/2018	1,005,000.00	4.000%	362,671.88	1,367,671.88	1,730,343.76
12/01/2018		5000 000 000 000 000 000 000 000 000 00	342,571.88	342,571.88	
06/01/2019	1,045,000.00	4.000%	342,571.88	1,387,571.88	1,730,143.76
12/01/2019	id=0	1-00000 - 0000000 - 0000000000000000000	321,671.88	321,671.88	15
06/01/2020	1,085,000.00	4.250%	321,671.88	1,406,671.88	1,728,343.76
12/01/2020	57 TS	¥	298,615.63	298,615.63	
06/01/2021	1,130,000.00	4.500%	298,615.63	1,428,615.63	1,727,231.26
12/01/2021			273,190.63	273,190.63	
06/01/2022	1,185,000.00	4.500%	273,190.63	1,458,190.63	1,731,381.26
12/01/2022			246,528.13	246,528.13	-
06/01/2023	1,235,000.00	4.625%	246,528.13	1,481,528.13	1,728,056.26
12/01/2023	(94))	*	217,968.75	217,968.75	
06/01/2024	1,295,000.00	4.875%	217,968.75	1,512,968.75	1,730,937.50
12/01/2024	A1 43 (141)	€	186,403.13	186,403.13	W W 4
06/01/2025	1,355,000.00	4.875%	186,403.13	1,541,403.13	1,727,806.26
12/01/2025	스로스 시간 전 스타 아이 아이 아이는 이 시간 시간 - 1시간 시간		153,375.00	153,375.00	
06/01/2026	1,425,000.00	5.000%	153,375.00	1,578,375.00	1,731,750.00
12/01/2026	10=0	9 SERVICE SERV	117,750.00	117,750.00	15
06/01/2027	1,495,000.00	5.000%	117,750.00	1,612,750.00	1,730,500.00
12/01/2027	1920		80,375.00	80,375.00	F
06/01/2028	1,570,000.00	5.000%	80,375.00	1,650,375.00	1,730,750.00
12/01/2028			41,125.00	41,125.00	
06/01/2029	1,645,000.00	5.000%	41,125.00	1,686,125.00	1,727,250.00
Total	\$18,255,000.00		\$7,267,953.22	\$25,522,953,22	

Yield Statistics

Base date for Avg. Life & Avg. Coupon Calculation	2/01/2015_
Average Life	8.150 Years
Average Coupon	4.7912999%
Weighted Average Maturity (Par Basis)	8.150 Years

Refunding Bond Information

Refunding Dated Date	2/01/2015_
Refunding Delivery Date	2/01/2015

Series 2009 MBA | SINGLE PURPOSE | 3/18/2014 | 11:06 AM

ZIONS BANK



Municipal Building Authority of Tooele County School District, Utah

\$21,545,000 Lease Revenue Bonds Series 2009

Debt Service To Maturity And To Call

Date	Refunded Bonds	Refunded Interest	D/S To Call	Principal	Coupon	Interest	Refunded D/S	Fiscal T ota
06/01/2015	890,000.00	418,371.88	1,308,371.88	890,000.00	4.000%	418,371.88	1,308,371.88	1,308,371.88
12/01/2015	-3	400,571.88	400,571.88	1	9	400,571.88	400,571.88	
06/01/2016	930,000.00	400,571.88	1,330,571.88	930,000.00	4.000%	400,571.88	1,330,571.88	1,731,143.76
12/01/2016	tio <u>∠</u> 3	381,971.88	381,971.88	A 2	32	381,971.88	381,971.88	84 D0 y
06/01/2017	965,000.00	381,971.88	1,346,971.88	965,000.00	4.000%	381,971.88	1,346,971.88	1,728,943.76
12/01/2017	20	362,671.88	362,671.88			362,671.88	362,671.88	
06/01/2018	15,470,000.00	362,671.88	15,832,671.88	1,005,000.00	4.000%	362,671.88	1,367,671.88	1,730,343.76
12/01/2018	20 CACACACACACACACACACACACACACACACACACACA	20.000	ACTOR AND ALL POST	-	150000000000000000000000000000000000000	342,571.88	342,571.88	2000-000 1512000 Vent
06/01/2019		-	Neg	1,045,000.00	4.000%	342,571.88	1,387,571.88	1,730,143.76
12/01/2019	-11	-	13-3	6	15	321,671.88	321,671.88	-
06/01/2020	- 3	-	S = 01	1,085,000.00	4.250%	321,671.88	1,406,671.88	1,728,343.76
12/01/2020	÷3	~	283			298,615.63	298,615.63	
06/01/2021	-9	~	9925	1,130,000.00	4.500%	298,615.63	1,428,615.63	1,727,231.26
12/01/2021	48	©	6828	20 40 2	15	273,190.63	273,190.63	86 98
06/01/2022	£1	· · · · · · · · · · · · · · · · · · ·	(4°)	1,185,000.00	4.500%	273,190.63	1,458,190.63	1,731,381.26
12/01/2022	26		2/2%	-		246,528.13	246,528.13	-
06/01/2023	7.0		s, ⊙ .c	1,235,000.00	4.625%	246,528.13	1,481,528.13	1,728,056.26
12/01/2023	75	- F	20.50	5.		217,968.75	217,968.75	5
06/01/2024	-11	-	13-3	1,295,000.00	4.875%	217,968.75	1,512,968.75	1,730,937.50
12/01/2024			53 5 2	-		186,403.13	186,403.13	-
06/01/2025	53		583	1,355,000.00	4.875%	186,403.13	1,541,403.13	1,727,806.26
12/01/2025	49	~	383			153,375.00	153,375.00	
06/01/2026	40	×	22.00	1,425,000.00	5.000%	153,375.00	1,578,375.00	1,731,750.00
12/01/2026	43	©	60 2 0	20 AS 20	8	117,750.00	117,750.00	80 90 2
06/01/2027	<u> 4</u> 8	설	923	1,495,000.00	5.000%	117,750.00	1,612,750.00	1,730,500.00
12/01/2027	26	2	242	<u> </u>		80,375.00	80,375.00	
06/01/2028	54	-	9.50	1,570,000.00	5.000%	80,375.00	1,650,375.00	1,730,750.00
12/01/2028	7.5	ē	828	-		41,125.00	41,125.00	
06/01/2029	7.1	-	6/5/6	1,645,000.00	5.000%	41,125.00	1,686,125.00	1,727,250.00
Total	\$18,255,000.00	\$2,708,803.16	\$20,963,803.16	\$18,255,000.00	2	\$7,267,953.22	\$25,522,953.22	2

Yield Statistics

Base date for Avg. Life & Avg. Coupon Calculation	2/01/2015
Average Life	8.150 Years
Average Coupon	4.7912999%
Weighted Average Maturity (Par Basis)	8.150 Years

Refunding Bond Information

Refunding Dated Date	2/01/2015
Refunding Delivery Date	2/01/2015

Series 2009 MBA | SINGLE PURPOSE | 3/18/2014 | 11:06 AM

ZIONS BANT



\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Summary Of Bonds Refunded

					Maturity		
Issue	Maturity	Type	of Bond	Coupon	Value	Call Date	Call Price
Dated 6/02/2009 Deliver	red 6/02/2009						
Series 2009 MBA	06/01/2015	Serial	Coupon	4.000%	890,000	æ	s
Series 2009 MBA	06/01/2016	Serial	Coupon	4.000%	930,000	<u> </u>	20
Series 2009 MBA	06/01/2017	Serial	Coupon	4.000%	965,000	9	
Series 2009 MBA	06/01/2018	Term 1	Coupon	4.000%	1,005,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2019	Term 1	Coupon	4.000%	1,045,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2020	Serial	Coupon	4.250%	1,085,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2021	Term 2	Coupon	4.500%	1,130,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2022	Term 2	Coupon	4.500%	1,185,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2023	Serial	Coupon	4.625%	1,235,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2024	Term 3	Coupon	4.875%	1,295,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2025	Term 3	Coupon	4.875%	1,355,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2026	Serial	Coupon	5.000%	1,425,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2027	Serial	Coupon	5.000%	1,495,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2028	Serial	Coupon	5.000%	1,570,000	06/01/2018	100.000%
Series 2009 MBA	06/01/2029	Serial	Coupon	5.000%	1,645,000	06/01/2018	100.000%
Subtotal	S2:		1000	921	\$18,255,000	=	2
Total	11 - 1			12 - 1	\$18,255,000	-	=

GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM





\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Debt Service Schedule

Part 1 of 2

DATE	PRINCIPAL	COUPON	INTEREST	TOTAL P+I	Fiscal Total
02/01/2015	2	(=	~	(2)	Ε
06/01/2015	665,000.00	2.000%	216,966.67	881,966.67	881,966.67
12/01/2015	<u> </u>	<u> 100</u>	318,800.00	318,800.00	21
06/01/2016	660,000.00	2.000%	318,800.00	978,800.00	1,297,600.00
12/01/2016	#	. .	312,200.00	312,200.00	
06/01/2017	670,000.00	2.000%	312,200.00	982,200.00	1,294,400.00
12/01/2017		x e	305,500.00	305,500.00	
06/01/2018	685,000.00	2.000%	305,500.00	990,500.00	1,296,000.00
12/01/2018		1 	298,650.00	298,650.00	100 may 2 m 2 m 2 m 2 m 2 m 2 m 2 m 2 m 2 m 2
06/01/2019	700,000.00	3.000%	298,650.00	998,650.00	1,297,300.00
12/01/2019	=	∫ e	288,150.00	288,150.00	=
06/01/2020	720,000.00	3.000%	288,150.00	1,008,150.00	1,296,300.00
12/01/2020	=	15	277,350.00	277,350.00	R
06/01/2021	740,000.00	3.000%	277,350.00	1,017,350.00	1,294,700.00
12/01/2021	¥	Œ	266,250.00	266,250.00	<u> </u>
06/01/2022	765,000.00	4.000%	266,250.00	1,031,250.00	1,297,500.00
12/01/2022	쓸	~	250,950.00	250,950.00	音
06/01/2023	795,000.00	4.000%	250,950.00	1,045,950.00	1,296,900.00
12/01/2023		. 	235,050.00	235,050.00	50 50
06/01/2024	825,000.00	5.000%	235,050.00	1,060,050.00	1,295,100.00
12/01/2024			214,425.00	214,425.00	
06/01/2025	865,000.00	5.000%	214,425.00	1,079,425.00	1,293,850.00
12/01/2025	5.65/2002-0.000-0.200-0.000-0.	£	192,800.00	192,800.00	**************************************
06/01/2026	910,000.00	4.000%	192,800.00	1,102,800.00	1,295,600.00
12/01/2026		X e	174,600.00	174,600.00	=
06/01/2027	945,000.00	4.000%	174,600.00	1,119,600.00	1,294,200.00
12/01/2027	9	39	155,700.00	155,700.00	=
06/01/2028	985,000.00	4.000%	155,700.00	1,140,700.00	1,296,400.00
12/01/2028	<u>*</u>	1 <u>2</u>	136,000.00	136,000.00	<u>=</u>

GO Ref 09 MB A all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM





\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Debt Service Schedule

Part 2 of 2

Fiscal Total	TOTAL P+I	INTEREST	COUPON	PRINCIPAL	DATE
1,297,000.00	1,161,000.00	136,000.00	4.000%	1,025,000.00	06/01/2029
-	115,500.00	115,500.00	£.	=	12/01/2029
1,296,000.00	1,180,500.00	115,500.00	4.000%	1,065,000.00	06/01/2030
=	94,200.00	94,200.00	Se Se	=2	12/01/2030
1,298,400.00	1,204,200.00	94,200.00	4.000%	1,110,000.00	06/01/2031
=	72,000.00	72,000.00	X 2	€	12/01/2031
1,294,000.00	1,222,000.00	72,000.00	4.000%	1,150,000.00	06/01/2032
~	49,000.00	49,000.00	12	~	12/01/2032
1,298,000.00	1,249,000.00	49,000.00	4.000%	1,200,000.00	06/01/2033
2	25,000.00	25,000.00	~	살	12/01/2033
1,300,000.00	1,275,000.00	25,000.00	4.000%	1,250,000.00	06/01/2034
-	\$25,511,216.67	\$7,781,216.67	-	\$17,730,000.00	Total

Yield Statistics

Bond Year Dollars	\$195,735.00
Average Life	11.040 Years
Average Coupon	3.9753834%
Net Interest Cost (NIC)	3.3933015%
True Interest Cost (TIC)	3.2368064%
Bond Yield for Arbitrage Purposes	3.0369892%
All Inclusive Cost (AIC)	3.2885660%

GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM



Net Interest Cost

Weighted Average Maturity



Page 5

3.1515400%

10.988 Years

\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Pricing Summary

Maturity	Type of Bond	Coupon	Yield	Maturity Value	Price		YTM	Call Date	Call Price	Dollar Price
06/01/2015	Serial Coupon	2.000%	0.400%	665,000.00	100.532%		-	-	950	668,537.80
06/01/2016	Serial Coupon	2.000%	0.430%	660,000.00	102.084%			-	0.70	673,754.40
06/01/2017	Serial Coupon	2.000%	0.560%	670,000.00	103.333%		8	9	686	692,331.10
06/01/2018	Serial Coupon	2.000%	0.760%	685,000.00	104.073%		8	8	120	712,900.05
06/01/2019	Serial Coupon	3.000%	1.080%	700,000.00	108.106%		5	82	528	756,742.00
06/01/2020	Serial Coupon	3.000%	1.360%	720,000.00	108.408%		-		950	780,537.60
06/01/2021	Serial Coupon	3.000%	1.770%	740,000.00	107.337%		-	5	\$ \$	794,293.80
06/01/2022	Serial Coupon	4.000%	2.160%	765,000.00	112.414%		8	9	88S	859,967.10
06/01/2023	Serial Coupon	4.000%	2.470%	795,000.00	111.457%		8	8	929	886,083.15
06/01/2024	Serial Coupon	5.000%	2.680%	825,000.00	119.041%		5	85	528	982,088.25
06/01/2025	Serial Coupon	5.000%	2.820%	865,000.00	119.419%		5.		3.53	1,032,974.35
06/01/2026	Serial Coupon	4.000%	2.970%	910,000.00	109.104%	С	3.044%	06/01/2025	100.000%	992,846.40
06/01/2027	Serial Coupon	4.000%	3.100%	945,000.00	107.902%	С	3.218%	06/01/2025	100.000%	1,019,673.90
06/01/2028	Serial Coupon	4.000%	3.230%	985,000.00	106.715%	С	3.370%	06/01/2025	100.000%	1,051,142.75
06/01/2029	Serial Coupon	4.000%	3.350%	1,025,000.00	105.634%	С	3.497%	06/01/2025	100.000%	1,082,748.50
06/01/2030	Serial Coupon	4.000%	3.440%	1,065,000.00	104.831%	С	3.587%	06/01/2025	100.000%	1,116,450.15
06/01/2031	Serial Coupon	4.000%	3.530%	1,110,000.00	104.036%	С	3.669%	06/01/2025	100.000%	1,154,799.60
06/01/2032	Serial Coupon	4.000%	3.620%	1,150,000.00	103.247%	С	3.743%	06/01/2025	100.000%	1,187,340.50
06/01/2033	Serial Coupon	4.000%	3.700%	1,200,000.00	102.552%	С	3.805%	06/01/2025	100.000%	1,230,624.00
06/01/2034	Serial Coupon	4.000%	3.780%	1,250,000.00	101.863%	С	3.862%	06/01/2025	100.000%	1,273,287.50
T otal	2)	7044	500	\$17,730,000.00	¥	=	-	12	140	\$18,949,122.90

\mathbf{B}	id	I	nf	01	rm	a	ti	on	ı

Par Amount of Bonds	\$17,730,000.00
Reoffering Premium or (Discount)	1,219,122.90
Gross Production	\$18,949,122.90
Total Underwriter's Discount (0.450%)	\$(79,785.00)
Bid (106.426%)	18,869,337.90
Total Purchase Price	\$18,869,337.90
Bond Year Dollars	\$195,735.00
Average Life	11.040 Years
Average Coupon	3.9753834%
Net Interest Cost (NIC)	3.3933015%
True Interest Cost (TIC)	3.2368064%

GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM



\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Sources & Uses

Dated 02/01/2015 | Delivered 02/01/2015

Sources	Of Funds

Par Amount of Bonds	\$17,730,000.00
Transfers from Prior Issue DSR Funds	1,731,750.00
Reoffering Premium	1,219,122.90

Total Sources \$20,680,872.90

Uses Of Funds

Deposit to Net Cash Escrow Fund	20,515,863.78
Costs of Issuance	85,000.00
Total Underwriter's Discount (0.450%)	79,785.00
Rounding Amount	224.12

Total Uses \$20,680,872.90

GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM





\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Net Debt Service Schedule

DATE	PRINCIPAL	COUPON	INTEREST	TOTAL P+I	NET NEW D/S	Fiscal Total
02/01/2015	V7	0.5	9 7 /2	₹0		
06/01/2015	665,000.00	2.000%	216,966.67	881,966.67	881,966.67	881,966.67
12/01/2015		1 -	318,800.00	318,800.00	318,800.00	-
06/01/2016	660,000.00	2.000%	318,800.00	978,800.00	978,800.00	1,297,600.00
12/01/2016	10 mg	84	312,200.00	312,200.00	312,200.00	25 25 25
06/01/2017	670,000.00	2.000%	312,200.00	982,200.00	982,200.00	1,294,400.00
12/01/2017		1000 000 000 000 000 000 000 000 000 00	305,500.00	305,500.00	305,500.00	1000
06/01/2018	685,000.00	2.000%	305,500.00	990,500.00	990,500.00	1,296,000.00
12/01/2018	19 2	######################################	298,650.00	298,650.00	298,650.00	-
06/01/2019	700,000.00	3.000%	298,650.00	998,650.00	998,650.00	1,297,300.00
12/01/2019	-	25	288,150.00	288,150.00	288,150.00	-
06/01/2020	720,000.00	3.000%	288,150.00	1,008,150.00	1,008,150.00	1,296,300.00
12/01/2020	Al ag	1/2	277,350.00	277,350.00	277,350.00	M 10
06/01/2021	740,000.00	3.000%	277,350.00	1,017,350.00	1,017,350.00	1,294,700.00
12/01/2021	MORROW ONCO CONTROL	GM280000094-5	266,250.00	266,250.00	266,250.00	
06/01/2022	765,000.00	4.000%	266,250.00	1,031,250.00	1,031,250.00	1,297,500.00
12/01/2022	300 000 Protect Contracts.	85-	250,950.00	250,950.00	250,950.00	18.
06/01/2023	795,000.00	4.000%	250,950.00	1,045,950.00	1,045,950.00	1,296,900.00
12/01/2023		84	235,050.00	235,050.00	235,050.00	3
06/01/2024	825,000.00	5.000%	235,050.00	1,060,050.00	1,060,050.00	1,295,100.00
12/01/2024			214,425.00	214,425.00	214,425.00	
06/01/2025	865,000.00	5.000%	214,425.00	1,079,425.00	1,079,425.00	1,293,850.00
12/01/2025	Startunding Productive Control	19444000000000	192,800.00	192,800.00	192,800.00	-
06/01/2026	910,000.00	4.000%	192,800.00	1,102,800.00	1,102,800.00	1,295,600.00
12/01/2026	3 -	E=	174,600.00	174,600.00	174,600.00	2
06/01/2027	945,000.00	4.000%	174,600.00	1,119,600.00	1,119,600.00	1,294,200.00
12/01/2027	Ar ag	1/4	155,700.00	155,700.00	155,700.00	W
06/01/2028	985,000.00	4.000%	155,700.00	1,140,700.00	1,140,700.00	1,296,400.00
12/01/2028	500 00 00 00 00 00 00 00 00 00 00 00 00	56000000000000000000000000000000000000	136,000.00	136,000.00	136,000.00	
06/01/2029	1,025,000.00	4.000%	136,000.00	1,161,000.00	1,161,000.00	1,297,000.00
12/01/2029	-	r. -	115,500.00	115,500.00	115,500.00	-
06/01/2030	1,065,000.00	4.000%	115,500.00	1,180,500.00	1,180,500.00	1,296,000.00
12/01/2030	F	89	94,200.00	94,200.00	94,200.00	-
06/01/2031	1,110,000.00	4.000%	94,200.00	1,204,200.00	1,204,200.00	1,298,400.00
12/01/2031	240004000000	20.000 Bagg	72,000.00	72,000.00	72,000.00	1474/24/03/10/10/10/10
06/01/2032	1,150,000.00	4.000%	72,000.00	1,222,000.00	1,222,000.00	1,294,000.00
12/01/2032	3503063303000	50000000000000000000000000000000000000	49,000.00	49,000.00	49,000.00	
06/01/2033	1,200,000.00	4.000%	49,000.00	1,249,000.00	1,249,000.00	1,298,000.00
12/01/2033		SE -	25,000.00	25,000.00	25,000.00	
06/01/2034	1,250,000.00	4.000%	25,000.00	1,275,000.00	1,275,000.00	1,300,000.00
Total	\$17,730,000,00		\$7,781,216.67	\$25,511,216.67	\$25.511.216.67	

GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM

ZIONS BANK Z B PUBLIC FINANCE

\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Gross Debt Service Comparison

Part 1 of 2

DATE	PRINCIPAL	COUPON	INTEREST	New D/S	OLD D/S	SAVINGS	Fiscal Total
02/01/2015	-	7021	23	<u>~</u>	Ξ;	(2	Σ:
06/01/2015	665,000.00	2.000%	216,966.67	881,966.67	1,308,371.88	426,405.21	426,405.21
12/01/2015	2	6823	318,800.00	318,800.00	400,571.88	81,771.88	20
06/01/2016	660,000.00	2.000%	318,800.00	978,800.00	1,330,571.88	351,771.88	433,543.76
12/01/2016	_		312,200.00	312,200.00	381,971.88	69,771.88	
06/01/2017	670,000.00	2.000%	312,200.00	982,200.00	1,346,971.88	364,771.88	434,543.76
12/01/2017		(0.77)	305,500.00	305,500.00	362,671.88	57,171.88	
06/01/2018	685,000.00	2.000%	305,500.00	990,500.00	1,367,671.88	377,171.88	434,343.76
12/01/2018		55=1	298,650.00	298,650.00	342,571.88	43,921.88	
06/01/2019	700,000.00	3.000%	298,650.00	998,650.00	1,387,571.88	388,921.88	432,843.76
12/01/2019	*	353	288,150.00	288,150.00	321,671.88	33,521.88	=
06/01/2020	720,000.00	3.000%	288,150.00	1,008,150.00	1,406,671.88	398,521.88	432,043.76
12/01/2020	3	989	277,350.00	277,350.00	298,615.63	21,265.63	₩.
06/01/2021	740,000.00	3.000%	277,350.00	1,017,350.00	1,428,615.63	411,265.63	432,531.26
12/01/2021	×	2 <u>2</u> 23	266,250.00	266,250.00	273,190.63	6,940.63	2
06/01/2022	765,000.00	4.000%	266,250.00	1,031,250.00	1,458,190.63	426,940.63	433,881.26
12/01/2022	12€	724	250,950.00	250,950.00	246,528.13	(4,421.87)	25
06/01/2023	795,000.00	4.000%	250,950.00	1,045,950.00	1,481,528.13	435,578.13	431,156.26
12/01/2023		, - -	235,050.00	235,050.00	217,968.75	(17,081.25)	
06/01/2024	825,000.00	5.000%	235,050.00	1,060,050.00	1,512,968.75	452,918.75	435,837.50
12/01/2024	· · · · · · · · · · · · · · · · · · ·	(2)	214,425.00	214,425.00	186,403.13	(28,021.87)	5
06/01/2025	865,000.00	5.000%	214,425.00	1,079,425.00	1,541,403.13	461,978.13	433,956.26
12/01/2025	Ξ.	55.52	192,800.00	192,800.00	153,375.00	(39,425.00)	=
06/01/2026	910,000.00	4.000%	192,800.00	1,102,800.00	1,578,375.00	475,575.00	436,150.00
12/01/2026		383	174,600.00	174,600.00	117,750.00	(56,850.00)	8
06/01/2027	945,000.00	4.000%	174,600.00	1,119,600.00	1,612,750.00	493,150.00	436,300.00
12/01/2027	*	000	155,700.00	155,700.00	80,375.00	(75,325.00)	*
06/01/2028	985,000.00	4.000%	155,700.00	1,140,700.00	1,650,375.00	509,675.00	434,350.00
12/01/2028	12	(ME)	136,000.00	136,000.00	41,125.00	(94,875.00)	E

GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM

ZIONS BANK



\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Gross Debt Service Comparison

Part 2 of 2

Fiscal Total	SAVINGS	OLD D/S	New D/S	INTEREST	COUPON	PRINCIPAL	DATE
430,250.00	525,125.00	1,686,125.00	1,161,000.00	136,000.00	4.000%	1,025,000.00	06/01/2029
	(115,500.00)	=3	115,500.00	115,500.00	1851	:=	12/01/2029
(1,296,000.00)	(1,180,500.00)	21	1,180,500.00	115,500.00	4.000%	1,065,000.00	06/01/2030
=	(94,200.00)	=1	94,200.00	94,200.00	353	:=	12/01/2030
(1,298,400.00)	(1,204,200.00)	70	1,204,200.00	94,200.00	4.000%	1,110,000.00	06/01/2031
=	(72,000.00)	-1	72,000.00	72,000.00	200	2	12/01/2031
(1,294,000.00)	(1,222,000.00)	5.0	1,222,000.00	72,000.00	4.000%	1,150,000.00	06/01/2032
2	(49,000.00)	2)	49,000.00	49,000.00	2020	×	12/01/2032
(1,298,000.00)	(1,249,000.00)	73	1,249,000.00	49,000.00	4.000%	1,200,000.00	06/01/2033
<u> </u>	(25,000.00)	29	25,000.00	25,000.00	721	12	12/01/2033
(1,300,000.00)	(1,275,000.00)	₹	1,275,000.00	25,000.00	4.000%	1,250,000.00	06/01/2034
-	\$11,736.55	\$25,522,953.22	\$25,511,216.67	\$7,781,216.67	(i=1	\$17,730,000.00	Total

PV Analysis Summary (Gross to Gross)

Gross PV Debt Service Savings	1,399,850.04
Transfers from Prior Issue DSR Fund	(1,731,750.00)
Contingency or Rounding Amount	224.12

Net Present Value Loss	\$(331,675.84)

Net PV Loss	/ \$18,255,000 Refunded Principal	(1.817%)
Net PV Loss	/ \$17,730,000 Refunding Principal	(1.871%)

Average Annual Cash Flow Savings 607.06

Refunding Bond Information

Refunding Dated Date	2/01/2015
Refunding Delivery Date	2/01/2015

GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM





\$17,730,000 General Obligation Refunding Bonds

Series February 1, 2015

(Refund Series 2009 MBA: Scenario 2)

Escrow Fund Cashflow

Date	Principal	Rate	Interest	Receipts	Disbursem ents	Cash Balance	Fiscal Total
02/01/2015	(8 7 1	ā.	150	0.78	i.e	0.78	
06/01/2015	1,262,698.00	0.050%	45,673.23	1,308,371.23	1,308,371.88	0.13	1,308,371.88
12/01/2015	331,368.00	0.090%	69,203.86	400,571.86	400,571.88	0.11	**************************************
06/01/2016	1,261,616.00	0.160%	68,956.29	1,330,572.29	1,330,571.88	0.52	1,731,143.76
12/01/2016	314,025.00	0.270%	67,947.00	381,972.00	381,971.88	0.64	
06/01/2017	1,279,449.00	0.430%	67,523.07	1,346,972.07	1,346,971.88	0.83	1,728,943.76
12/01/2017	297,899.00	0.610%	64,772.26	362,671.26	362,671.88	0.21	=
06/01/2018	15,768,808.00	0.810%	63,863.67	15,832,671.67	15,832,671.88	100 X 200 X	16,195,343.76
Total	\$20,515,863.00	=	\$447,939.38	\$20,963,803.16	\$20,963,803.16		

Investment Parameters

Investment Model [PV, GIC, or Securities] Default investment yield target	Securities Bond Yield
Cash Deposit	0.78
Cost of Investments Purchased with Bond Proceeds	20,515,863.00
Total Cost of Investments	\$20,515,863.78
Target Cost of Investments at bond yield	\$19,233,233.83
Actual positive or (negative) arbitrage	(1,282,629.95)
Yield to Receipt	0.7545139%
Yield for Arbitrage Purposes	3.0369892%


GO Ref 09 MBA all mats 20 | SINGLE PURPOSE | 3/18/2014 | 11:06 AM








APPENDIX J:

















U.S. Population by Region: 1900-2030




Intermountain States Populations




Utah Population: 1970-2060




Utah Population Change by Decade



Utah and U.S. Annual Births: 1940-2012




Utah School Age Population




Source: BEBR Analysis of Governor's Office of Management and Budget, 2012 Projections and historical birth data.

Utah School Age Population



Source: BEBR Analysis of Governor's Office of Management and Budget, 2012 Projections and historical birth data.


Utah School Age Population Change: Annual Increments



Source: BEBR Analysis of Governor's Office of Management and Budget, 2012 Projections and historical birth data.

US Dependency Ratios


Aging Baby Boomer Drive Increases in Total



Source: BEBR analysis of Governor's Office of Management and Budget, 2012 Projections. Note: Dependency Ratios are computed as the number of nonworking age persons per 100 working age (18 – 64 years old) persons in the population. Youth are less than 18 years old and retirement age is 65 years and older.


Utah Dependency Ratios

Youth Dependency Ratios Decline and Stabilize




Source: BEBR analysis of Governor's Office of Management and Budget, 2012 Projections. Note: Dependency Ratios are computed as the number of nonworking age persons per 100 working age (18 – 64 years old) persons in the population. Youth are less than 18 years old and retirement age is 65 years and older.

Utah: Net Migration, Natural Increase, and Population Change - 1950-2012



Utah: Net Migration has Slowed Significantly







Almost half of migrants from 1990 to 2010 were foreign born

Source: BEBR, University of Utah Analysis of UPEC data.


U.S. Foreign Born Population: 1900–2012




Utah Foreign Born Population: 1900–2012



Educational Transition Points




Source: Octavio Villalpando, University of Utah



Welcome to the Utah Community Data Project

An online system of community-level demographic, housing, and socioeconomic data, indicators, and profiles.

2.utah.edu/#





Demography is Possibility

Thank you.





Pamela S. Perlich, Ph.D.

Senior Research Economist

Bureau of Economic and Business Research, University of Utah

www.bebr.utah.edu • Pam.Perlich@utah.edu

Voice: 801.581.3358 • Fax: 801.581.3354



